

This instruction sheet is designed to demonstrate how to assemble Datamate product equipped with metal backshells. The part numbers include:

- M80-4C1XX05S1
- M80-4C1XX42S1
- M80-4D1XX05S1
- M80-4D1XX42S1

Note: Example shown is M80-4C11005S1. Kits includes four 'E'-clips, two are spare. Kit of parts is as follows:



Datamate S-Tek

Tools required for these products include:

- BAND-IT Tie-Dex tool A301 (A590 kit)
- Hand Crimp Tool M22520/2-01 with Positioner T5747
- Contact insertion tool Z80-280
- 'E'-clip tool Z80-300




- 1) Feed cables through required length of braiding. It may be advisable to secure the cables together with electrical tape or similar to prevent wires becoming entangled in braiding. Leave the tape on until instructed to remove it later in these instructions.
- 2) Feed Band-It tie over cables and braiding for application later.
- 3) Feed cabling through ellipse/circular feature of backshell as shown below. Again, securing the cables together with electrical tape or similar may ease this process.



4) If tape was used, remove it now. Crimp the Datamate contacts onto the wires, and insert the contacts into the moulding. Please consult the relevant Instruction sheets: for crimping instructions see Instruction Sheet IS-01 for more details. For contact insertion into moulding see instruction sheet IS-25. All instruction sheets can be found at http://www.harwin.com/downloads/instructions/.




5) Terminate the braiding to the backshell using the Band-It tie. Harwin strongly recommend that all terminations are made so that the locking lip of the Band-It Tie Dex is positioned along the longer portion of the backshell exit to ensure a uniform band and braid compression (see example below). This also prevents the locking lip of the tie obstructing jackscrew insertion at a later stage. For full tooling instructions on the Band-It Tie Dex go to http://www.band-it.co.uk/tooling.htm and select tool A590 for full details.







6) Once braiding has been terminated as described and shown on page 2, and the locking lip is positioned as recommended, the Datamate connector can be positioned into the backshell housing ready to receive the jackscrews as shown below. Ensure moulding is pushed fully into backshell prior to fitting the jackscrews.



7) With the Datamate connector correctly positioned in the metal backshell, the jackscrews can now be inserted from the rear of the backshell as shown below. Ensure that Datamate connector remains fully inserted into backshell and using your finger and thumb support the jackscrews. Visually inspect the connector and backshell assembly to ensure the 'E'-clip groove in the jackscrews is visible.





- 8) Using Harwin tool Z80-300 apply 'E'-clips to the jackscrews:
 - a. The picture right shows the 'E'-clip groove in the tools tip this must be face down on surface when engaging clips with tool.



b. Position clip as shown in fig.1 it is recommended all 'E'-clips are placed on a flat surface and a square block is used to push clip against to engage tool. Slide the tool flat along the surface to engage the 'E'-clip.




c. Once the clip is engaged with the tool, ensure that the clip is orientated correctly as shown in fig.2.





d. Apply 'E'-clip to jackscrew as shown in Fig.3 and repeat step a. to c. for second 'E'-clip application. Assembly complete. Make sure that both 'E'-clips are fully seated around the jackscrews.



Please contact technical@harwin.co.uk for advice and assistance.

All instructions are available at http://www.harwin.com/downloads/instructions/

For full tooling instructions on the Band-It Tie Dex go to http://www.band-it.co.uk/tooling.htm and select tool A590 for full details.



