



May 18, 2011

Dear Customer,

Please be advised that with immediate effect we will no longer be able to supply the following components:

T1558R05	T1565R05	T1558-46	T1560-46	T1561-46
T1562-46	T1564-46	T1565-46	T105004C	T108398C

We are informing you of this change because you have either purchased this product from us in the past or you are on our Product Change Notification circulation list.

If you have any questions, do please contact me at the e-mail address below.

Yours sincerely,

Wendy Jane Bourne, BEng
Technical Marketing Engineer
technical@harwin.co.uk