



Harwin plc
Fitzherbert Road
Farlington, Portsmouth
Hampshire PO6 1RT
United Kingdom

Reception: +44 (0)23 9231 4545
Sales Desk: +44 (0)23 9237 0451
Fax: +44 (0)23 9231 4590

Friday 23rd November, 2012

Dear Customer,

Re: Obsolescence notification for Harwin product.

Please be advised that the following connectors are now obsolete with immediate effect. Some existing stock is available, and will be available until stocks are exhausted. Please contact quote@harwin.co.uk if you wish to purchase any of the existing stock.

- M30 crimps and Hand crimp tools as follows:
 - M30-1000046
 - M30-1010046
 - Z30-020

These 3 items have been replaced with an equivalent product – the products have undergone a design improvement, which also required the crimp tool to be replaced. Please see the attached spreadsheet for the replacement part numbers.

- M802-2001100 and M802-2001200 – these products are no longer supported by Harwin.

Please see the attached spreadsheet for a complete list of affected items, along with replacement recommendations where applicable. Unfortunately, we are no longer able to support these product lines under these part numbers.

If you have any further questions regarding this letter, please do not hesitate to contact us.

Yours faithfully,

The Product Management Team
technical@harwin.com

Obsolete Product Notification from Harwin

Part number being made obsolete	Last Time Buy date	Alternative product	Drawing for alternative product
M30-1000046	Immediate	M30-1050046	M30-105.PDF
M30-1010046	Immediate	M30-1060046	M30-106.PDF
Z30-020	Immediate	Z30-021	Z30-021.PDF
M802-2001100	Immediate	None available	
M802-2001200	Immediate	None available	
M802-2001100R	Immediate	None available	
M802-2001200R	Immediate	None available	