



Harwin plc  
Fitzherbert Road  
Farlington, Portsmouth  
Hampshire PO6 1RT  
United Kingdom

Reception: +44 (0)23 9231 4545  
Sales Desk: +44 (0)23 9237 0451  
Fax: +44 (0)23 9231 4590

Monday 10<sup>th</sup> March, 2014

Dear Customer,

**Re: Obsolescence notification for Harwin product.**

Please be advised that a range of Datamate single items are now obsolete with immediate effect. Attached is the list of affected items in Excel Spreadsheet format: "Obsolescence notification spreadsheet - Datamate selection March 2014.xlsx".

Please consult this spreadsheet for the complete list of affected items. Alternative items are available; please see the attached spreadsheet for the alternative part numbers.

If you have any further questions regarding this letter, please do not hesitate to contact us.

Yours faithfully,

The Product Management Team  
[technical@harwin.com](mailto:technical@harwin.com)

## Obsolete Product Notification from Harwin

Part number being made obsolete	Alternative product	Drawing for alternative product
M80-4010601	M80-4010642	<a href="#">M80-401.pdf</a>
M80-4012001	M80-4012042	<a href="#">M80-401.pdf</a>
M80-4020601	M80-4020642	<a href="#">M80-402.pdf</a>
M80-4021001	M80-4021042	<a href="#">M80-402.pdf</a>
M80-4021201	M80-4021242	<a href="#">M80-402.pdf</a>
M80-4022001	M80-4022042	<a href="#">M80-402.pdf</a>
M80-4024201	M80-4024242	<a href="#">M80-402.pdf</a>
M80-4050642	M80-4050605	<a href="#">M80-405.pdf</a>
M80-4052001	M80-4052042	<a href="#">M80-405.pdf</a>
M80-4054242	M80-4054205	<a href="#">M80-405.pdf</a>
M80-4055042	M80-4055005	<a href="#">M80-405.pdf</a>
M80-4060605	M80-4060642	<a href="#">M80-406.pdf</a>
M80-4061042	M80-4061005	<a href="#">M80-406.pdf</a>
M80-4063401	M80-4063442	<a href="#">M80-406.pdf</a>
M80-4101001	M80-4101042	<a href="#">M80-410.pdf</a>
M80-4101201	M80-4101242	<a href="#">M80-410.pdf</a>
M80-4120601	M80-4120642	<a href="#">M80-412.pdf</a>
M80-4121001	M80-4121042	<a href="#">M80-412.pdf</a>
M80-4121201	M80-4021242	<a href="#">M80-402.pdf</a>
M80-4121242	M80-4021242	<a href="#">M80-402.pdf</a>
M80-4122001	M80-4122042	<a href="#">M80-412.pdf</a>
M80-4211042	M80-4211005	<a href="#">M80-421.pdf</a>
M80-4581098	M80-4551098	<a href="#">M80-455.pdf</a>
M80-4581498	M80-4551498	<a href="#">M80-455.pdf</a>
M80-4630605	M80-4630642	<a href="#">M80-463.pdf</a>
M80-4651205	M80-4851205	<a href="#">M80-485.pdf</a>
M80-4662042	M80-4662005	<a href="#">M80-466.pdf</a>
M80-4712005	M80-4712042	<a href="#">M80-471.pdf</a>
M80-4761005	M80-4661005	<a href="#">M80-466.pdf</a>
M80-4851405	M80-4651405	<a href="#">M80-466.pdf</a>
M80-5111442	M80-5111422	<a href="#">M80-511.pdf</a>
M80-5120622	M80-5120642	<a href="#">M80-512.pdf</a>
M80-5121022P	M80-5121042P	<a href="#">M80-512P.pdf</a>
M80-5121222	M80-5121242	<a href="#">M80-512.pdf</a>
M80-5122022P	M80-5122042P	<a href="#">M80-512P.pdf</a>
M80-5200622	M80-5200642	<a href="#">M80-520.pdf</a>
M80-5201222	M80-5201242	<a href="#">M80-520.pdf</a>
M80-5202022	M80-5202042	<a href="#">M80-520.pdf</a>
M80-5203442	M80-5203422	<a href="#">M80-520.pdf</a>
M80-5212022	M80-5212042	<a href="#">M80-521.pdf</a>
M80-5213422	M80-5213442	<a href="#">M80-521.pdf</a>
M80-5220622	M80-5220642	<a href="#">M80-522.pdf</a>
M80-5221042	M80-5221005	<a href="#">M80-522.pdf</a>
M80-5221222	M80-5221242	<a href="#">M80-522.pdf</a>
M80-5222022	M80-5222042	<a href="#">M80-522.pdf</a>
M80-5223422	M80-5223442	<a href="#">M80-522.pdf</a>
M80-5224242	M80-5224222	<a href="#">M80-522.pdf</a>
M80-5304222	M80-5304242	<a href="#">M80-530.pdf</a>
M80-5314242	M80-5314222	<a href="#">M80-531.pdf</a>
M80-5321022	M80-5321042	<a href="#">M80-532.pdf</a>
M80-5321222	M80-5321242	<a href="#">M80-532.pdf</a>
M80-5322022	M80-5322042	<a href="#">M80-532.pdf</a>

## Obsolete Product Notification from Harwin

Part number being made obsolete	Alternative product	Drawing for alternative product
M80-5413422	M80-5413442	<a href="#">M80-541.pdf</a>
M80-5421222	M80-5421242	<a href="#">M80-542.pdf</a>
M80-5421422	M80-5421442	<a href="#">M80-542.pdf</a>
M80-5431842	M80-5431805	<a href="#">M80-543.pdf</a>
M80-5432642	M80-5432605	<a href="#">M80-543.pdf</a>
M80-5500842	M80-5300842	<a href="#">M80-530.pdf</a>
M80-5501222	M80-5501242	<a href="#">M80-550.pdf</a>
M80-5502042	M80-5502005	<a href="#">M80-550.pdf</a>
M80-5511022	M80-5511042	<a href="#">M80-551.pdf</a>
M80-5520622	M80-5520642	<a href="#">M80-552.pdf</a>
M80-5521022	M80-5521005	<a href="#">M80-552.pdf</a>
M80-5521042	M80-5521005	<a href="#">M80-552.pdf</a>
M80-5521222	M80-5521242	<a href="#">M80-552.pdf</a>
M80-5522022	M80-5522042	<a href="#">M80-552.pdf</a>
M80-5634205	M80-5624205	<a href="#">M80-562.pdf</a>
M80-5652005	M80-5602005	<a href="#">M80-560.pdf</a>
M80-5700605	M80-5600605	<a href="#">M80-560.pdf</a>
M80-5701405	M80-5601405	<a href="#">M80-560.pdf</a>
M80-5702605	M80-5602605	<a href="#">M80-560.pdf</a>
M80-5703405	M80-5603405	<a href="#">M80-560.pdf</a>
M80-5704205	M80-5604205	<a href="#">M80-560.pdf</a>
M80-5705005	M80-5605005	<a href="#">M80-560.pdf</a>
M80-5711405	M80-5611405	<a href="#">M80-561.pdf</a>
M80-5713405	M80-5613405	<a href="#">M80-561.pdf</a>
M80-5714205	M80-5614205	<a href="#">M80-561.pdf</a>
M80-5761005	M80-5661005	<a href="#">M80-566.pdf</a>
M80-5821005	M80-5621005	<a href="#">M80-562.pdf</a>
M80-5824205	M80-5624205	<a href="#">M80-562.pdf</a>
M80-5834205	M80-5624205	<a href="#">M80-562.pdf</a>
M80-6130442	M80-8890405	<a href="#">M80-889.pdf</a>
M80-6130642	M80-8890605	<a href="#">M80-889.pdf</a>
M80-6133445	M80-8893405	<a href="#">M80-889.pdf</a>
M80-6140245	M80-6140242	<a href="#">M80-614.pdf</a>
M80-6140345	M80-6140342	<a href="#">M80-614.pdf</a>
M80-6152042	M80-6152045	<a href="#">M80-615.pdf</a>
M80-6160422	M80-6160442	<a href="#">M80-616.pdf</a>
M80-6160842	M80-6160822	<a href="#">M80-616.pdf</a>
M80-6650422	M80-6650442	<a href="#">M80-665.pdf</a>
M80-6650622	M80-6650642	<a href="#">M80-665.pdf</a>
M80-6650822	M80-6650842	<a href="#">M80-665.pdf</a>
M80-6651022	M80-6651042	<a href="#">M80-665.pdf</a>
M80-6651222	M80-6651242	<a href="#">M80-665.pdf</a>
M80-6670422	M80-6670442	<a href="#">M80-667.pdf</a>
M80-6670622	M80-6670642	<a href="#">M80-667.pdf</a>
M80-6670822	M80-6670842	<a href="#">M80-667.pdf</a>
M80-6671022	M80-6671042	<a href="#">M80-667.pdf</a>
M80-6671222	M80-6671242	<a href="#">M80-667.pdf</a>
M80-6810401	M80-6810442	<a href="#">M80-681.pdf</a>
M80-6810445	M80-6810442	<a href="#">M80-681.pdf</a>
M80-6810801	M80-6810842	<a href="#">M80-681.pdf</a>
M80-6811001	M80-6811042	<a href="#">M80-681.pdf</a>
M80-6811201	M80-6811242	<a href="#">M80-681.pdf</a>

M80-5821005 Reinstated in 2023

## Obsolete Product Notification from Harwin

Part number being made obsolete	Alternative product	Drawing for alternative product
M80-6811601	M80-6811642	<a href="#">M80-681.pdf</a>
M80-6813442	M80-6813445	<a href="#">M80-681.pdf</a>
M80-7015122	M80-7015142	<a href="#">M80-701.pdf</a>
M80-7062705	M80-7052705	<a href="#">M80-705.pdf</a>
M80-7092705	M80-7082705	<a href="#">M80-708.pdf</a>
M80-7096305	M80-7086305	<a href="#">M80-708.pdf</a>
M80-7101542	M80-7101522	<a href="#">M80-710.pdf</a>
M80-7520222	M80-7520242	<a href="#">M80-752.pdf</a>
M80-7520342	M80-7520322	<a href="#">M80-752.pdf</a>
M80-7520442	M80-7520422	<a href="#">M80-752.pdf</a>
M80-7540642	M80-7540622	<a href="#">M80-754.pdf</a>
M80-7541442	M80-7541422	<a href="#">M80-754.pdf</a>
M80-7700442	M80-7700445	<a href="#">M80-770.pdf</a>
M80-7700642	M80-7700645	<a href="#">M80-770.pdf</a>
M80-7703442	M80-8503442	<a href="#">M80-850.pdf</a>
M80-7703445	M80-8503445	<a href="#">M80-850.pdf</a>
M80-8100405	M80-8160405	<a href="#">M80-816.pdf</a>
M80-8110405	M80-8170405	<a href="#">M80-817.pdf</a>
M80-8111005	M80-8121005	<a href="#">M80-812.pdf</a>
M80-8141822	M80-8391842	<a href="#">M80-839.pdf</a>
M80-8170805	M80-8130805	<a href="#">M80-813.pdf</a>
M80-8171005	M80-8131005	<a href="#">M80-813.pdf</a>
M80-8260422	M80-8260442	<a href="#">M80-826.pdf</a>
M80-8270422	M80-8270442	<a href="#">M80-827.pdf</a>
M80-8271622	M80-8271642	<a href="#">M80-827.pdf</a>
M80-8271822	M80-8271842	<a href="#">M80-827.pdf</a>
M80-8272622	M80-8272642	<a href="#">M80-827.pdf</a>
M80-8273422	M80-8273442	<a href="#">M80-827.pdf</a>
M80-8284422	M80-8284442	<a href="#">M80-828.pdf</a>
M80-8350422	M80-8360442	<a href="#">M80-836.pdf</a>
M80-8370642	M80-8360642	<a href="#">M80-836.pdf</a>
M80-8450345	M80-8980305	<a href="#">M80-898.pdf</a>
M80-8504445	M80-8504442	<a href="#">M80-850.pdf</a>
M80-8552022	M80-6172042	<a href="#">M80-617.pdf</a>
M80-8581022	M80-8251042	<a href="#">M80-825.pdf</a>
M80-8760705	M80-8760722	<a href="#">M80-876.pdf</a>
M80-8780322	M80-8430342	<a href="#">M80-843.pdf</a>
M80-8780522	M80-8430542	<a href="#">M80-843.pdf</a>
M80-8810345	M80-8810342	<a href="#">M80-881.pdf</a>
M80-8910805	M80-6150845	<a href="#">M80-615.pdf</a>
M80-9401042	M80-9401005	<a href="#">M80-940.pdf</a>
M80-9402642	M80-9402605	<a href="#">M80-940.pdf</a>
M80-9431005	M80-9421005	<a href="#">M80-942.pdf</a>
M80-9431205	M80-9421205	<a href="#">M80-942.pdf</a>