



Harwin plc
Fitzherbert Road
Farlington, Portsmouth
Hampshire PO6 1RT
United Kingdom

Reception: +44 (0)23 9231 4545
Sales Desk: +44 (0)23 9237 0451
Fax: +44 (0)23 9231 4590

Friday 14th March, 2014

Dear Customer,

Re: Obsolescence notification for Harwin product.

Please be advised that there are a number of ranges and individual items that are now obsolete. Some are with immediate effect, and some are with a last time buy date of 13th June, 2014. Please see the attached spreadsheet for a complete list of affected items. The larger ranges that may be of most interest are:

- M20-784 series
- D62xx, D67xx, D69xx series
- D92xx, D97xx, D99xx series

Unfortunately, we are no longer able to support these product lines. Alternative items are available in some cases; please see the attached spreadsheet for the alternative part numbers.

If you have any further questions regarding this letter, please do not hesitate to contact us.

Yours faithfully,

The Product Management Team
technical@harwin.com

Obsolete Product Notification from Harwin

Part number being made obsolete	Drawing for obsolete product	Last Time Buy?	Alternative product	Drawing for alternative product
506892	Contact technical@harwin.com	No - immediate	M80-5000000M1-07-331-00-000	M80-5000000M1-XX-XXX-00-000.PDF
506901	Contact technical@harwin.com	No - immediate	M80-5000000M1-07-333-00-000	M80-5000000M1-XX-XXX-00-000.PDF
506928	Contact technical@harwin.com	No - immediate	M80-4000000F2-07-327-00-000	M80-4000000F2-XX-XXX-00-000.PDF
006232D	Contact technical@harwin.com	No - immediate	No alternative	
006541X	Contact technical@harwin.com	No - immediate	No alternative	
006546A	Contact technical@harwin.com	No - immediate	No alternative	
006658F	Contact technical@harwin.com	No - immediate	No alternative	
006659F	Contact technical@harwin.com	No - immediate	No alternative	
006990E	Contact technical@harwin.com	No - immediate	No alternative	
06-115912-127	Contact technical@harwin.com	No - immediate	No alternative	
06-115912-140	Contact technical@harwin.com	No - immediate	No alternative	
3447-0114	Contact technical@harwin.com	No - immediate	No alternative	
D01B9933201	Contact technical@harwin.com	No - immediate	No alternative	
D01B9952001	Contact technical@harwin.com	No - immediate	No alternative	
D01B9972021	Contact technical@harwin.com	No - immediate	No alternative	
D4490033-0	Contact technical@harwin.com	No - immediate	No alternative	
D4490034-0	Contact technical@harwin.com	No - immediate	No alternative	
D6206-01	D6XXX-XX OBSOLETE.PDF	Until 13-06-2014	No alternative	
D6206-46	D6XXX-XX OBSOLETE.PDF	Until 13-06-2014	No alternative	
D6208-01	D6XXX-XX OBSOLETE.PDF	Until 13-06-2014	No alternative	
D6208-46	D6XXX-XX OBSOLETE.PDF	Until 13-06-2014	No alternative	
D6214-01	D6XXX-XX OBSOLETE.PDF	Until 13-06-2014	No alternative	
D6214-46	D6XXX-XX OBSOLETE.PDF	Until 13-06-2014	No alternative	
D6214B01	Contact technical@harwin.com	No - immediate	No alternative	
D6214B46	Contact technical@harwin.com	No - immediate	No alternative	
D6214R01	Contact technical@harwin.com	No - immediate	No alternative	
D6216-01	D6XXX-XX OBSOLETE.PDF	Until 13-06-2014	No alternative	
D6216-46	D6XXX-XX OBSOLETE.PDF	Until 13-06-2014	No alternative	
D6216B01	Contact technical@harwin.com	No - immediate	No alternative	
D6216B46	Contact technical@harwin.com	No - immediate	No alternative	
D6216R01	Contact technical@harwin.com	No - immediate	No alternative	
D6218-01	D6XXX-XX OBSOLETE.PDF	Until 13-06-2014	No alternative	
D6218-46	D6XXX-XX OBSOLETE.PDF	Until 13-06-2014	No alternative	
D6218B01	Contact technical@harwin.com	No - immediate	No alternative	
D6220-01	D6XXX-XX OBSOLETE.PDF	Until 13-06-2014	No alternative	
D6220-46	D6XXX-XX OBSOLETE.PDF	Until 13-06-2014	No alternative	
D6220B01	Contact technical@harwin.com	No - immediate	No alternative	
D6220B46	Contact technical@harwin.com	No - immediate	No alternative	
D6220R01	Contact technical@harwin.com	No - immediate	No alternative	
D6222-01	D6XXX-XX OBSOLETE.PDF	Until 13-06-2014	No alternative	
D6222-46	D6XXX-XX OBSOLETE.PDF	Until 13-06-2014	No alternative	
D6224-01	D6XXX-XX OBSOLETE.PDF	Until 13-06-2014	No alternative	
D6224-46	D6XXX-XX OBSOLETE.PDF	Until 13-06-2014	No alternative	
D6224B01	Contact technical@harwin.com	No - immediate	No alternative	
D6224R01	Contact technical@harwin.com	No - immediate	No alternative	
D6228-01	D6XXX-XX OBSOLETE.PDF	Until 13-06-2014	No alternative	
D6228-46	D6XXX-XX OBSOLETE.PDF	Until 13-06-2014	No alternative	
D6228B01	Contact technical@harwin.com	No - immediate	No alternative	
D6232-01	D6XXX-XX OBSOLETE.PDF	Until 13-06-2014	No alternative	
D6232-46	D6XXX-XX OBSOLETE.PDF	Until 13-06-2014	No alternative	
D6240-01	D6XXX-XX OBSOLETE.PDF	Until 13-06-2014	No alternative	
D6240-46	D6XXX-XX OBSOLETE.PDF	Until 13-06-2014	No alternative	
D6240B01	Contact technical@harwin.com	No - immediate	No alternative	
D6240R01	Contact technical@harwin.com	No - immediate	No alternative	
D6248-01	D6XXX-XX OBSOLETE.PDF	Until 13-06-2014	No alternative	
D6248-46	D6XXX-XX OBSOLETE.PDF	Until 13-06-2014	No alternative	
D6264-01	D6XXX-XX OBSOLETE.PDF	Until 13-06-2014	No alternative	
D6264-46	D6XXX-XX OBSOLETE.PDF	Until 13-06-2014	No alternative	
D6724-01	D6XXX-XX OBSOLETE.PDF	Until 13-06-2014	No alternative	
D6724-46	D6XXX-XX OBSOLETE.PDF	Until 13-06-2014	No alternative	
D6922-01	D6XXX-XX OBSOLETE.PDF	Until 13-06-2014	No alternative	
D6922-46	D6XXX-XX OBSOLETE.PDF	Until 13-06-2014	No alternative	
D6924-01	D6XXX-XX OBSOLETE.PDF	Until 13-06-2014	No alternative	
D6924-46	D6XXX-XX OBSOLETE.PDF	Until 13-06-2014	No alternative	
D6948-01	D6XXX-XX OBSOLETE.PDF	Until 13-06-2014	No alternative	
D6948-46	D6XXX-XX OBSOLETE.PDF	Until 13-06-2014	No alternative	
D73064R01	Contact technical@harwin.com	No - immediate	No alternative	
D9206-01	D9XXX-XX OBSOLETE.PDF	Until 13-06-2014	No alternative	
D9206-46	D9XXX-XX OBSOLETE.PDF	Until 13-06-2014	No alternative	
D9208-01	D9XXX-XX OBSOLETE.PDF	Until 13-06-2014	No alternative	
D9208-46	D9XXX-XX OBSOLETE.PDF	Until 13-06-2014	No alternative	

Obsolete Product Notification from Harwin

Part number being made obsolete	Drawing for obsolete product	Last Time Buy?	Alternative product	Drawing for alternative product
D9214-01	D9XXX-XX OBSOLETE.PDF	Until 13-06-2014	No alternative	
D9214-46	D9XXX-XX OBSOLETE.PDF	Until 13-06-2014	No alternative	
D9216-01	D9XXX-XX OBSOLETE.PDF	Until 13-06-2014	No alternative	
D9216-46	D9XXX-XX OBSOLETE.PDF	Until 13-06-2014	No alternative	
D9218-01	D9XXX-XX OBSOLETE.PDF	Until 13-06-2014	No alternative	
D9218-46	D9XXX-XX OBSOLETE.PDF	Until 13-06-2014	No alternative	
D9220-01	D9XXX-XX OBSOLETE.PDF	Until 13-06-2014	No alternative	
D9220-46	D9XXX-XX OBSOLETE.PDF	Until 13-06-2014	No alternative	
D9222-01	D9XXX-XX OBSOLETE.PDF	Until 13-06-2014	No alternative	
D9222-46	D9XXX-XX OBSOLETE.PDF	Until 13-06-2014	No alternative	
D9224-01	D9XXX-XX OBSOLETE.PDF	Until 13-06-2014	No alternative	
D9224-46	D9XXX-XX OBSOLETE.PDF	Until 13-06-2014	No alternative	
D9228-01	D9XXX-XX OBSOLETE.PDF	Until 13-06-2014	No alternative	
D9228-46	D9XXX-XX OBSOLETE.PDF	Until 13-06-2014	No alternative	
D9232-01	D9XXX-XX OBSOLETE.PDF	Until 13-06-2014	No alternative	
D9232-46	D9XXX-XX OBSOLETE.PDF	Until 13-06-2014	No alternative	
D9240-01	D9XXX-XX OBSOLETE.PDF	Until 13-06-2014	No alternative	
D9240-46	D9XXX-XX OBSOLETE.PDF	Until 13-06-2014	No alternative	
D9248-01	D9XXX-XX OBSOLETE.PDF	Until 13-06-2014	No alternative	
D9248-46	D9XXX-XX OBSOLETE.PDF	Until 13-06-2014	No alternative	
D9264-01	D9XXX-XX OBSOLETE.PDF	Until 13-06-2014	No alternative	
D9264-46	D9XXX-XX OBSOLETE.PDF	Until 13-06-2014	No alternative	
D95040B01	Contact technical@harwin.com	No - immediate	No alternative	
D9724-01	D9XXX-XX OBSOLETE.PDF	Until 13-06-2014	No alternative	
D9724-46	D9XXX-XX OBSOLETE.PDF	Until 13-06-2014	No alternative	
D9922-01	D9XXX-XX OBSOLETE.PDF	Until 13-06-2014	No alternative	
D9922-46	D9XXX-XX OBSOLETE.PDF	Until 13-06-2014	No alternative	
D9924-01	D9XXX-XX OBSOLETE.PDF	Until 13-06-2014	No alternative	
D9924-46	D9XXX-XX OBSOLETE.PDF	Until 13-06-2014	No alternative	
D9948-01	D9XXX-XX OBSOLETE.PDF	Until 13-06-2014	No alternative	
D9948-46	D9XXX-XX OBSOLETE.PDF	Until 13-06-2014	No alternative	
M20-7840242	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7850242	M20-785.PDF
M20-7840246	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7850246	M20-785.PDF
M20-7840342	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7850342	M20-785.PDF
M20-7840346	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7850346	M20-785.PDF
M20-7840442	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7850442	M20-785.PDF
M20-7840446	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7850446	M20-785.PDF
M20-7840542	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7850542	M20-785.PDF
M20-7840546	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7850546	M20-785.PDF
M20-7840642	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7850642	M20-785.PDF
M20-7840646	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7850646	M20-785.PDF
M20-7840742	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7850742	M20-785.PDF
M20-7840746	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7850746	M20-785.PDF
M20-7840842	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7850842	M20-785.PDF
M20-7840846	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7850846	M20-785.PDF
M20-7840942	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7850942	M20-785.PDF
M20-7840946	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7850946	M20-785.PDF
M20-7841042	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7851042	M20-785.PDF
M20-7841046	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7851046	M20-785.PDF
M20-7841142	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7851142	M20-785.PDF
M20-7841146	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7851146	M20-785.PDF
M20-7841242	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7851242	M20-785.PDF
M20-7841246	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7851246	M20-785.PDF
M20-7841342	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7851342	M20-785.PDF
M20-7841346	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7851346	M20-785.PDF
M20-7841442	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7851442	M20-785.PDF
M20-7841446	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7851446	M20-785.PDF
M20-7841542	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7851542	M20-785.PDF
M20-7841546	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7851546	M20-785.PDF
M20-7841642	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7851642	M20-785.PDF
M20-7841646	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7851646	M20-785.PDF
M20-7841742	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7851742	M20-785.PDF
M20-7841746	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7851746	M20-785.PDF
M20-7841842	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7851842	M20-785.PDF
M20-7841846	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7851846	M20-785.PDF
M20-7841942	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7851942	M20-785.PDF
M20-7841946	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7851946	M20-785.PDF
M20-7842042	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7852042	M20-785.PDF
M20-7842046	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7852046	M20-785.PDF
M20-7842142	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7852142	M20-785.PDF
M20-7842146	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7852146	M20-785.PDF

Obsolete Product Notification from Harwin

Part number being made obsolete	Drawing for obsolete product	Last Time Buy?	Alternative product	Drawing for alternative product
M20-7842242	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7852242	M20-785.PDF
M20-7842246	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7852246	M20-785.PDF
M20-7842342	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7852342	M20-785.PDF
M20-7842346	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7852346	M20-785.PDF
M20-7842442	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7852442	M20-785.PDF
M20-7842446	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7852446	M20-785.PDF
M20-7842542	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7852542	M20-785.PDF
M20-7842546	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7852546	M20-785.PDF
M20-7842642	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7852642	M20-785.PDF
M20-7842646	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7852646	M20-785.PDF
M20-7842742	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7852742	M20-785.PDF
M20-7842746	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7852746	M20-785.PDF
M20-7842842	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7852842	M20-785.PDF
M20-7842846	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7852846	M20-785.PDF
M20-7842942	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7852942	M20-785.PDF
M20-7842946	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7852946	M20-785.PDF
M20-7843042	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7853042	M20-785.PDF
M20-7843046	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7853046	M20-785.PDF
M20-7843142	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7853142	M20-785.PDF
M20-7843146	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7853146	M20-785.PDF
M20-7843242	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7853242	M20-785.PDF
M20-7843246	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7853246	M20-785.PDF
M20-7843342	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7853342	M20-785.PDF
M20-7843346	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7853346	M20-785.PDF
M20-7843442	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7853442	M20-785.PDF
M20-7843446	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7853446	M20-785.PDF
M20-7843542	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7853542	M20-785.PDF
M20-7843546	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7853546	M20-785.PDF
M20-7843642	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7853642	M20-785.PDF
M20-7843646	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7853646	M20-785.PDF
M20-7843742	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7853742	M20-785.PDF
M20-7843746	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7853746	M20-785.PDF
M20-7843842	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7853842	M20-785.PDF
M20-7843846	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7853846	M20-785.PDF
M20-7843942	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7853942	M20-785.PDF
M20-7843946	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7853946	M20-785.PDF
M20-7844042	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7854042	M20-785.PDF
M20-7844046	M20-784 OBSOLETE.PDF	Until 13-06-2014	M20-7854046	M20-785.PDF
M80-0400001	Contact technical@harwin.com	No - immediate	M80-0400005	M80-040.PDF
M80-0410001	Contact technical@harwin.com	No - immediate	M80-0410005	M80-041.PDF
M80-1940006	Contact technical@harwin.com	No - immediate	M80-1940005	M80-194.PDF
M80-1940046	Contact technical@harwin.com	No - immediate	M80-1940005	M80-194.PDF
M80-1950006	Contact technical@harwin.com	No - immediate	M80-1950005	M80-195.PDF
M80-1950046	Contact technical@harwin.com	No - immediate	M80-1950005	M80-195.PDF
M80-8260406	None available	No - immediate	M80-8260442	M80-826.PDF
M80-8260406P	None available	No - immediate	M80-8260442P	M80-826P.PDF
M80-8260606	None available	No - immediate	M80-8260642	M80-826.PDF
M80-8260606P	None available	No - immediate	M80-8260642P	M80-826P.PDF
M80-8260806	None available	No - immediate	M80-8260842	M80-826.PDF
M80-8260806P	None available	No - immediate	M80-8260842P	M80-826P.PDF
M80-8261006	None available	No - immediate	M80-8261042	M80-826.PDF
M80-8261006P	None available	No - immediate	M80-8261042P	M80-826P.PDF
M80-8261206	None available	No - immediate	M80-8261242	M80-826.PDF
M80-8261206P	None available	No - immediate	M80-8261242P	M80-826P.PDF
M80-8261406	None available	No - immediate	M80-8261442	M80-826.PDF
M80-8261406P	None available	No - immediate	M80-8261442P	M80-826P.PDF
M80-8261606	None available	No - immediate	M80-8261642	M80-826.PDF
M80-8261606P	None available	No - immediate	M80-8261642P	M80-826P.PDF
M80-8261806	None available	No - immediate	M80-8261842	M80-826.PDF
M80-8261806P	None available	No - immediate	M80-8261842P	M80-826P.PDF
M80-8262006	None available	No - immediate	M80-8262042	M80-826.PDF
M80-8262006P	None available	No - immediate	M80-8262042P	M80-826P.PDF
M80-8262606	None available	No - immediate	M80-8262642	M80-826.PDF
M80-8262606P	None available	No - immediate	M80-8262642P	M80-826P.PDF
M80-8263406	None available	No - immediate	M80-8263442	M80-826.PDF
M80-8263406P	None available	No - immediate	M80-8263442P	M80-826P.PDF
M80-8264406	None available	No - immediate	M80-8264442	M80-826.PDF
M80-8264406P	None available	No - immediate	M80-8264442P	M80-826P.PDF
M80-8270406	None available	No - immediate	M80-8270442	M80-827.PDF
M80-8270406P	None available	No - immediate	M80-8270442P	M80-827P.PDF
M80-8270606	None available	No - immediate	M80-8270642	M80-827.PDF

Obsolete Product Notification from Harwin

Part number being made obsolete	Drawing for obsolete product	Last Time Buy?	Alternative product	Drawing for alternative product
M80-8270606P	None available	No - immediate	M80-8270642P	M80-827P.PDF
M80-8270806	None available	No - immediate	M80-8270842	M80-827.PDF
M80-8270806P	None available	No - immediate	M80-8270842P	M80-827P.PDF
M80-8271006	None available	No - immediate	M80-8271042	M80-827.PDF
M80-8271006P	None available	No - immediate	M80-8271042P	M80-827P.PDF
M80-8271206	None available	No - immediate	M80-8271242	M80-827.PDF
M80-8271206P	None available	No - immediate	M80-8271242P	M80-827P.PDF
M80-8271406	None available	No - immediate	M80-8271442	M80-827.PDF
M80-8271406P	None available	No - immediate	M80-8271442P	M80-827P.PDF
M80-8271606	None available	No - immediate	M80-8271642	M80-827.PDF
M80-8271606P	None available	No - immediate	M80-8271642P	M80-827P.PDF
M80-8271806	None available	No - immediate	M80-8271842	M80-827.PDF
M80-8271806P	None available	No - immediate	M80-8271842P	M80-827P.PDF
M80-8272006	None available	No - immediate	M80-8272042	M80-827.PDF
M80-8272006P	None available	No - immediate	M80-8272042P	M80-827P.PDF
M80-8272606	None available	No - immediate	M80-8272642	M80-827.PDF
M80-8272606P	None available	No - immediate	M80-8272642P	M80-827P.PDF
M80-8273406	None available	No - immediate	M80-8273442	M80-827.PDF
M80-8273406P	None available	No - immediate	M80-8273442P	M80-827P.PDF
M80-8274406	None available	No - immediate	M80-8274442	M80-827.PDF
M80-8274406P	None available	No - immediate	M80-8274442P	M80-827P.PDF
M80-8280406	None available	No - immediate	M80-8280442	M80-828.PDF
M80-8280406P	None available	No - immediate	M80-8280442P	M80-828P.PDF
M80-8280606	None available	No - immediate	M80-8280642	M80-828.PDF
M80-8280606P	None available	No - immediate	M80-8280642P	M80-828P.PDF
M80-8280806	None available	No - immediate	M80-8280842	M80-828.PDF
M80-8280806P	None available	No - immediate	M80-8280842P	M80-828P.PDF
M80-8281006	None available	No - immediate	M80-8281042	M80-828.PDF
M80-8281006P	None available	No - immediate	M80-8281042P	M80-828P.PDF
M80-8281206	None available	No - immediate	M80-8281242	M80-828.PDF
M80-8281206P	None available	No - immediate	M80-8281242P	M80-828P.PDF
M80-8281406	None available	No - immediate	M80-8281442	M80-828.PDF
M80-8281406P	None available	No - immediate	M80-8281442P	M80-828P.PDF
M80-8281606	None available	No - immediate	M80-8281642	M80-828.PDF
M80-8281606P	None available	No - immediate	M80-8281642P	M80-828P.PDF
M80-8281806	None available	No - immediate	M80-8281842	M80-828.PDF
M80-8281806P	None available	No - immediate	M80-8281842P	M80-828P.PDF
M80-8282006	None available	No - immediate	M80-8282042	M80-828.PDF
M80-8282006P	None available	No - immediate	M80-8282042P	M80-828P.PDF
M80-8282606	None available	No - immediate	M80-8282642	M80-828.PDF
M80-8282606P	None available	No - immediate	M80-8282642P	M80-828P.PDF
M80-8283406	None available	No - immediate	M80-8283442	M80-828.PDF
M80-8283406P	None available	No - immediate	M80-8283442P	M80-828P.PDF
M80-8284406	None available	No - immediate	M80-8284442	M80-828.PDF
M80-8284406P	None available	No - immediate	M80-8284442P	M80-828P.PDF
M80B1010298	Contact technical@harwin.com	No - immediate	M80-1010298S	M80-101S.PDF
M80B1010398	Contact technical@harwin.com	No - immediate	M80-1010398S	M80-101S.PDF
M80B1010498	Contact technical@harwin.com	No - immediate	M80-1010498S	M80-101S.PDF
M80B1010598	Contact technical@harwin.com	No - immediate	M80-1010598S	M80-101S.PDF
M80B1010698	Contact technical@harwin.com	No - immediate	M80-1010698S	M80-101S.PDF
M80B1010798	Contact technical@harwin.com	No - immediate	M80-1010798S	M80-101S.PDF
M80B1011798	Contact technical@harwin.com	No - immediate	M80-1011798S	M80-101S.PDF
M80B1030498	Contact technical@harwin.com	No - immediate	M80-1030498S	M80-103S.PDF
M80B1030698	Contact technical@harwin.com	No - immediate	M80-1030698S	M80-103S.PDF
M80B1030898	Contact technical@harwin.com	No - immediate	M80-1030898S	M80-103S.PDF
M80B1031098	Contact technical@harwin.com	No - immediate	M80-1031098S	M80-103S.PDF
M80B1031298	Contact technical@harwin.com	No - immediate	M80-1031298S	M80-103S.PDF
M80B1031498	Contact technical@harwin.com	No - immediate	M80-1031498S	M80-103S.PDF
M80B1031698	Contact technical@harwin.com	No - immediate	M80-1031698S	M80-103S.PDF
M80B1031898	Contact technical@harwin.com	No - immediate	M80-1031898S	M80-103S.PDF
M80B1032098	Contact technical@harwin.com	No - immediate	M80-1032098S	M80-103S.PDF
M80B1032698	Contact technical@harwin.com	No - immediate	M80-1032698S	M80-103S.PDF
M80B1033498	Contact technical@harwin.com	No - immediate	M80-1033498S	M80-103S.PDF
M80C108109C-06	Contact technical@harwin.com	No - immediate	M80-4650605	M80-465.PDF
M80C108109C-10	Contact technical@harwin.com	No - immediate	M80-4651005	M80-465.PDF
M80C108109C-14	Contact technical@harwin.com	No - immediate	M80-4651405	M80-465.PDF
M80C108109C-20	Contact technical@harwin.com	No - immediate	M80-4652005	M80-465.PDF
M80C108109C-26	Contact technical@harwin.com	No - immediate	M80-4652605	M80-465.PDF
M80C108109C-34	Contact technical@harwin.com	No - immediate	M80-4653405	M80-465.PDF
M80C108109C-42	Contact technical@harwin.com	No - immediate	M80-4654205	M80-465.PDF
M80C108112C-06	Contact technical@harwin.com	No - immediate	M80-5650605	M80-565.PDF

Obsolete Product Notification from Harwin

Part number being made obsolete	Drawing for obsolete product	Last Time Buy?	Alternative product	Drawing for alternative product
M80C108112C-10	Contact technical@harwin.com	No - immediate	M80-5651005	M80-565.PDF
M80C108112C-14	Contact technical@harwin.com	No - immediate	M80-5651405	M80-565.PDF
M80C108112C-20	Contact technical@harwin.com	No - immediate	M80-5652005	M80-565.PDF
M80C108112C-26	Contact technical@harwin.com	No - immediate	M80-5652605	M80-565.PDF
M80C108112C-34	Contact technical@harwin.com	No - immediate	M80-5653405	M80-565.PDF
M80C108112C-42	Contact technical@harwin.com	No - immediate	M80-5654205	M80-565.PDF
M80C108132C-12	Contact technical@harwin.com	No - immediate	M80-5101222	M80-510.PDF
M80C108132C-20	Contact technical@harwin.com	No - immediate	M80-5102022	M80-510.PDF
M80C108132C-26	Contact technical@harwin.com	No - immediate	M80-5102622	M80-510.PDF
M80C108132C-34	Contact technical@harwin.com	No - immediate	M80-5103422	M80-510.PDF
S3291-06	Contact technical@harwin.com	No - immediate	No alternative	
S4051-46	S4051_OBSOLETE.PDF	Until 13-06-2014	No alternative	
S4091-46	S4091-S4101_OBSOLETE.PDF	Until 13-06-2014	No alternative	
S4101-46	S4091-S4101_OBSOLETE.PDF	Until 13-06-2014	No alternative	
S5231-46	S5231_OBSOLETE.PDF	Until 13-06-2014	No alternative	
T004480-1	Contact technical@harwin.com	No - immediate	No alternative	
T004481-1	Contact technical@harwin.com	No - immediate	No alternative	
Z104399C	Contact technical@harwin.com	No - immediate	No alternative	
Z104402C	Contact technical@harwin.com	No - immediate	No alternative	
Z104402C-00	Contact technical@harwin.com	No - immediate	No alternative	
Z3071-00	Contact technical@harwin.com	No - immediate	No alternative	