



Harwin plc
Fitzherbert Road
Farlington, Portsmouth
Hampshire PO6 1RT
United Kingdom

Reception: +44 (0)23 9231 4545
Sales Desk: +44 (0)23 9237 0451
Fax: +44 (0)23 9231 4590

Thursday 20th November, 2014

Dear Customer,

Re: Obsolescence notification for Harwin product.

Please be advised that there are a number of ranges and individual items that are now obsolete. All are obsolete with immediate effect, although some stocks may remain of a few items. Please see the attached spreadsheet (that has 2 pages) for a complete list of affected items. Some of the items are customer special products, but there are a number of standard products:

- F03E-XX21XXR, F05E-XX1146R, F05E-XX2146R, F05E-XX3146R, F08-200 and F08-210 series
- Majority of M402VF and M402-VM series – only a few items remain in these ranges
- M80-712, M80-713 and M80-719 series
- M83-LFC1F1N50-0004-307, M83-LML3M5N50-0004-313, M83-LMT1M2N50-0004-311

Unfortunately, we are no longer able to support these product lines.

If you have any further questions regarding this letter, please do not hesitate to contact us.

Yours faithfully,

The Product Management Team
technical@harwin.com

Obsolete Product Notification from Harwin - Standard

[illegible]

Obsolete Product Notification from Harwin - Standard

[illegible]

Obsolete Product Notification from Harwin - Standard

[illegible]

Obsolete Product Notification from Harwin - Standard

[illegible]

Obsolete Product Notification from Harwin - Standard

[illegible]

Obsolete Product Notification from Harwin - Standard

[illegible]

Obsolete Product Notification from Harwin - Standard

[illegible]

Obsolete Product Notification from Harwin - Standard

[illegible]

Obsolete Product Notification from Harwin - Standard

[illegible]

Obsolete Product Notification from Harwin - Standard

[illegible]

Obsolete Product Notification from Harwin - Standard

[illegible]

Obsolete Product Notification from Harwin - Standard

[illegible]

Obsolete Product Notification from Harwin - Standard

[illegible]

Obsolete Product Notification from Harwin - Standard

[illegible]

Obsolete Product Notification from Harwin - Standard

[illegible]

Obsolete Product Notification from Harwin - Standard

[illegible]

Obsolete Product Notification from Harwin - Standard

Part number being made obsolete	Drawing for obsolete product	Last Time Buy?	Alternative product	Drawing for alternative product
M80-7191505	M80-719_obsolete.pdf	No - immediate	M80-7161505	M80-716.pdf
M80-7191505A	M80-719_obsolete.pdf	No - immediate	M80-7161505A	M80-716.pdf
M80-7192401	M80-719_obsolete.pdf	No - immediate	M80-7162405	M80-716.pdf
M80-7192401A	M80-719_obsolete.pdf	No - immediate	M80-7162405A	M80-716.pdf
M80-7192405	M80-719_obsolete.pdf	No - immediate	M80-7162405	M80-716.pdf
M80-7192405A	M80-719_obsolete.pdf	No - immediate	M80-7162405A	M80-716.pdf
M80-7193001	M80-719_obsolete.pdf	No - immediate	M80-7163005	M80-716.pdf
M80-7193001A	M80-719_obsolete.pdf	No - immediate	M80-7163005A	M80-716.pdf
M80-7193005	M80-719_obsolete.pdf	No - immediate	M80-7163005	M80-716.pdf
M80-7193005A	M80-719_obsolete.pdf	No - immediate	M80-7163005A	M80-716.pdf
M80-7194201	M80-719_obsolete.pdf	No - immediate	M80-7164205	M80-716.pdf
M80-7194201A	M80-719_obsolete.pdf	No - immediate	M80-7164205A	M80-716.pdf
M80-7194205	M80-719_obsolete.pdf	No - immediate	M80-7164205	M80-716.pdf
M80-7194205A	M80-719_obsolete.pdf	No - immediate	M80-7164205A	M80-716.pdf
M83-LFC1F1N50-0004-307	M83-LFC1F1N50-0004-307_obsolete.pdf	No - immediate	Other M83	http://www.harwin.com/product-search/M83/
M83-LML3M5N50-0004-313	M83-LML3M5N50-0004-313_obsolete.pdf	No - immediate	Other M83	http://www.harwin.com/product-search/M83/
M83-LMT1M2N50-0004-311	M83-LMT1M2N50-0004-311_obsolete.pdf	No - immediate	Other M83	http://www.harwin.com/product-search/M83/

Obsolete Product Notification from Harwin - Special

Part number being made obsolete	Drawing for obsolete product	Last Time Buy?	Alternative product
3424-0130	Contact technical@harwin.com	No - immediate	No alternative
C107377C	Contact technical@harwin.com	No - immediate	No alternative
C107377CFI	Contact technical@harwin.com	No - immediate	No alternative
C107952C-40	Contact technical@harwin.com	No - immediate	No alternative
C107952C-50	Contact technical@harwin.com	No - immediate	No alternative
C107952C-60	Contact technical@harwin.com	No - immediate	No alternative
C107952C-70	Contact technical@harwin.com	No - immediate	No alternative
H108759C-00	Contact technical@harwin.com	No - immediate	No alternative
H108759C-06	Contact technical@harwin.com	No - immediate	No alternative
H108759C-46	Contact technical@harwin.com	No - immediate	No alternative
HD4669	Contact technical@harwin.com	No - immediate	No alternative
HD4670	Contact technical@harwin.com	No - immediate	No alternative
HD4671	Contact technical@harwin.com	No - immediate	No alternative
HD4672	Contact technical@harwin.com	No - immediate	No alternative
HD4673	Contact technical@harwin.com	No - immediate	No alternative
M106195C	Contact technical@harwin.com	No - immediate	No alternative
M22C107507C-88	Contact technical@harwin.com	No - immediate	No alternative
M22C107507C-92	Contact technical@harwin.com	No - immediate	No alternative
M22C107507C-93	Contact technical@harwin.com	No - immediate	No alternative
M22C107507C-94	Contact technical@harwin.com	No - immediate	No alternative
M22C107507C-95	Contact technical@harwin.com	No - immediate	No alternative
M22C107507C-96	Contact technical@harwin.com	No - immediate	No alternative
M22C107507C-97	Contact technical@harwin.com	No - immediate	No alternative
M22C107507C-98	Contact technical@harwin.com	No - immediate	No alternative
M22C107507C-99	Contact technical@harwin.com	No - immediate	No alternative
M22C107855C-88	Contact technical@harwin.com	No - immediate	No alternative
M22C107855C-92	Contact technical@harwin.com	No - immediate	No alternative
M22C107855C-93	Contact technical@harwin.com	No - immediate	No alternative
M22C107855C-94	Contact technical@harwin.com	No - immediate	No alternative
M22C107855C-95	Contact technical@harwin.com	No - immediate	No alternative
M22C107855C-96	Contact technical@harwin.com	No - immediate	No alternative
M22C107855C-97	Contact technical@harwin.com	No - immediate	No alternative
M22C107855C-98	Contact technical@harwin.com	No - immediate	No alternative
M22C107855C-99	Contact technical@harwin.com	No - immediate	No alternative
M30C107000C	Contact technical@harwin.com	No - immediate	No alternative
M30C107000C-SC	Contact technical@harwin.com	No - immediate	No alternative
M30C107001C	Contact technical@harwin.com	No - immediate	No alternative
M30C107002C	Contact technical@harwin.com	No - immediate	No alternative
M30C107002C-SC	Contact technical@harwin.com	No - immediate	No alternative
M30C107003C	Contact technical@harwin.com	No - immediate	No alternative
M30C107003C-SC	Contact technical@harwin.com	No - immediate	No alternative
M30C107004C	Contact technical@harwin.com	No - immediate	No alternative
M30C107350C	Contact technical@harwin.com	No - immediate	No alternative
M30C107350C-SC	Contact technical@harwin.com	No - immediate	No alternative
M30C107351C	Contact technical@harwin.com	No - immediate	No alternative
M30C107351C-SC	Contact technical@harwin.com	No - immediate	No alternative
M30C107402C	Contact technical@harwin.com	No - immediate	No alternative
M30C107402C-SC	Contact technical@harwin.com	No - immediate	No alternative
M30C107409C	Contact technical@harwin.com	No - immediate	No alternative
M30C107409C-SC	Contact technical@harwin.com	No - immediate	No alternative
M30C107410C	Contact technical@harwin.com	No - immediate	No alternative
M30C107410C-SC	Contact technical@harwin.com	No - immediate	No alternative
M30C107493C	Contact technical@harwin.com	No - immediate	No alternative
M30C107493C-SC	Contact technical@harwin.com	No - immediate	No alternative
M30C107494C	Contact technical@harwin.com	No - immediate	No alternative
M80C107962C-PRE	Contact technical@harwin.com	No - immediate	No alternative
M80C107963C-PRE	Contact technical@harwin.com	No - immediate	No alternative
M80C107966C-PRE	Contact technical@harwin.com	No - immediate	No alternative
M80C107967C-PRE	Contact technical@harwin.com	No - immediate	No alternative
M80C107968C-PRE	Contact technical@harwin.com	No - immediate	No alternative
M80C107969C-PRE	Contact technical@harwin.com	No - immediate	No alternative
M80C108005C	Contact technical@harwin.com	No - immediate	No alternative

Obsolete Product Notification from Harwin - Special

Part number being made obsolete	Drawing for obsolete product	Last Time Buy?	Alternative product
M80C108005C-PRE	Contact technical@harwin.com	No - immediate	No alternative
M80C108006C	Contact technical@harwin.com	No - immediate	No alternative
M80C108008C	Contact technical@harwin.com	No - immediate	No alternative
M80C108008C-PRE	Contact technical@harwin.com	No - immediate	No alternative
M80C108009C	Contact technical@harwin.com	No - immediate	No alternative
M80C108011C-PRE	Contact technical@harwin.com	No - immediate	No alternative
M80C108012C-PRE	Contact technical@harwin.com	No - immediate	No alternative
M80C108013C-PRE	Contact technical@harwin.com	No - immediate	No alternative
M22-5320206RTL	Contact technical@harwin.com	No - immediate	No alternative
M22-6362022RTL	Contact technical@harwin.com	No - immediate	No alternative
M22C106844CTL	Contact technical@harwin.com	No - immediate	No alternative
M22C106845CTL	Contact technical@harwin.com	No - immediate	No alternative
M22-6362106R-TL	Contact technical@harwin.com	No - immediate	No alternative