



Harwin plc
Fitzherbert Road
Farlington, Portsmouth
Hampshire PO6 1RT
United Kingdom

Reception: +44 (0)23 9231 4545
Sales Desk: +44 (0)23 9237 0451
Fax: +44 (0)23 9231 4590

Thursday 7th May, 2015

Dear Customer,

Re: Obsolescence notification for Harwin product.

Please be advised that there are a number of individual items that are now obsolete. M502-7850942 has a Last Time Buy date of Friday 5th June 2015. All other items are obsolete with immediate effect; stocks may remain of a few items, but most have not been manufactured in more than 6 years. Please see the attached spreadsheet for a complete list of affected items (there are two sheets in the spreadsheet, please check both). Here is a summary of affected ranges:

- M502-7850942
- Various Turned items starting H
- Various 2.54mm pitch specials
- Various 2mm pitch specials
- Various special items packaged for Farnell or RS
- A selection of other special items

Unfortunately, we are no longer able to support these product lines.

If you have any further questions regarding this letter, please do not hesitate to contact us.

Yours faithfully,

The Product Management Team
technical@harwin.com

If you have not been sent the accompanying spreadsheet, please request it from the contact that sent you this letter.

Obsolete Product Notification from Harwin - Standard

Part number being made obsolete	Drawing for obsolete product	Last Time Buy?	Alternative product	Drawing for alternative product
1778609	Contact technical@harwin.com	No - immediate	C90-3101F10SL-4S	C90-3101F.pdf
1778610	Contact technical@harwin.com	No - immediate	C90-3101F10SL-3S	C90-3101F.pdf
1778615	Contact technical@harwin.com	No - immediate	C90-3101F10SL-3P	C90-3101F.pdf
1778616	Contact technical@harwin.com	No - immediate	C90-3106F12S-3S	C90-3106F.pdf
1778618	Contact technical@harwin.com	No - immediate	C90-3101F12S-3S	C90-3101F.pdf
1778619	Contact technical@harwin.com	No - immediate	C90-3101F12S-3P	C90-3101F.pdf
1778622	Contact technical@harwin.com	No - immediate	C90-25042-10SL	C90-25042.pdf
1778623	Contact technical@harwin.com	No - immediate	C90-25042-12S	C90-25042.pdf
1778627	Contact technical@harwin.com	No - immediate	C90-25043-12S	C90-25043.pdf
H1010-09	Contact technical@harwin.com	No - immediate	H2101B01	H2101B01-H2103B01.pdf
H1011-09	Contact technical@harwin.com	No - immediate	H2101B01	H2101B01-H2103B01.pdf
H1012-09	Contact technical@harwin.com	No - immediate	H2105B01	H2105B01-H2106B01.pdf
H3175S01	Contact technical@harwin.com	No - immediate	H3175-01	H3175.pdf
H9005-01	H9005_obsolete.pdf	No - immediate	H9004-01	H9004.pdf
M20F1060700	Contact technical@harwin.com	No - immediate	M20-1060700	M20-106.pdf
M20F1070200	Contact technical@harwin.com	No - immediate	M20-1070200	M20-107.pdf
M20F1070300	Contact technical@harwin.com	No - immediate	M20-1070300	M20-107.pdf
M20F1070600	Contact technical@harwin.com	No - immediate	M20-1070600	M20-107.pdf
M20F1070800	Contact technical@harwin.com	No - immediate	M20-1070800	M20-107.pdf
M20F1071200	Contact technical@harwin.com	No - immediate	M20-1071200	M20-107.pdf
M20F1180006ST	Contact technical@harwin.com	No - immediate	M20-1180046	M20-118.pdf
M22F1920005	Contact technical@harwin.com	No - immediate	M22-1920005	M22-19X.pdf
M22F1930005	Contact technical@harwin.com	No - immediate	M22-1930005	M22-19X.pdf
M22F2041205	Contact technical@harwin.com	No - immediate	M22-2041205	M22-204.pdf
M22F3050022	Contact technical@harwin.com	No - immediate	M22-3050042	M22-305.pdf
M22F6360422	Contact technical@harwin.com	No - immediate	M22-6360442	M22-636.pdf
M22F6361022	Contact technical@harwin.com	No - immediate	M22-6361042	M22-636.pdf
M22R2041806	Contact technical@harwin.com	No - immediate	M22-2041846	M22-204.pdf
M22R3010400	Contact technical@harwin.com	No - immediate	M22-3010400	M22-301.pdf
M22R3010600	Contact technical@harwin.com	No - immediate	M22-3010600	M22-301.pdf
M22R3011000	Contact technical@harwin.com	No - immediate	M22-3011000	M22-301.pdf
M22R3020300	Contact technical@harwin.com	No - immediate	M22-3020300	M22-302.pdf
M22R3020400	Contact technical@harwin.com	No - immediate	M22-3020400	M22-302.pdf
M502-7850942	M502-7850942_obsolete.pdf	05/06/2015	None	
M50F3000522	Contact technical@harwin.com	No - immediate	M50-3000545	M50-300.pdf
M50F3002022	Contact technical@harwin.com	No - immediate	M50-3002045	M50-300.pdf
M50F3002522	Contact technical@harwin.com	No - immediate	M50-3002545	M50-300.pdf
M50F3005022	Contact technical@harwin.com	No - immediate	M50-3005045	M50-300.pdf
M50F3150522	Contact technical@harwin.com	No - immediate	M50-3150542	M50-315.pdf
M50F3151022	Contact technical@harwin.com	No - immediate	M50-3151042	M50-315.pdf
M50F3152022	Contact technical@harwin.com	No - immediate	M50-3152042	M50-315.pdf
M50F3152522	Contact technical@harwin.com	No - immediate	M50-3152542	M50-315.pdf
M50F3155022	Contact technical@harwin.com	No - immediate	M50-3155042	M50-315.pdf
M50F3500522	Contact technical@harwin.com	No - immediate	M50-3500542	M50-350.pdf
M50F3501022	Contact technical@harwin.com	No - immediate	M50-3501042	M50-350.pdf
M50F3502022	Contact technical@harwin.com	No - immediate	M50-3502042	M50-350.pdf
M50F3502522	Contact technical@harwin.com	No - immediate	M50-3502542	M50-350.pdf
M50F3505022	Contact technical@harwin.com	No - immediate	M50-3505042	M50-350.pdf
M50F3600522	Contact technical@harwin.com	No - immediate	M50-3600542	M50-360.pdf
M50F3602022	Contact technical@harwin.com	No - immediate	M50-3602042	M50-360.pdf
M50F3602522	Contact technical@harwin.com	No - immediate	M50-3602542	M50-360.pdf
M50F3605022	Contact technical@harwin.com	No - immediate	M50-3605042	M50-360.pdf
M50F3900522	Contact technical@harwin.com	No - immediate	M50-3900542	M50-390.pdf
M50F3901022	Contact technical@harwin.com	No - immediate	M50-3901042	M50-390.pdf
M50F3902022	Contact technical@harwin.com	No - immediate	M50-3902042	M50-390.pdf
M50F3902522	Contact technical@harwin.com	No - immediate	M50-3902542	M50-390.pdf
M50F3905022	Contact technical@harwin.com	No - immediate	M50-3905042	M50-390.pdf
M50R4321005	Contact technical@harwin.com	No - immediate	M50-4301045	M50-430.pdf
M50R4322005	Contact technical@harwin.com	No - immediate	M50-4302045	M50-430.pdf
M50R4921005	Contact technical@harwin.com	No - immediate	M50-4901045	M50-490.pdf
M50R4922005	Contact technical@harwin.com	No - immediate	M50-4902045	M50-490.pdf
M50S4324005	Contact technical@harwin.com	No - immediate	M50-4304045	M50-430.pdf

Obsolete Product Notification from Harwin - Standard

Part number being made obsolete	Drawing for obsolete product	Last Time Buy?	Alternative product	Drawing for alternative product
M50S4924005	Contact technical@harwin.com	No - immediate	M50-4904045	M50-490.pdf
M7571F05	Contact technical@harwin.com	No - immediate	M7571-05	M7565-M7571.pdf

Obsolete Product Notification from Harwin - Special

Part number being made obsolete	Drawing for obsolete product	Last Time Buy?
6653872854	Contact technical@harwin.com	No - immediate
3425-0020	Contact technical@harwin.com	No - immediate
3425-0042	Contact technical@harwin.com	No - immediate
C106553C	Contact technical@harwin.com	No - immediate
C106561C	Contact technical@harwin.com	No - immediate
C106608C	Contact technical@harwin.com	No - immediate
C108516C	Contact technical@harwin.com	No - immediate
C108517C	Contact technical@harwin.com	No - immediate
C108518C	Contact technical@harwin.com	No - immediate
C108519C	Contact technical@harwin.com	No - immediate
C108520C	Contact technical@harwin.com	No - immediate
C108521C	Contact technical@harwin.com	No - immediate
C108522C	Contact technical@harwin.com	No - immediate
C108523C	Contact technical@harwin.com	No - immediate
C108524C	Contact technical@harwin.com	No - immediate
H105951C	Contact technical@harwin.com	No - immediate
H108423C	Contact technical@harwin.com	No - immediate
M103429C	Contact technical@harwin.com	No - immediate
M103430C	Contact technical@harwin.com	No - immediate
M104934C	Contact technical@harwin.com	No - immediate
M104935C	Contact technical@harwin.com	No - immediate
M105321C	Contact technical@harwin.com	No - immediate
M105438C	Contact technical@harwin.com	No - immediate
M105517C	Contact technical@harwin.com	No - immediate
M105660C	Contact technical@harwin.com	No - immediate
M105703C	Contact technical@harwin.com	No - immediate
M106085C	Contact technical@harwin.com	No - immediate
M106091C	Contact technical@harwin.com	No - immediate
M106092C	Contact technical@harwin.com	No - immediate
M106093C	Contact technical@harwin.com	No - immediate
M106109C	Contact technical@harwin.com	No - immediate
M106110C	Contact technical@harwin.com	No - immediate
M106149C	Contact technical@harwin.com	No - immediate
M106191C	Contact technical@harwin.com	No - immediate
M106260C	Contact technical@harwin.com	No - immediate
M106557C	Contact technical@harwin.com	No - immediate
M106617C	Contact technical@harwin.com	No - immediate
M106618C	Contact technical@harwin.com	No - immediate
M106619C	Contact technical@harwin.com	No - immediate
M107606C	Contact technical@harwin.com	No - immediate
M20C106855C	Contact technical@harwin.com	No - immediate
M20C106972C	Contact technical@harwin.com	No - immediate
M20C107037C	Contact technical@harwin.com	No - immediate
M20C107060C	Contact technical@harwin.com	No - immediate
M20C107064C	Contact technical@harwin.com	No - immediate
M20C107065C	Contact technical@harwin.com	No - immediate
M20C107066C	Contact technical@harwin.com	No - immediate
M20C107158C	Contact technical@harwin.com	No - immediate
M20C107159C	Contact technical@harwin.com	No - immediate
M20C107189C	Contact technical@harwin.com	No - immediate
M20C107190C	Contact technical@harwin.com	No - immediate
M20C107300C	Contact technical@harwin.com	No - immediate
M20C107312C	Contact technical@harwin.com	No - immediate
M20C107373C	Contact technical@harwin.com	No - immediate
M20C107374C	Contact technical@harwin.com	No - immediate
M20C107379C	Contact technical@harwin.com	No - immediate
M20C107380C	Contact technical@harwin.com	No - immediate
M20C107403C	Contact technical@harwin.com	No - immediate
M20C107407C	Contact technical@harwin.com	No - immediate
M20C107408C	Contact technical@harwin.com	No - immediate
M20C107541C	Contact technical@harwin.com	No - immediate
M20C107618C	Contact technical@harwin.com	No - immediate

Obsolete Product Notification from Harwin - Special

Part number being made obsolete	Drawing for obsolete product	Last Time Buy?
M20C107630C	Contact technical@harwin.com	No - immediate
M20C107692C	Contact technical@harwin.com	No - immediate
M20C107693C	Contact technical@harwin.com	No - immediate
M20C107694C	Contact technical@harwin.com	No - immediate
M20C107761C	Contact technical@harwin.com	No - immediate
M20C108152C	Contact technical@harwin.com	No - immediate
M20C108272C	Contact technical@harwin.com	No - immediate
M20C108312C	Contact technical@harwin.com	No - immediate
M20C108313C	Contact technical@harwin.com	No - immediate
M20C108484C	Contact technical@harwin.com	No - immediate
M22C106862C	Contact technical@harwin.com	No - immediate
M22C107476C	Contact technical@harwin.com	No - immediate
M22C107486CR	Contact technical@harwin.com	No - immediate
M22C107848C	Contact technical@harwin.com	No - immediate
M22C107849C	Contact technical@harwin.com	No - immediate
M22C107850C	Contact technical@harwin.com	No - immediate
M22C107854C	Contact technical@harwin.com	No - immediate
M22C108032C	Contact technical@harwin.com	No - immediate
M22C108033C	Contact technical@harwin.com	No - immediate
M22C108048C	Contact technical@harwin.com	No - immediate
M22C108049C	Contact technical@harwin.com	No - immediate
M22C108131C-05	Contact technical@harwin.com	No - immediate
M22C108131C-05R	Contact technical@harwin.com	No - immediate
M22C108131C-46	Contact technical@harwin.com	No - immediate
M22C108131C-46R	Contact technical@harwin.com	No - immediate
M22C108338C	Contact technical@harwin.com	No - immediate
M22C108476C	Contact technical@harwin.com	No - immediate
M40C108894C-91	Contact technical@harwin.com	No - immediate
M40C108894C-93	Contact technical@harwin.com	No - immediate
M40C108894C-94	Contact technical@harwin.com	No - immediate
M40C108894C-95	Contact technical@harwin.com	No - immediate
M40C108894C-96	Contact technical@harwin.com	No - immediate
M40C108894C-97	Contact technical@harwin.com	No - immediate
M40C108894C-98	Contact technical@harwin.com	No - immediate
M40C108894C-99	Contact technical@harwin.com	No - immediate
UBX410500885	Contact technical@harwin.com	No - immediate