



Harwin plc  
Fitzherbert Road  
Farlington, Portsmouth  
Hampshire PO6 1RT  
United Kingdom

Reception: +44 (0)23 9231 4545  
Sales Desk: +44 (0)23 9237 0451  
Fax: +44 (0)23 9231 4590

Monday 5<sup>th</sup> October, 2015

Dear Customer,

**Re: Obsolescence notification for Harwin product.**

Please be advised that there are a number of individual items that are now obsolete. Some of these items have a Last Time Buy date – please check the attached spreadsheet list for specific details. The rest of the items are obsolete with immediate effect; stocks may remain of a few items, but most of these have not been manufactured in more than 6 years. Please see the attached spreadsheet for a complete list of affected items (there are two sheets in the spreadsheet, please check both). Here is a summary of affected ranges:

- Various Turned items starting H
- Various Standard products for Farnell and RS
- 3423-2316
- Various tools relating to obsolete products
- A selection of other special items

Unfortunately, we are no longer able to support these product lines.

If you have any further questions regarding this letter, please do not hesitate to contact us.

Yours faithfully,

The Product Management Team  
[technical@harwin.com](mailto:technical@harwin.com)

**If you have not been sent the accompanying spreadsheet, please request it from the contact that sent you this letter.**

# Obsolete Product Notification from Harwin - Standard

Part number being made obsolete	Drawing for obsolete product	Last Time Buy?	Alternative product	Drawing for alternative product
D3080B01	Contact technical@harwin.com	No - immediate	<a href="#">D3080-46</a>	<a href="#">D3080.pdf</a>
D3080R05	Contact technical@harwin.com	No - immediate	<a href="#">D3080-05</a>	<a href="#">D3080.pdf</a>
D3082B01	Contact technical@harwin.com	No - immediate	<a href="#">D3082-46</a>	<a href="#">D3082.pdf</a>
D3082R05	Contact technical@harwin.com	No - immediate	<a href="#">D3082-05</a>	<a href="#">D3082.pdf</a>
D3083B01	Contact technical@harwin.com	No - immediate	<a href="#">D3083-46</a>	<a href="#">D3083.pdf</a>
D3086B97	Contact technical@harwin.com	No - immediate	<a href="#">D3086-97</a>	<a href="#">D3086.pdf</a>
D3086R97	Contact technical@harwin.com	No - immediate	<a href="#">D3086-97</a>	<a href="#">D3086.pdf</a>
D3086R98	Contact technical@harwin.com	No - immediate	<a href="#">D3086-98</a>	<a href="#">D3086.pdf</a>
D3088R99	Contact technical@harwin.com	No - immediate	<a href="#">D3088-99</a>	<a href="#">D3088.pdf</a>
D3089DT99	Contact technical@harwin.com	No - immediate	<a href="#">D3089-99</a>	<a href="#">D3089.pdf</a>
H2152-01	<a href="#">H2152_obsolete.pdf</a>	24/12/2015	<a href="#">H2101A01</a>	<a href="#">H2101A01.pdf</a>
H2158-01	<a href="#">H2158_obsolete.pdf</a>	24/12/2015	<a href="#">H2159-01</a>	<a href="#">H2159.pdf</a>
H2158-06	<a href="#">H2158_obsolete.pdf</a>	24/12/2015	<a href="#">H2159-01</a>	<a href="#">H2159.pdf</a>
H2173DT05	Contact technical@harwin.com	No - immediate	<a href="#">H2173-05</a>	<a href="#">H2170-H2174.pdf</a>
H3073-01	<a href="#">H3073_obsolete.pdf</a>	24/12/2015	<a href="#">H2055-01</a>	<a href="#">H2055.pdf</a>
H9024-01	<a href="#">H9024_obsolete.pdf</a>	24/12/2015	<a href="#">H9023-01</a>	<a href="#">H9023.pdf</a>
H9039-01	<a href="#">H9039_obsolete.pdf</a>	24/12/2015	<a href="#">H2039-01</a>	<a href="#">H2039.pdf</a>
H9069-01	<a href="#">H9069_obsolete.pdf</a>	24/12/2015	<a href="#">H9001-01</a>	<a href="#">H9001.pdf</a>
P25-7017	<a href="#">P25-7017_obsolete.pdf</a>	24/12/2015	<a href="#">P25-0126</a>	<a href="#">P25-XX26.pdf</a>
P25B0423	Contact technical@harwin.com	No - immediate	<a href="#">P25-0423</a>	<a href="#">P25-XX23.pdf</a>
P25B1223	Contact technical@harwin.com	No - immediate	<a href="#">P25-1223</a>	<a href="#">P25-XX23.pdf</a>
P25B2223	Contact technical@harwin.com	No - immediate	<a href="#">P25-2223</a>	<a href="#">P25-XX23.pdf</a>
R30B4002502	Contact technical@harwin.com	No - immediate	<a href="#">R30-4002502</a>	<a href="#">R30-400.pdf</a>
R30F9401600	Contact technical@harwin.com	No - immediate	<a href="#">R30-9401600</a>	<a href="#">R30-940.pdf</a>
R3504-02	<a href="#">R3504-R3520_obsolete.pdf</a>	24/12/2015	<a href="#">R30-1010402</a>	<a href="#">R30-101.pdf</a>
R3506-02	<a href="#">R3504-R3520_obsolete.pdf</a>	24/12/2015	<a href="#">R30-1010602</a>	<a href="#">R30-101.pdf</a>
R3508-02	<a href="#">R3504-R3520_obsolete.pdf</a>	24/12/2015	<a href="#">R30-1010802</a>	<a href="#">R30-101.pdf</a>
R3510-02	<a href="#">R3504-R3520_obsolete.pdf</a>	24/12/2015	<a href="#">R30-1011002</a>	<a href="#">R30-101.pdf</a>
R3512-02	<a href="#">R3504-R3520_obsolete.pdf</a>	24/12/2015	<a href="#">R30-1011202</a>	<a href="#">R30-101.pdf</a>
R3514-02	<a href="#">R3504-R3520_obsolete.pdf</a>	24/12/2015	<a href="#">R30-1011402</a>	<a href="#">R30-101.pdf</a>
R3516-02	<a href="#">R3504-R3520_obsolete.pdf</a>	24/12/2015	<a href="#">R30-1011602</a>	<a href="#">R30-101.pdf</a>
R3518-02	<a href="#">R3504-R3520_obsolete.pdf</a>	24/12/2015	<a href="#">R30-1011802</a>	<a href="#">R30-101.pdf</a>
R3520-02	<a href="#">R3504-R3520_obsolete.pdf</a>	24/12/2015	<a href="#">R30-1012002</a>	<a href="#">R30-101.pdf</a>
R6325B02	Contact technical@harwin.com	No - immediate	<a href="#">R30-5001202</a>	<a href="#">R30-500.pdf</a>
R6326B02	Contact technical@harwin.com	No - immediate	<a href="#">R30-5001402</a>	<a href="#">R30-500.pdf</a>
R6332B02	Contact technical@harwin.com	No - immediate	<a href="#">R30-1010802</a>	<a href="#">R30-101.pdf</a>
R6333B02	Contact technical@harwin.com	No - immediate	<a href="#">R30-1011002</a>	<a href="#">R30-101.pdf</a>
R6335B02	Contact technical@harwin.com	No - immediate	<a href="#">R30-1011402</a>	<a href="#">R30-101.pdf</a>
R6336B02	Contact technical@harwin.com	No - immediate	<a href="#">R30-1011602</a>	<a href="#">R30-101.pdf</a>
R6337B02	Contact technical@harwin.com	No - immediate	<a href="#">R30-1011802</a>	<a href="#">R30-101.pdf</a>
R6337BV02	Contact technical@harwin.com	No - immediate	<a href="#">R30-1011802</a>	<a href="#">R30-101.pdf</a>
R6362R02	Contact technical@harwin.com	No - immediate	<a href="#">R30-6010602</a>	<a href="#">R30-601.pdf</a>
R6364R02	Contact technical@harwin.com	No - immediate	<a href="#">R30-6011002</a>	<a href="#">R30-601.pdf</a>
R6369R02	Contact technical@harwin.com	No - immediate	<a href="#">R30-6012002</a>	<a href="#">R30-601.pdf</a>
R6372R02	Contact technical@harwin.com	No - immediate	<a href="#">R30-1000602</a>	<a href="#">R30-100.pdf</a>
R6374R02	Contact technical@harwin.com	No - immediate	<a href="#">R30-1001002</a>	<a href="#">R30-100.pdf</a>
R6379R02	Contact technical@harwin.com	No - immediate	<a href="#">R30-1002002</a>	<a href="#">R30-100.pdf</a>
R6397R02	Contact technical@harwin.com	No - immediate	<a href="#">R6397-02</a>	<a href="#">R6390-R6397.pdf</a>
R6463-00	<a href="#">R6460-R6465_obsolete.pdf</a>	24/12/2015	None	
R6513F00	Contact technical@harwin.com	No - immediate	<a href="#">R6513-00</a>	<a href="#">R6505-R6535.pdf</a>
R6519F00	Contact technical@harwin.com	No - immediate	<a href="#">R6519-00</a>	<a href="#">R6505-R6535.pdf</a>
R6710F00	Contact technical@harwin.com	No - immediate	<a href="#">R6710-00</a>	<a href="#">R6706-R6718.pdf</a>
R83-1010602	<a href="#">R83-101_obsolete.pdf</a>	24/12/2015	<a href="#">R44-1000602</a>	<a href="#">R44-100.pdf</a>
R83-1010902	<a href="#">R83-101_obsolete.pdf</a>	24/12/2015	<a href="#">R44-1000902</a>	<a href="#">R44-100.pdf</a>
R83-1011002	<a href="#">R83-101_obsolete.pdf</a>	24/12/2015	<a href="#">R44-1001002</a>	<a href="#">R44-100.pdf</a>
R83-1011202	<a href="#">R83-101_obsolete.pdf</a>	24/12/2015	<a href="#">R44-1001202</a>	<a href="#">R44-100.pdf</a>
R83-1011302	<a href="#">R83-101_obsolete.pdf</a>	24/12/2015	<a href="#">R44-1001302</a>	<a href="#">R44-100.pdf</a>
R83-1011502	<a href="#">R83-101_obsolete.pdf</a>	24/12/2015	<a href="#">R44-1001502</a>	<a href="#">R44-100.pdf</a>
R83-1011602	<a href="#">R83-101_obsolete.pdf</a>	24/12/2015	<a href="#">R44-1001602</a>	<a href="#">R44-100.pdf</a>
R83-1011902	<a href="#">R83-101_obsolete.pdf</a>	24/12/2015	<a href="#">R44-1001902</a>	<a href="#">R44-100.pdf</a>
R83-1012202	<a href="#">R83-101_obsolete.pdf</a>	24/12/2015	<a href="#">R44-1002202</a>	<a href="#">R44-100.pdf</a>
R83-1012302	<a href="#">R83-101_obsolete.pdf</a>	24/12/2015	<a href="#">R44-1002302</a>	<a href="#">R44-100.pdf</a>

## Obsolete Product Notification from Harwin - Standard

Part number being made obsolete	Drawing for obsolete product	Last Time Buy?	Alternative product	Drawing for alternative product
R83-1012502	<a href="#">R83-101_obsolete.pdf</a>	24/12/2015	None	
R83-1013002	<a href="#">R83-101_obsolete.pdf</a>	24/12/2015	None	
R83-1013502	<a href="#">R83-101_obsolete.pdf</a>	24/12/2015	None	
R83-1014502	<a href="#">R83-101_obsolete.pdf</a>	24/12/2015	None	
R83-1015002	<a href="#">R83-101_obsolete.pdf</a>	24/12/2015	None	
S1771-06	Contact technical@harwin.com	No - immediate	None	
S1781-06	Contact technical@harwin.com	No - immediate	None	
T5748-09	Contact technical@harwin.com	No - immediate	<a href="#">Z80-280</a>	<a href="#">Z80-280.pdf</a>
T5748-10	Contact technical@harwin.com	No - immediate	<a href="#">Z80-280</a>	<a href="#">Z80-280.pdf</a>
W2130-00	<a href="#">W2130_obsolete.pdf</a>	24/12/2015	<a href="#">W2131-00</a>	<a href="#">W2131.pdf</a>
W2334-00	<a href="#">W2334_obsolete.pdf</a>	24/12/2015	<a href="#">R30-3011102</a>	<a href="#">R30-301.pdf</a>
W2630-00	<a href="#">W2630_obsolete.pdf</a>	24/12/2015	<a href="#">W2131-00</a>	<a href="#">W2131.pdf</a>
Z2073-00	Contact technical@harwin.com	No - immediate	None	
Z2152-00	<a href="#">Z2152_obsolete.pdf</a>	24/12/2015	None	
Z2156-00	<a href="#">Z2156_obsolete.pdf</a>	No - immediate	None	
Z2157-00	<a href="#">Z2157_obsolete.pdf</a>	No - immediate	None	
Z2158-00	<a href="#">Z2158_obsolete.pdf</a>	24/12/2015	None	
Z3073-00	<a href="#">Z3073_obsolete.pdf</a>	24/12/2015	None	
Z3075-00	Contact technical@harwin.com	No - immediate	None	
Z3076-00	Contact technical@harwin.com	No - immediate	None	
Z3146-00	Contact technical@harwin.com	No - immediate	None	
Z3150-00	<a href="#">Z3150_obsolete.pdf</a>	No - immediate	None	
Z3151-00	<a href="#">Z3151_obsolete.pdf</a>	No - immediate	None	
Z80-288	Contact technical@harwin.com	No - immediate	None	
Z9018-00	Contact technical@harwin.com	No - immediate	None	
Z9023S00	Contact technical@harwin.com	No - immediate	None	
Z9035-00	Contact technical@harwin.com	No - immediate	None	
Z9039-00	<a href="#">Z9039_obsolete.pdf</a>	24/12/2015	None	
Z9044-00	Contact technical@harwin.com	No - immediate	None	
Z9069-00	<a href="#">Z9069_obsolete.pdf</a>	24/12/2015	None	

## Obsolete Product Notification from Harwin - Special

Part number being made obsolete	Drawing for obsolete product	Last Time Buy?
Z103841C	Contact technical@harwin.com	No - immediate
Z105312C	Contact technical@harwin.com	No - immediate
Z105760C	Contact technical@harwin.com	No - immediate
Z106541C	Contact technical@harwin.com	No - immediate
Z106637C	Contact technical@harwin.com	No - immediate
Z106956C	Contact technical@harwin.com	No - immediate
Z107447C	Contact technical@harwin.com	No - immediate
Z107882C	Contact technical@harwin.com	No - immediate
Z108698C	Contact technical@harwin.com	No - immediate
Z22C106987C	Contact technical@harwin.com	No - immediate
Z22C106988C	Contact technical@harwin.com	No - immediate