



Harwin plc
Fitzherbert Road
Farlington, Portsmouth
Hampshire PO6 1RT
United Kingdom

Reception: +44 (0)23 9231 4545
Sales Desk: +44 (0)23 9237 0451
Fax: +44 (0)23 9231 4590

Monday 7th December, 2015

Dear Customer,

Re: Obsolescence notification for Harwin product.

Please be advised that there are a number of individual items that are now obsolete. **Some of these items have a Last Time Buy date of 4th March 2016** – please check the attached spreadsheet list for specific details. The rest of the items are obsolete with immediate effect; stocks may remain of a few items, but most of these have not been manufactured in more than 8 years. Please see the attached spreadsheet for a complete list of affected items (there are two sheets in the spreadsheet, please check both). Here is a summary of affected standard ranges:

- Extended SIL IC Sockets D01-950xxxx
- PLCC connectors: D830xxB-46, D830xxC-46, D840xxB-46
- Reeled PCB sockets starting S31xx, S80xx and S85xx
- A selection of special items

Unfortunately, we are no longer able to support these product lines.

If you have any further questions regarding this letter, please do not hesitate to contact us.

Yours faithfully,

The Product Management Team
technical@harwin.com

If you have not been sent the accompanying spreadsheet, please request it from the contact that sent you this letter.

Obsolete Product Notification from Harwin - Standard

Part number being made obsolete	Drawing for obsolete product	Last Time Buy?	Alternative product	Drawing for alternative product
D01-9500442	D01-950_obsolete.pdf	04/03/2016	D01-9970442	D01-997.pdf
D01-9500542	D01-950_obsolete.pdf	04/03/2016	D01-9970542	D01-997.pdf
D01-9500642	D01-950_obsolete.pdf	04/03/2016	D01-9970642	D01-997.pdf
D01-9500742	D01-950_obsolete.pdf	04/03/2016	D01-9970742	D01-997.pdf
D01-9500842	D01-950_obsolete.pdf	04/03/2016	D01-9970842	D01-997.pdf
D01-9500942	D01-950_obsolete.pdf	04/03/2016	D01-9970942	D01-997.pdf
D01-9501042	D01-950_obsolete.pdf	04/03/2016	D01-9971042	D01-997.pdf
D01-9501242	D01-950_obsolete.pdf	04/03/2016	D01-9971242	D01-997.pdf
D01-9501442	D01-950_obsolete.pdf	04/03/2016	D01-9971442	D01-997.pdf
D01-9501642	D01-950_obsolete.pdf	04/03/2016	D01-9971642	D01-997.pdf
D01-9501842	D01-950_obsolete.pdf	04/03/2016	D01-9971842	D01-997.pdf
D01-9502042	D01-950_obsolete.pdf	04/03/2016	D01-9972042	D01-997.pdf
D01-9503242	D01-950_obsolete.pdf	04/03/2016	D01-9973242	D01-997.pdf
D01-9506442	D01-950_obsolete.pdf	04/03/2016	D01-9973242	D01-997.pdf
D83020B-46	D830XXB-XX_obsolete.pdf	04/03/2016	None	
D83020B-46R	D830XXB-XXR_obsolete.pdf	04/03/2016	None	
D83020C-46	D830XXC-XX_obsolete.pdf	04/03/2016	None	
D83028B-46	D830XXB-XX_obsolete.pdf	04/03/2016	None	
D83028B-46R	D830XXB-XXR_obsolete.pdf	04/03/2016	None	
D83028C-46	D830XXC-XX_obsolete.pdf	04/03/2016	None	
D83032B-46	D830XXB-XX_obsolete.pdf	04/03/2016	None	
D83032B-46R	D830XXB-XXR_obsolete.pdf	04/03/2016	None	
D83032C-46	D830XXC-XX_obsolete.pdf	04/03/2016	None	
D83044B-46	D830XXB-XX_obsolete.pdf	04/03/2016	None	
D83044B-46R	D830XXB-XXR_obsolete.pdf	04/03/2016	None	
D83044C-46	D830XXC-XX_obsolete.pdf	04/03/2016	None	
D83052B-46	D830XXB-XX_obsolete.pdf	04/03/2016	None	
D83052C-46	D830XXC-XX_obsolete.pdf	04/03/2016	None	
D83068B-46	D830XXB-XX_obsolete.pdf	04/03/2016	None	
D83068B-46R	D830XXB-XXR_obsolete.pdf	04/03/2016	None	
D83068C-46	D830XXC-XX_obsolete.pdf	04/03/2016	None	
D83084B-46	D830XXB-XX_obsolete.pdf	04/03/2016	None	
D83084C-46	D830XXC-XX_obsolete.pdf	04/03/2016	None	
D84028B-46	D840XXB-XX_obsolete.pdf	04/03/2016	None	
D84032B-46	D840XXB-XX_obsolete.pdf	04/03/2016	None	
D84032B-46R	D840XXB-XXR_obsolete.pdf	04/03/2016	None	
D84044B-46	D840XXB-XX_obsolete.pdf	04/03/2016	None	
D84068B-46	D840XXB-XX_obsolete.pdf	04/03/2016	None	
D84068B-46R	D840XXB-XXR_obsolete.pdf	04/03/2016	None	
D84084B-46	D840XXB-XX_obsolete.pdf	04/03/2016	None	
D84084B-46R	D840XXB-XXR_obsolete.pdf	04/03/2016	None	
S8042-01	S8042-S8043_obsolete.pdf	No - immediate	H3153-01	H3153.pdf
S8043-01	S8042-S8043_obsolete.pdf	No - immediate	H3153-01	H3153.pdf
S8062-01	S8062-S8063_obsolete.pdf	No - immediate	H8501-01	H8501.pdf
S8063-01	S8062-S8063_obsolete.pdf	No - immediate	H8501-01	H8501.pdf
S8078-01	S8078-S8079_obsolete.pdf	No - immediate	H8501-01	H8501.pdf
S8079-01	S8078-S8079_obsolete.pdf	No - immediate	H8501-01	H8501.pdf
S8094-01	S8094-S8095_obsolete.pdf	No - immediate	H3153-01	H3153.pdf
S8095-01	S8094-S8095_obsolete.pdf	No - immediate	H3153-01	H3153.pdf
S3161-01	S3161_obsolete.pdf	No - immediate	H3161-01	H3161.pdf
S3161-05	S3161_obsolete.pdf	No - immediate	H3161-05	H3161.pdf
S3161-T6	S3161_obsolete.pdf	No - immediate	H3161-46	H3161.pdf
S3165-01	S3165_obsolete.pdf	No - immediate	H3165-01	H3165.pdf
S3165-05	S3165_obsolete.pdf	No - immediate	H3165-05	H3165.pdf
S3165-T6	S3165_obsolete.pdf	No - immediate	H3165-46	H3165.pdf
S8501-01	S8501_obsolete.pdf	No - immediate	H8501-01	H8501.pdf
S8501-05	S8501_obsolete.pdf	No - immediate	H8501-05	H8501.pdf
S8501-T6	S8501_obsolete.pdf	No - immediate	H8501-46	H8501.pdf

Obsolete Product Notification from Harwin - Special

Part number being made obsolete	Drawing for obsolete product	Last Time Buy?
C106181C	Contact technical@harwin.com	No - immediate
C106445C	Contact technical@harwin.com	No - immediate
C106674C	Contact technical@harwin.com	No - immediate
C106675C	Contact technical@harwin.com	No - immediate
C107252C	Contact technical@harwin.com	No - immediate
C107710C	Contact technical@harwin.com	No - immediate
D01C108073C	Contact technical@harwin.com	No - immediate
D01C108339C	Contact technical@harwin.com	No - immediate
D01C108461C	Contact technical@harwin.com	No - immediate
D01R9901401	Contact technical@harwin.com	No - immediate
D108187C	Contact technical@harwin.com	No - immediate
D108280C	Contact technical@harwin.com	No - immediate
D108280C-A	Contact technical@harwin.com	No - immediate
H104305C	Contact technical@harwin.com	No - immediate
H104871C	Contact technical@harwin.com	No - immediate
H105787C	Contact technical@harwin.com	No - immediate
H106726C	Contact technical@harwin.com	No - immediate
H106781C	Contact technical@harwin.com	No - immediate
H106828C	Contact technical@harwin.com	No - immediate
H107306C	Contact technical@harwin.com	No - immediate
H107432C	Contact technical@harwin.com	No - immediate
H107456C	Contact technical@harwin.com	No - immediate
H107667C	Contact technical@harwin.com	No - immediate
H107858C	Contact technical@harwin.com	No - immediate
H108030C	Contact technical@harwin.com	No - immediate
H108056C-PRE	Contact technical@harwin.com	No - immediate
H150190C	Contact technical@harwin.com	No - immediate
H3153PTET6	Contact technical@harwin.com	No - immediate
H3161PTE05	Contact technical@harwin.com	No - immediate
H3161RM01	Contact technical@harwin.com	No - immediate
H3165PTE05	Contact technical@harwin.com	No - immediate
HD5174	Contact technical@harwin.com	No - immediate
M106713CR	Contact technical@harwin.com	No - immediate
M60C108184C	Contact technical@harwin.com	No - immediate
M60C108185C	Contact technical@harwin.com	No - immediate
M85C108470C	Contact technical@harwin.com	No - immediate