

Harwin plc Fitzherbert Road Farlington, Portsmouth Hampshire PO6 1RT United Kingdom

Reception: +44 (0)23 9231 4545 Sales Desk: +44 (0)23 9237 0451 Fax: +44 (0)23 9231 4590

Wednesday 20th January, 2016

Dear Customer,

Re: Obsolescence notification for Harwin product.

Please be advised that there are a number of individual items that are now obsolete with immediate effect. These products have not been manufactured for a number of years, and there will be no stock available. Please see the attached spreadsheet for a complete list of affected items. Here is a summary of affected standard ranges:

- Tact Switch M801-3001100
- Tact Switch M801-31X0X00R
- Tact Switch M803-2100200

Unfortunately, we are no longer able to support these product lines.

If you have any further questions regarding this letter, please do not hesitate to contact us.

Yours faithfully,

The Product Management Team technical@harwin.com

If you have not been sent the accompanying spreadsheet, please request it from the contact that sent you this letter.

## **Obsolete Product Notification from Harwin**

Part number being	Drawing for	Loot Time Dung	Alternative	Drawing for
made obsolete	obsolete product	Last Time Buy?	product	alternative product
M801-3001100	M801-3001100 obsolete.pdf	No - immediate	None	
M801-3110100R	M801-31X0X00R_obsolete.pdf	No - immediate	None	
M801-3110200R	M801-31X0X00R obsolete.pdf	No - immediate	None	
M801-3110300R	M801-31X0X00R obsolete.pdf	No - immediate	None	
M801-3110400R	M801-31X0X00R_obsolete.pdf	No - immediate	None	
M801-3110500R	M801-31X0X00R_obsolete.pdf	No - immediate	None	
M801-3110600R	M801-31X0X00R obsolete.pdf	No - immediate	None	
M801-3120100R	M801-31X0X00R obsolete.pdf	No - immediate	None	
M801-3120200R	M801-31X0X00R_obsolete.pdf	No - immediate	None	
M801-3120300R	M801-31X0X00R obsolete.pdf	No - immediate	None	
M801-3120400R	M801-31X0X00R obsolete.pdf	No - immediate	None	
M801-3120500R	M801-31X0X00R obsolete.pdf	No - immediate	None	
M801-3120600R	M801-31X0X00R_obsolete.pdf	No - immediate	None	
M803-2100200	M803-2100200 obsolete.pdf	No - immediate	None	