



Harwin plc
Fitzherbert Road
Farlington, Portsmouth
Hampshire PO6 1RT
United Kingdom

Reception: +44 (0)23 9231 4545
Sales Desk: +44 (0)23 9237 0451
Fax: +44 (0)23 9231 4590

Thursday 28th January, 2016

Dear Customer,

Re: Obsolescence notification for Harwin product.

Please be advised that there are a number of individual items that are now obsolete. One of these items has a Last Time Buy date of 15th February 2016, the rest of the items are obsolete with immediate effect. Stocks may remain of a few items, but most of these have not been manufactured in some time. Please see the attached spreadsheet for a complete list of affected items (there are two sheets in the spreadsheet, please check both). Here is a summary of affected standard ranges:

- Tact Switches M802, M804, M807
- Various customer specials

Unfortunately, we are no longer able to support these product lines.

If you have any further questions regarding this letter, please do not hesitate to contact us.

Yours faithfully,

The Product Management Team
technical@harwin.com

If you have not been sent the accompanying spreadsheet, please request it from the contact that sent you this letter.

Obsolete Product Notification from Harwin - Standard

Part number being made obsolete	Drawing for obsolete product	Last Time Buy?	Alternative product	Drawing for alternative product
M802-2300400	Contact technical@harwin.com	No - immediate	None	
M804-2450000	Contact technical@harwin.com	No - immediate	None	
M804-2480000	Contact technical@harwin.com	No - immediate	None	
M807-2010000	Contact technical@harwin.com	No - immediate	None	
M807-3010000	Contact technical@harwin.com	No - immediate	None	

Obsolete Product Notification from Harwin - Special

Part number being made obsolete	Drawing for obsolete product	Last Time Buy?
3414-7641-02	Contact technical@harwin.com	15/02/2016
BLD-PCB6.3X0.5MM	Contact technical@harwin.com	No - immediate
H107358C	Contact technical@harwin.com	No - immediate
HD4343-06	Contact technical@harwin.com	No - immediate
HD5008-06	Contact technical@harwin.com	No - immediate
HD5037	Contact technical@harwin.com	No - immediate
HD5038	Contact technical@harwin.com	No - immediate
HD5049	Contact technical@harwin.com	No - immediate
HD5056	Contact technical@harwin.com	No - immediate
HD5168	Contact technical@harwin.com	No - immediate
HD5460	Contact technical@harwin.com	No - immediate
HD5461	Contact technical@harwin.com	No - immediate
HD5815	Contact technical@harwin.com	No - immediate
HD5816	Contact technical@harwin.com	No - immediate
HD5817	Contact technical@harwin.com	No - immediate
HD5818	Contact technical@harwin.com	No - immediate
HD5819	Contact technical@harwin.com	No - immediate
HD5820	Contact technical@harwin.com	No - immediate
HD5821	Contact technical@harwin.com	No - immediate
HD5822	Contact technical@harwin.com	No - immediate
HD5823	Contact technical@harwin.com	No - immediate
HD5855	Contact technical@harwin.com	No - immediate
HD5856	Contact technical@harwin.com	No - immediate
HD5857	Contact technical@harwin.com	No - immediate
HD5891	Contact technical@harwin.com	No - immediate
HD5892	Contact technical@harwin.com	No - immediate
HD5893	Contact technical@harwin.com	No - immediate
M40C108441C	Contact technical@harwin.com	No - immediate
S107021C	Contact technical@harwin.com	No - immediate
S107021CR	Contact technical@harwin.com	No - immediate
S107058C	Contact technical@harwin.com	No - immediate
S107059C	Contact technical@harwin.com	No - immediate
S107280C	Contact technical@harwin.com	No - immediate
S107281C	Contact technical@harwin.com	No - immediate
S107347C	Contact technical@harwin.com	No - immediate
S107348C	Contact technical@harwin.com	No - immediate
S107400C	Contact technical@harwin.com	No - immediate
S107401C	Contact technical@harwin.com	No - immediate