



Harwin plc
Fitzherbert Road
Farlington, Portsmouth
Hampshire PO6 1RT
United Kingdom

Reception: +44 (0)23 9231 4545
Sales Desk: +44 (0)23 9237 0451
Fax: +44 (0)23 9231 4590

Monday 11th December, 2017

Dear Customer,

Re: Obsolescence notification for Harwin product.

Please be advised that there are a number of items that are now obsolete. A few items covered by this notification are obsolete **with immediate effect**. They include:

- 6050-0005-802, 6050-0005-803
- B5743-234-M-X-0, M80C109246C

The remainder of the items have a **Last Time Buy date of Friday, 9th March 2018** – these include:

- B5743-1xx-M-L-Y, B5743-1xx-M-T-A, B5743-1xx-M-T-T, B5743-2xx-M-L-Y, B5743-2xx-M-T-B, B5743-2xx-M-T-U, B5743-2xx-M-T-V series
- M80-457, M80-458, M80-614, M80-615, M80-616, M80-617, M80-682, M80-740, M80-789, M80-791, M80-793, M80-796, M80-819, M80-820, M80-822, M80-823, M80-824, M80-825, M80-855, M80-856, M80-858, M80-865, M80-890, M80-891, M80-894 series.
- A list of customer special products.

Please see the following spreadsheet for a detailed list of affected items:

https://cdn.harwin.com/pdfs/Obsolescence_notification_spreadsheet_Datamate_Products_December_2017.xlsx

Unfortunately, we are no longer able to support these products.

If you have any further questions regarding this letter, please do not hesitate to contact us.

Yours faithfully,

The Product Change Team
technical@harwin.com

Obsolete Product Notification from Harwin

Part number being made obsolete	Drawing for obsolete product	Last Time Buy?	Alternative product	Drawing for alternative product	Notes
6050-0005-802	Contact technical@harwin.com	Immediate	Contact technical@harwin.com		
6050-0005-803	Contact technical@harwin.com	Immediate	Contact technical@harwin.com		
B5743-102-M-L-Y	M80-804.pdf	09-Mar-18	M80-8040222	M80-804.pdf	
B5743-102-M-T-A	M80-820 obsolete.pdf	09-Mar-18	M80-7820245	M80-782.pdf	
B5743-102-M-T-T	M80-820 obsolete.pdf	09-Mar-18	M80-7820242	M80-782.pdf	
B5743-103-M-L-Y	M80-804.pdf	09-Mar-18	M80-8040322	M80-804.pdf	
B5743-103-M-T-A	M80-820 obsolete.pdf	09-Mar-18	M80-7820345	M80-782.pdf	
B5743-103-M-T-T	M80-820 obsolete.pdf	09-Mar-18	M80-7820342	M80-782.pdf	
B5743-104-M-L-Y	M80-804.pdf	09-Mar-18	M80-8040422	M80-804.pdf	
B5743-104-M-T-A	M80-820 obsolete.pdf	09-Mar-18	M80-7820445	M80-782.pdf	
B5743-104-M-T-T	M80-820 obsolete.pdf	09-Mar-18	M80-7820442	M80-782.pdf	
B5743-105-M-L-Y	M80-804.pdf	09-Mar-18	M80-8040522	M80-804.pdf	
B5743-105-M-T-A	M80-820 obsolete.pdf	09-Mar-18	M80-7820545	M80-782.pdf	
B5743-105-M-T-T	M80-820 obsolete.pdf	09-Mar-18	M80-7820542	M80-782.pdf	
B5743-106-M-L-Y	M80-804.pdf	09-Mar-18	M80-8040622	M80-804.pdf	
B5743-106-M-T-A	M80-820 obsolete.pdf	09-Mar-18	M80-7820645	M80-782.pdf	
B5743-106-M-T-T	M80-820 obsolete.pdf	09-Mar-18	M80-7820642	M80-782.pdf	
B5743-107-M-L-Y	M80-804.pdf	09-Mar-18	M80-8040722	M80-804.pdf	
B5743-107-M-T-A	M80-820 obsolete.pdf	09-Mar-18	M80-7820745	M80-782.pdf	
B5743-107-M-T-T	M80-820 obsolete.pdf	09-Mar-18	M80-7820742	M80-782.pdf	
B5743-117-M-L-Y	M80-804.pdf	09-Mar-18	M80-8041722	M80-804.pdf	
B5743-117-M-T-A	M80-820 obsolete.pdf	09-Mar-18	M80-7821745	M80-782.pdf	
B5743-117-M-T-T	M80-820 obsolete.pdf	09-Mar-18	M80-7821742	M80-782.pdf	
B5743-122-M-L-Y	M80-804.pdf	09-Mar-18	M80-8042222	M80-804.pdf	
B5743-122-M-T-A	M80-820 obsolete.pdf	09-Mar-18	M80-7822245	M80-782.pdf	
B5743-122-M-T-T	M80-820 obsolete.pdf	09-Mar-18	M80-7822242	M80-782.pdf	
B5743-204-M-L-Y	M80-814.pdf	09-Mar-18	M80-8140422	M80-814.pdf	
B5743-204-M-T-B	M80-856 obsolete.pdf	09-Mar-18	M80-7530445	M80-753.pdf	
B5743-204-M-T-U	M80-819 obsolete.pdf	09-Mar-18	M80-7540442	M80-754.pdf	
B5743-204-M-T-V	M80-858 obsolete.pdf	09-Mar-18	M80-7540442	M80-754.pdf	
B5743-204-M-T-W	M80-856 obsolete.pdf	09-Mar-18	M80-7530442	M80-753.pdf	
B5743-206-M-L-Y	M80-814.pdf	09-Mar-18	M80-8140622	M80-814.pdf	
B5743-206-M-T-B	M80-856 obsolete.pdf	09-Mar-18	M80-7530645	M80-753.pdf	
B5743-206-M-T-U	M80-819 obsolete.pdf	09-Mar-18	M80-7540645	M80-754.pdf	
B5743-206-M-T-V	M80-858 obsolete.pdf	09-Mar-18	M80-7540645	M80-754.pdf	
B5743-206-M-T-W	M80-856 obsolete.pdf	09-Mar-18	M80-7530642	M80-753.pdf	
B5743-208-M-L-Y	M80-814.pdf	09-Mar-18	M80-8140822	M80-814.pdf	
B5743-208-M-T-B	M80-856 obsolete.pdf	09-Mar-18	M80-7530845	M80-753.pdf	
B5743-208-M-T-U	M80-819 obsolete.pdf	09-Mar-18	M80-7540842	M80-754.pdf	
B5743-208-M-T-V	M80-858 obsolete.pdf	09-Mar-18	M80-7540842	M80-754.pdf	
B5743-208-M-T-W	M80-856 obsolete.pdf	09-Mar-18	M80-7530842	M80-753.pdf	
B5743-210-M-L-Y	M80-814.pdf	09-Mar-18	M80-8141022	M80-814.pdf	
B5743-210-M-T-B	M80-856 obsolete.pdf	09-Mar-18	M80-7531045	M80-753.pdf	
B5743-210-M-T-U	M80-819 obsolete.pdf	09-Mar-18	M80-7541042	M80-754.pdf	
B5743-210-M-T-V	M80-858 obsolete.pdf	09-Mar-18	M80-7541042	M80-754.pdf	
B5743-210-M-T-W	M80-856 obsolete.pdf	09-Mar-18	M80-7531042	M80-753.pdf	
B5743-212-M-L-Y	M80-814.pdf	09-Mar-18	M80-8141222	M80-814.pdf	
B5743-212-M-T-B	M80-856 obsolete.pdf	09-Mar-18	M80-7531245	M80-753.pdf	
B5743-212-M-T-U	M80-819 obsolete.pdf	09-Mar-18	M80-7541242	M80-754.pdf	
B5743-212-M-T-V	M80-858 obsolete.pdf	09-Mar-18	M80-7541242	M80-754.pdf	
B5743-212-M-T-W	M80-856 obsolete.pdf	09-Mar-18	M80-7531242	M80-753.pdf	
B5743-214-M-L-Y	M80-814.pdf	09-Mar-18	M80-8141422	M80-814.pdf	
B5743-214-M-T-B	M80-856 obsolete.pdf	09-Mar-18	M80-7531445	M80-753.pdf	
B5743-214-M-T-U	M80-819 obsolete.pdf	09-Mar-18	M80-7541445	M80-754.pdf	
B5743-214-M-T-V	M80-858 obsolete.pdf	09-Mar-18	M80-7541445	M80-754.pdf	
B5743-214-M-T-W	M80-856 obsolete.pdf	09-Mar-18	M80-7531442	M80-753.pdf	
B5743-216-M-L-Y	M80-814.pdf	09-Mar-18	M80-8141622	M80-814.pdf	
B5743-216-M-T-B	M80-856 obsolete.pdf	09-Mar-18	M80-7531645	M80-753.pdf	
B5743-216-M-T-U	M80-819 obsolete.pdf	09-Mar-18	M80-7541642	M80-754.pdf	
B5743-216-M-T-V	M80-858 obsolete.pdf	09-Mar-18	M80-7541642	M80-754.pdf	
B5743-216-M-T-W	M80-856 obsolete.pdf	09-Mar-18	M80-7531642	M80-753.pdf	
B5743-218-M-L-Y	M80-814.pdf	09-Mar-18	M80-8391842	M80-814.pdf	
B5743-218-M-T-B	M80-856 obsolete.pdf	09-Mar-18	M80-7531845	M80-753.pdf	
B5743-218-M-T-U	M80-819 obsolete.pdf	09-Mar-18	M80-7541842	M80-754.pdf	
B5743-218-M-T-V	M80-858 obsolete.pdf	09-Mar-18	M80-7541842	M80-754.pdf	
B5743-218-M-T-W	M80-856 obsolete.pdf	09-Mar-18	M80-7531842	M80-753.pdf	
B5743-220-M-L-Y	M80-814.pdf	09-Mar-18	M80-8142022	M80-814.pdf	
B5743-220-M-T-B	M80-856 obsolete.pdf	09-Mar-18	M80-7532045	M80-753.pdf	
B5743-220-M-T-U	M80-819 obsolete.pdf	09-Mar-18	M80-7542042	M80-754.pdf	
B5743-220-M-T-V	M80-858 obsolete.pdf	09-Mar-18	M80-7542042	M80-754.pdf	
B5743-220-M-T-W	M80-856 obsolete.pdf	09-Mar-18	M80-7532042	M80-753.pdf	
B5743-226-M-L-Y	M80-814.pdf	09-Mar-18	M80-8142622	M80-814.pdf	
B5743-226-M-T-B	M80-856 obsolete.pdf	09-Mar-18	M80-7532645	M80-753.pdf	
B5743-226-M-T-U	M80-819 obsolete.pdf	09-Mar-18	M80-7542642	M80-754.pdf	
B5743-226-M-T-V	M80-858 obsolete.pdf	09-Mar-18	M80-7542642	M80-754.pdf	
B5743-226-M-T-W	M80-856 obsolete.pdf	09-Mar-18	M80-7532642	M80-753.pdf	
B5743-234-M-L-Y	M80-814.pdf	09-Mar-18	M80-8143422	M80-814.pdf	
B5743-234-M-T-B	M80-856 obsolete.pdf	09-Mar-18	M80-7533445	M80-753.pdf	
B5743-234-M-T-U	M80-819 obsolete.pdf	09-Mar-18	M80-7543442	M80-754.pdf	
B5743-234-M-T-V	M80-858 obsolete.pdf	09-Mar-18	M80-7543442	M80-754.pdf	
B5743-234-M-T-W	M80-856 obsolete.pdf	09-Mar-18	M80-7533442	M80-753.pdf	
B5743-234-M-X-0	Contact technical@harwin.com	Immediate	M80-7543442	M80-754.pdf	
B5743-244-M-L-Y	M80-814.pdf	09-Mar-18	M80-8144422	M80-814.pdf	
B5743-244-M-T-B	M80-856 obsolete.pdf	09-Mar-18	M80-7534445	M80-753.pdf	
B5743-244-M-T-U	M80-819 obsolete.pdf	09-Mar-18	M80-7544442	M80-754.pdf	
B5743-244-M-T-V	M80-858 obsolete.pdf	09-Mar-18	M80-7544442	M80-754.pdf	
B5743-244-M-T-W	M80-856 obsolete.pdf	09-Mar-18	M80-7534442	M80-753.pdf	
M104694C	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M104787C	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M104788C	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M104789C	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M104790C	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M104791C	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M104792C	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M104793C	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		

Obsolete Product Notification from Harwin

Part number being made obsolete	Drawing for obsolete product	Last Time Buy?	Alternative product	Drawing for alternative product	Notes
M104794C	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M104795C	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M104796C	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M104797C	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M104798C	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M104799C	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M104802C	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M104803C	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M80-1030491	Contact technical@harwin.com	09-Mar-18	M80-1030498S	M80-103S.pdf	
M80-4570498	M80-457_obsolete.pdf	09-Mar-18	M80-4550498	M80-455.pdf	
M80-4570698	M80-457_obsolete.pdf	09-Mar-18	M80-4550698	M80-455.pdf	
M80-4570898	M80-457_obsolete.pdf	09-Mar-18	M80-4550898	M80-455.pdf	
M80-4571098	M80-457_obsolete.pdf	09-Mar-18	M80-4551098	M80-455.pdf	
M80-4571298	M80-457_obsolete.pdf	09-Mar-18	M80-4551298	M80-455.pdf	
M80-4571498	M80-457_obsolete.pdf	09-Mar-18	M80-4551498	M80-455.pdf	
M80-4572098	M80-457_obsolete.pdf	09-Mar-18	M80-4552098	M80-455.pdf	
M80-4572698	M80-457_obsolete.pdf	09-Mar-18	M80-4552698	M80-455.pdf	
M80-4572898	M80-457_obsolete.pdf	09-Mar-18	M80-4552898	M80-455.pdf	
M80-4573498	M80-457_obsolete.pdf	09-Mar-18	M80-4553498	M80-455.pdf	
M80-4574298	M80-457_obsolete.pdf	09-Mar-18	M80-4554298	M80-455.pdf	
M80-4575098	M80-457_obsolete.pdf	09-Mar-18	M80-4555098	M80-455.pdf	
M80-4580498	M80-458_obsolete.pdf	09-Mar-18	M80-4550498	M80-455.pdf	
M80-4580698	M80-458_obsolete.pdf	09-Mar-18	M80-4550698	M80-455.pdf	
M80-4580898	M80-458_obsolete.pdf	09-Mar-18	M80-4550898	M80-455.pdf	
M80-4581098	M80-458_obsolete.pdf	09-Mar-18	M80-4551098	M80-455.pdf	
M80-4581298	M80-458_obsolete.pdf	09-Mar-18	M80-4551298	M80-455.pdf	
M80-4581498	M80-458_obsolete.pdf	09-Mar-18	M80-4551498	M80-455.pdf	
M80-4582098	M80-458_obsolete.pdf	09-Mar-18	M80-4552098	M80-455.pdf	
M80-4582698	M80-458_obsolete.pdf	09-Mar-18	M80-4552698	M80-455.pdf	
M80-4582898	M80-458_obsolete.pdf	09-Mar-18	M80-4552898	M80-455.pdf	
M80-4583498	M80-458_obsolete.pdf	09-Mar-18	M80-4553498	M80-455.pdf	
M80-4584298	M80-458_obsolete.pdf	09-Mar-18	M80-4554298	M80-455.pdf	
M80-4585098	M80-458_obsolete.pdf	09-Mar-18	M80-4555098	M80-455.pdf	
M80-4C100F1-60-327	M80-4C100F1-60-327_obsolete.pdf	09-Mar-18	M80-4000000F1-06-327-00-000	M80-4000000F1-XX-XXX-00-000.pdf	
M80-4C100F1-66-327	M80-4C100F1-66-327_obsolete.pdf	09-Mar-18	M80-4000000F1-12-327-00-000	M80-4000000F1-XX-XXX-00-000.pdf	
M80-4C100F2-20-327	M80-4C100F2-20-327_obsolete.pdf	09-Mar-18	M80-4000000F2-02-327-00-000	M80-4000000F2-XX-XXX-00-000.pdf	
M80-4C100F2-40-325	M80-4C100F2-40-325_obsolete.pdf	09-Mar-18	M80-4000000F2-04-325-00-000	M80-4000000F2-XX-XXX-00-000.pdf	
M80-4C100F2-50-327	M80-4C100F2-50-327_obsolete.pdf	09-Mar-18	M80-4000000F2-05-327-00-000	M80-4000000F2-XX-XXX-00-000.pdf	
M80-4C102F1-11-000	M80-4C102F1-11-000_obsolete.pdf	09-Mar-18	Contact technical@harwin.com		
M80-4C102F1-11-305	M80-4C102F1-11-305_obsolete.pdf	09-Mar-18	Contact technical@harwin.com		
M80-4C102F1-22-000	M80-4C102F1-22-000_obsolete.pdf	09-Mar-18	Contact technical@harwin.com		
M80-5C106M4	Contact technical@harwin.com	09-Mar-18	M80-5C10605M5	M80-5C1XX05M5.pdf	
M80-5D104M1-11-335	M80-5D104M1-11-335_obsolete.pdf	09-Mar-18	Contact technical@harwin.com		
M80-5L100M1-50-333	M80-5L100M1-50-333_obsolete.pdf	09-Mar-18	M80-5000000M1-05-333-00-000	M80-5000000M1-XX-XXX-00-000.pdf	
M80-5L100M4-40-333	M80-5L100M4-40-333_obsolete.pdf	09-Mar-18	M80-5000000M5-04-333-00-000	M80-5000000M5-XX-XXX-00-000.pdf	
M80-5L104M5-02-333	M80-5L104M5-02-333_obsolete.pdf	09-Mar-18	Contact technical@harwin.com		
M80-5L104M5-20-333	M80-5L104M5-20-333_obsolete.pdf	09-Mar-18	M80-5L10422M5-02-333-00-000	M80-5L10422M5-02-333-00-000.pdf	
M80-5L11000-03-333	M80-5L11000-03-333_obsolete.pdf	09-Mar-18	Contact technical@harwin.com		
M80-5L110M1-12-313	M80-5L110M1-12-313_obsolete.pdf	09-Mar-18	Contact technical@harwin.com		
M80-5L110M4-03-313	M80-5L110M4-03-313_obsolete.pdf	09-Mar-18	Contact technical@harwin.com		
M80-5L12800-30-313	M80-5L12800-30-313_obsolete.pdf	09-Mar-18	Contact technical@harwin.com		
M80-5L202M5-11-334	M80-5L202M5-11-334_obsolete.pdf	09-Mar-18	M80-5L2022M5-01-334-01-334	M80-5L2022M5-01-334-01-334.pdf	
M80-5L22800-30-314	M80-5L22800-30-314_obsolete.pdf	09-Mar-18	Contact technical@harwin.com		
M80-5T100M2-66-331	M80-5T100M2-66-331_obsolete.pdf	09-Mar-18	M80-5000000M2-12-331-00-000	M80-5000000M2-XX-XXX-00-000.pdf	
M80-5T102M2-11-311	M80-5T102M2-11-311_obsolete.pdf	09-Mar-18	Contact technical@harwin.com		
M80-5T102M2-22-331	M80-5T102M2-22-331_obsolete.pdf	09-Mar-18	M80-5T1022M2-02-331-02-331	M80-5T1022M2-02-331-02-331.pdf	
M80-5T106M1-20-311	M80-5T106M1-20-311_obsolete.pdf	09-Mar-18	Contact technical@harwin.com		
M80-5T106M2-04-331	M80-5T106M2-04-331_obsolete.pdf	09-Mar-18	M80-5T10642M2-00-000-04-331	M80-5T10642M2-00-000-04-331.pdf	
M80-5T110M3-30-331	M80-5T110M3-30-331_obsolete.pdf	09-Mar-18	M80-5T11022M3-03-331-00-000	M80-5T11022M3-03-331-00-000.pdf	
M80-5T200M3-60-332	M80-5T200M3-60-332_obsolete.pdf	09-Mar-18	M80-5000000M3-06-332-00-000	M80-5000000M3-XX-XXX-00-000.pdf	
M80-5T202M3-11-000	M80-5T202M3-11-000_obsolete.pdf	09-Mar-18	Contact technical@harwin.com		
M80-5T202M3-22-000	M80-5T202M3-22-000_obsolete.pdf	09-Mar-18	Contact technical@harwin.com		
M80-6140201	M80-614_obsolete.pdf	09-Mar-18	M80-8400242	M80-840.pdf	
M80-6140242	M80-614_obsolete.pdf	09-Mar-18	M80-8400242	M80-840.pdf	
M80-6140245	M80-614_obsolete.pdf	09-Mar-18	M80-8400245	M80-840.pdf	
M80-6140301	M80-614_obsolete.pdf	09-Mar-18	M80-8400342	M80-840.pdf	
M80-6140342	M80-614_obsolete.pdf	09-Mar-18	M80-8400342	M80-840.pdf	
M80-6140345	M80-614_obsolete.pdf	09-Mar-18	M80-8400345	M80-840.pdf	
M80-6140401	M80-614_obsolete.pdf	09-Mar-18	M80-8400442	M80-840.pdf	
M80-6140442	M80-614_obsolete.pdf	09-Mar-18	M80-8400442	M80-840.pdf	
M80-6140445	M80-614_obsolete.pdf	09-Mar-18	M80-8400445	M80-840.pdf	
M80-6140501	M80-614_obsolete.pdf	09-Mar-18	M80-8400542	M80-840.pdf	
M80-6140542	M80-614_obsolete.pdf	09-Mar-18	M80-8400542	M80-840.pdf	
M80-6140545	M80-614_obsolete.pdf	09-Mar-18	M80-8400545	M80-840.pdf	
M80-6140601	M80-614_obsolete.pdf	09-Mar-18	M80-8400642	M80-840.pdf	
M80-6140642	M80-614_obsolete.pdf	09-Mar-18	M80-8400642	M80-840.pdf	
M80-6140645	M80-614_obsolete.pdf	09-Mar-18	M80-8400645	M80-840.pdf	
M80-6140701	M80-614_obsolete.pdf	09-Mar-18	M80-8400742	M80-840.pdf	
M80-6140742	M80-614_obsolete.pdf	09-Mar-18	M80-8400742	M80-840.pdf	
M80-6140745	M80-614_obsolete.pdf	09-Mar-18	M80-8400745	M80-840.pdf	
M80-6141701	M80-614_obsolete.pdf	09-Mar-18	M80-8401742	M80-840.pdf	
M80-6141742	M80-614_obsolete.pdf	09-Mar-18	M80-8401742	M80-840.pdf	
M80-6141745	M80-614_obsolete.pdf	09-Mar-18	M80-8401745	M80-840.pdf	
M80-6142201	M80-614_obsolete.pdf	09-Mar-18	M80-8402242	M80-840.pdf	
M80-6142242	M80-614_obsolete.pdf	09-Mar-18	M80-8402242	M80-840.pdf	
M80-6142245	M80-614_obsolete.pdf	09-Mar-18	M80-8402245	M80-840.pdf	
M80-6150401	M80-615_obsolete.pdf	09-Mar-18	M80-8500442	M80-850.pdf	
M80-6150442	M80-615_obsolete.pdf	09-Mar-18	M80-8500442	M80-850.pdf	
M80-6150445	M80-615_obsolete.pdf	09-Mar-18	M80-8500445	M80-850.pdf	
M80-6150601	M80-615_obsolete.pdf	09-Mar-18	M80-8500642	M80-850.pdf	
M80-6150642	M80-615_obsolete.pdf	09-Mar-18	M80-8500642	M80-850.pdf	
M80-6150645	M80-615_obsolete.pdf	09-Mar-18	M80-8500645	M80-850.pdf	
M80-6150801	M80-615_obsolete.pdf	09-Mar-18	M80-8500842	M80-850.pdf	
M80-6150842	M80-615_obsolete.pdf	09-Mar-18	M80-8500842	M80-850.pdf	
M80-6150845	M80-615_obsolete.pdf	09-Mar-18	M80-8500845	M80-850.pdf	

Obsolete Product Notification from Harwin

Part number being made obsolete	Drawing for obsolete product	Last Time Buy?	Alternative product	Drawing for alternative product	Notes
M80B1011798	Contact technical@harwin.com	09-Mar-18	M80-1011798S	M80-101S.pdf	
M80C107393C	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M80C107397C	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M80C107503C	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M80C107611C	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M80C107615C	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M80C107795C	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M80C107818C	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M80C107830C	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M80C107831C	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M80C107950C	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M80C107964C-PRE	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M80C107965C-PRE	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M80C107970C-PRE	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M80C107971C-PRE	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M80C107997C-PRE	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M80C107998C-PRE	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M80C108026C	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M80C108053C	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M80C108317C	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M80C108317C	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M80C108358CFI	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M80C108436C	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M80C108605C	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M80C108606C	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M80C108704C-14	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M80C108744C	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M80C108746C	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M80C108781C-3442	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M80C108790C-18	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M80C108791C-18	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M80C108821C	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M80C108846C-26	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M80C108847C-26	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M80C108896C-26	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M80C108901C	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M80C108958C	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M80C108959C	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M80C109060C	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M80C109061C	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M80C109062C	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M80C109063C	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M80C109246C	Contact technical@harwin.com	Immediate	Contact technical@harwin.com		
M80C150174C-12	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M80C150222C	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M80F1031898S	Contact technical@harwin.com	09-Mar-18	M80-1031898S	M80-103S.pdf	
M80GM1010698	Contact technical@harwin.com	09-Mar-18	M80-1010698S	M80-101S.pdf	
M80GM1030498	Contact technical@harwin.com	09-Mar-18	M80-1030498S	M80-103S.pdf	
M80GM1030698	Contact technical@harwin.com	09-Mar-18	M80-1030698S	M80-103S.pdf	
M80GM1030898	Contact technical@harwin.com	09-Mar-18	M80-1030898S	M80-103S.pdf	
M80GM1031098	Contact technical@harwin.com	09-Mar-18	M80-1031098S	M80-103S.pdf	
M80GM1032698	Contact technical@harwin.com	09-Mar-18	M80-1032698S	M80-103S.pdf	
M80GM1033498	Contact technical@harwin.com	09-Mar-18	M80-1033498S	M80-103S.pdf	
M83-301	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M83-302	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M83C108634C	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M83C108634CL	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M83C108637C	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M83C108637CL	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M83C108639C	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M83C108639CL	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M83C108640C	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M83C108640CL	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M83C108641C	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M83C108641CL	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M83C108642C	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M83C108642CL	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M83C108643C	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M83C108643CL	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M83C108644C	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M83C108644CL	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M83C108645C	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M83C108645CL	Contact technical@harwin.com	09-Mar-18	Contact technical@harwin.com		
M83-LFC1F2N08-0400-325	M83-LFC1F2N08-0400-325 obsolete.pdf	09-Mar-18	Contact technical@harwin.com		
M83-LFC1FBN19-0101-325	M83-LFC1FBN19-0101-325 obsolete.pdf	09-Mar-18	M83-LFC1F2N19-0101-325	M83-LFC1F2N19-0101-325.pdf	
M83-LFT1F2N19-0101-321	M83-LFT1F2N19-0101-321 obsolete.pdf	09-Mar-18	Contact technical@harwin.com		
M83-LFT1F4N13-0302-301	M83-LFT1F4N13-0302-301 obsolete.pdf	09-Mar-18	Contact technical@harwin.com		