



Harwin plc
Fitzherbert Road
Farlington, Portsmouth
Hampshire PO6 1RT
United Kingdom

Reception: +44 (0)23 9231 4545
Sales Desk: +44 (0)23 9237 0451

Friday 23rd February, 2018

Dear Customer,

Re: Obsolescence notification for Harwin product.

Please be advised that the following ranges are now obsolete. These items have a **Last Time Buy date of 9th March 2018:**

- B5743-2xx-M-T-A
- B5743-2xx-M-T-T
- B5743-1xx-M-T-V
- B5741-1xx-F-N-0
- B5741-1xx-F-N-2
- B5741-2xx-F-N-0
- B5741-2xx-F-N-2

These items have a **Last Time Buy date of 18th May 2018:**

- D01-992xx01, D01-993xx01
- D3080-01, D3081-01, D3082-01, D3083-01, D3083-05
- S1621-06, S1621-06R, S1711-06, S1711-46, S1711-06R, S1721-06R, S1731-06R, S1751-06, S1751-06R, S2711-06E
- D39xx-42 series
- W109055C, W109056C, W2131-00, W2530-00, W2831-00
- M80-306, M80-316, M80-330 and any Datamate Mix-Tek connectors using these special contacts
- M80-4C10642F2-00-000-04-32D
- M80-055 series

These items have **no Last Time Buy date**, and are obsolete with immediate effect:

- S1411-06R, S1731-06, S1731-46, S2711-06, S2711-46
- ZK3610-00
- M80-747 series
- M105841C
- M80-5T100M1-40-331, M80-5T100M1-50-331, M80-5T100M1-60-331, M80-4C100F2-40-327, M80-4C100F2-60-327

Please see the following spreadsheet for a detailed list of affected items:

https://cdn.harwin.com/pdfs/Obsolescence_notification_spreadsheet_Harwin_Products_23_February_2018.xlsx

HARWIN

Unfortunately, we are no longer able to support these product lines. Alternative items are available in most cases; please see the attached spreadsheet for the alternative part numbers.

If you have any further questions regarding this letter, please do not hesitate to contact us.

Yours faithfully,

The Product Management Team
technical@harwin.com

Obsolete Product Notification from Harwin

Part number being made obsolete	Drawing for obsolete product	Last Time buy date	Alternative product	Drawing for alternative product
D01-9922001	D01-992.pdf	18th May 2018	D01-9922046	D01-992.pdf
D01-9923201	D01-992.pdf	18th May 2018	D01-9923246	D01-992.pdf
D01-9933201	D01-993.pdf	18th May 2018	D01-9933246	D01-993.pdf
D3080-01	D3080.pdf	18th May 2018	D3080-46	D3080.pdf
D3081-01	D3081.pdf	18th May 2018	D3081-46	D3081.pdf
D3082-01	D3082.pdf	18th May 2018	D3082-46	D3082.pdf
D3083-01	D3083.pdf	18th May 2018	D3083-46	D3083.pdf
D3083-05	D3083.pdf	18th May 2018	D3083-46	D3083.pdf
S1411-06R	S1411-XXR.pdf	Immediate	S1411-46R	S1411-XXR.pdf
S1621-06	S1621.pdf	18th May 2018	S1621-46R	S1621R.pdf
S1621-06R	S1621R.pdf	18th May 2018	S1621-46R	S1621R.pdf
S1711-06	S1711_obsolete.pdf	18th May 2018	S1711-46R	S1711-XXR.pdf
S1711-46	S1711_obsolete.pdf	18th May 2018	S1711-46R	S1711-XXR.pdf
S1711-06R	S1711-XXR.pdf	18th May 2018	S1711-46R	S1711-XXR.pdf
S1721-06R	S1721-XXR.pdf	18th May 2018	S1721-46R	S1721-XXR.pdf
S1731-06	S1731_obsolete.pdf	Immediate	S1731-46R	S1731R.pdf
S1731-46	S1731_obsolete.pdf	Immediate	S1731-46R	S1731R.pdf
S1731-06R	S1731R.pdf	18th May 2018	S1731-46R	S1731R.pdf
S1751-06	S1751.pdf	18th May 2018	S1751-46R	S1751R.pdf
S1751-06R	S1751R.pdf	18th May 2018	S1751-46R	S1751R.pdf
S2711-06	S2711_obsolete.pdf	Immediate	S2711-46R	S2711-XXR.pdf
S2711-46	S2711_obsolete.pdf	Immediate	S2711-46R	S2711-XXR.pdf
S2711-06R	S2711-XXR.pdf	18th May 2018	S2711-46R	S2711-XXR.pdf
ZK3610-00	ZK3610_obsolete.pdf	Immediate	Not applicable	
B5743-204-M-T-A	M80-855_obsolete.pdf	9th March 2018	M80-7530445	M80-753.pdf
B5743-204-M-T-T	M80-855_obsolete.pdf	9th March 2018	M80-7530442	M80-753.pdf
B5743-206-M-T-A	M80-855_obsolete.pdf	9th March 2018	M80-7530645	M80-753.pdf
B5743-206-M-T-T	M80-855_obsolete.pdf	9th March 2018	M80-7530642	M80-753.pdf
B5743-208-M-T-A	M80-855_obsolete.pdf	9th March 2018	M80-7530845	M80-753.pdf
B5743-208-M-T-T	M80-855_obsolete.pdf	9th March 2018	M80-7530842	M80-753.pdf
B5743-210-M-T-A	M80-855_obsolete.pdf	9th March 2018	M80-7531045	M80-753.pdf
B5743-210-M-T-T	M80-855_obsolete.pdf	9th March 2018	M80-7531042	M80-753.pdf
B5743-212-M-T-A	M80-855_obsolete.pdf	9th March 2018	M80-7531245	M80-753.pdf
B5743-212-M-T-T	M80-855_obsolete.pdf	9th March 2018	M80-7531242	M80-753.pdf
B5743-214-M-T-A	M80-855_obsolete.pdf	9th March 2018	M80-7531445	M80-753.pdf
B5743-214-M-T-T	M80-855_obsolete.pdf	9th March 2018	M80-7531442	M80-753.pdf
B5743-216-M-T-A	M80-855_obsolete.pdf	9th March 2018	M80-7531645	M80-753.pdf
B5743-216-M-T-T	M80-855_obsolete.pdf	9th March 2018	M80-7531642	M80-753.pdf
B5743-218-M-T-A	M80-855_obsolete.pdf	9th March 2018	M80-7531845	M80-753.pdf
B5743-218-M-T-T	M80-855_obsolete.pdf	9th March 2018	M80-7531842	M80-753.pdf
B5743-220-M-T-A	M80-855_obsolete.pdf	9th March 2018	M80-7532045	M80-753.pdf
B5743-220-M-T-T	M80-855_obsolete.pdf	9th March 2018	M80-7532042	M80-753.pdf
B5743-226-M-T-A	M80-855_obsolete.pdf	9th March 2018	M80-7532645	M80-753.pdf
B5743-226-M-T-T	M80-855_obsolete.pdf	9th March 2018	M80-7532642	M80-753.pdf
B5743-234-M-T-A	M80-855_obsolete.pdf	9th March 2018	M80-7533445	M80-753.pdf
B5743-234-M-T-T	M80-855_obsolete.pdf	9th March 2018	M80-7533442	M80-753.pdf
B5743-244-M-T-A	M80-855_obsolete.pdf	9th March 2018	M80-7534445	M80-753.pdf
B5743-244-M-T-T	M80-855_obsolete.pdf	9th March 2018	M80-7534442	M80-753.pdf
B5743-102-M-T-V	M80-865_obsolete.pdf	9th March 2018	M80-7520242	M80-752.pdf
B5743-103-M-T-V	M80-865_obsolete.pdf	9th March 2018	M80-7520345	M80-752.pdf
B5743-104-M-T-V	M80-865_obsolete.pdf	9th March 2018	M80-7520445	M80-752.pdf
B5743-105-M-T-V	M80-865_obsolete.pdf	9th March 2018	M80-7520542	M80-752.pdf
B5743-106-M-T-V	M80-865_obsolete.pdf	9th March 2018	M80-7520642	M80-752.pdf
B5743-107-M-T-V	M80-865_obsolete.pdf	9th March 2018	M80-7520742	M80-752.pdf
B5743-117-M-T-V	M80-865_obsolete.pdf	9th March 2018	M80-7521742	M80-752.pdf
B5743-122-M-T-V	M80-865_obsolete.pdf	9th March 2018	M80-7522242	M80-752.pdf
B5741-204-F-N-0	M80-891_obsolete.pdf	9th March 2018	M80-8500442	M80-850.pdf
B5741-204-F-N-2	M80-891_obsolete.pdf	9th March 2018	M80-8500445	M80-850.pdf
B5741-206-F-N-0	M80-891_obsolete.pdf	9th March 2018	M80-8500642	M80-850.pdf
B5741-206-F-N-2	M80-891_obsolete.pdf	9th March 2018	M80-8500645	M80-850.pdf
B5741-208-F-N-0	M80-891_obsolete.pdf	9th March 2018	M80-8500842	M80-850.pdf
B5741-208-F-N-2	M80-891_obsolete.pdf	9th March 2018	M80-8500845	M80-850.pdf
B5741-210-F-N-0	M80-891_obsolete.pdf	9th March 2018	M80-8501042	M80-850.pdf
B5741-210-F-N-2	M80-891_obsolete.pdf	9th March 2018	M80-8501045	M80-850.pdf
B5741-212-F-N-0	M80-891_obsolete.pdf	9th March 2018	M80-8501242	M80-850.pdf
B5741-212-F-N-2	M80-891_obsolete.pdf	9th March 2018	M80-8501245	M80-850.pdf
B5741-214-F-N-0	M80-891_obsolete.pdf	9th March 2018	M80-8501442	M80-850.pdf
B5741-214-F-N-2	M80-891_obsolete.pdf	9th March 2018	M80-8501445	M80-850.pdf
B5741-216-F-N-0	M80-891_obsolete.pdf	9th March 2018	M80-8501642	M80-850.pdf
B5741-216-F-N-2	M80-891_obsolete.pdf	9th March 2018	M80-8501645	M80-850.pdf
B5741-218-F-N-0	M80-891_obsolete.pdf	9th March 2018	M80-8501842	M80-850.pdf
B5741-218-F-N-2	M80-891_obsolete.pdf	9th March 2018	M80-8501845	M80-850.pdf
B5741-220-F-N-0	M80-891_obsolete.pdf	9th March 2018	M80-8502045	M80-850.pdf
B5741-220-F-N-2	M80-891_obsolete.pdf	9th March 2018	M80-8502045	M80-850.pdf
B5741-226-F-N-0	M80-891_obsolete.pdf	9th March 2018	M80-8502642	M80-850.pdf

Obsolete Product Notification from Harwin

Part number being made obsolete	Drawing for obsolete product	Last Time buy date	Alternative product	Drawing for alternative product
B5741-226-F-N-2	M80-891_obsolete.pdf	9th March 2018	M80-8502645	M80-850.pdf
B5741-234-F-N-0	M80-891_obsolete.pdf	9th March 2018	M80-8503442	M80-850.pdf
B5741-234-F-N-2	M80-891_obsolete.pdf	9th March 2018	M80-8503445	M80-850.pdf
B5741-244-F-N-0	M80-891_obsolete.pdf	9th March 2018	M80-8504442	M80-850.pdf
B5741-244-F-N-2	M80-891_obsolete.pdf	9th March 2018	M80-8504445	M80-850.pdf
B5741-102-F-N-0	M80-894_obsolete.pdf	9th March 2018	M80-8400242	M80-840.pdf
B5741-102-F-N-2	M80-894_obsolete.pdf	9th March 2018	M80-8400242	M80-840.pdf
B5741-103-F-N-0	M80-894_obsolete.pdf	9th March 2018	M80-8400342	M80-840.pdf
B5741-103-F-N-2	M80-894_obsolete.pdf	9th March 2018	M80-8400342	M80-840.pdf
B5741-104-F-N-0	M80-894_obsolete.pdf	9th March 2018	M80-8400442	M80-840.pdf
B5741-104-F-N-2	M80-894_obsolete.pdf	9th March 2018	M80-8400445	M80-840.pdf
B5741-105-F-N-0	M80-894_obsolete.pdf	9th March 2018	M80-8400542	M80-840.pdf
B5741-105-F-N-2	M80-894_obsolete.pdf	9th March 2018	M80-8400545	M80-840.pdf
B5741-106-F-N-0	M80-894_obsolete.pdf	9th March 2018	M80-8400642	M80-840.pdf
B5741-106-F-N-2	M80-894_obsolete.pdf	9th March 2018	M80-8400645	M80-840.pdf
B5741-107-F-N-0	M80-894_obsolete.pdf	9th March 2018	M80-8400742	M80-840.pdf
B5741-107-F-N-2	M80-894_obsolete.pdf	9th March 2018	M80-8400745	M80-840.pdf
B5741-117-F-N-0	M80-894_obsolete.pdf	9th March 2018	M80-8401742	M80-840.pdf
B5741-117-F-N-2	M80-894_obsolete.pdf	9th March 2018	M80-8401745	M80-840.pdf
B5741-122-F-N-0	M80-894_obsolete.pdf	9th March 2018	M80-8402242	M80-840.pdf
B5741-122-F-N-2	M80-894_obsolete.pdf	9th March 2018	M80-8402245	M80-840.pdf
M80-7470222	Contact technical@harwin.com	Immediate	M80-8520242	M80-852.pdf
M80-7470242	Contact technical@harwin.com	Immediate	M80-8520242	M80-852.pdf
M80-7470245	Contact technical@harwin.com	Immediate	M80-8520245	M80-852.pdf
M80-7470322	Contact technical@harwin.com	Immediate	M80-8520342	M80-852.pdf
M80-7470342	Contact technical@harwin.com	Immediate	M80-8520342	M80-852.pdf
M80-7470345	Contact technical@harwin.com	Immediate	M80-8520345	M80-852.pdf
M80-7470422	Contact technical@harwin.com	Immediate	M80-8520442	M80-852.pdf
M80-7470442	Contact technical@harwin.com	Immediate	M80-8520442	M80-852.pdf
M80-7470445	Contact technical@harwin.com	Immediate	M80-8520445	M80-852.pdf
M80-7470522	Contact technical@harwin.com	Immediate	M80-8520542	M80-852.pdf
M80-7470542	Contact technical@harwin.com	Immediate	M80-8520542	M80-852.pdf
M80-7470545	Contact technical@harwin.com	Immediate	M80-8520545	M80-852.pdf
M80-7470622	Contact technical@harwin.com	Immediate	M80-8520642	M80-852.pdf
M80-7470642	Contact technical@harwin.com	Immediate	M80-8520642	M80-852.pdf
M80-7470645	Contact technical@harwin.com	Immediate	M80-8520645	M80-852.pdf
M80-7470722	Contact technical@harwin.com	Immediate	M80-8520742	M80-852.pdf
M80-7470742	Contact technical@harwin.com	Immediate	M80-8520742	M80-852.pdf
M80-7470745	Contact technical@harwin.com	Immediate	M80-8520745	M80-852.pdf
M80-7471722	Contact technical@harwin.com	Immediate	M80-8521742	M80-852.pdf
M80-7471742	Contact technical@harwin.com	Immediate	M80-8521742	M80-852.pdf
M80-7471745	Contact technical@harwin.com	Immediate	M80-8521745	M80-852.pdf
M80-7472222	Contact technical@harwin.com	Immediate	M80-8522242	M80-852.pdf
M80-7472242	Contact technical@harwin.com	Immediate	M80-8522242	M80-852.pdf
M80-7472245	Contact technical@harwin.com	Immediate	M80-8522245	M80-852.pdf
D3906-42	D39XX_obsolete.pdf	18th May 2018	D2806-42	D2XXX.pdf
D3908-42	D39XX_obsolete.pdf	18th May 2018	D2808-42	D2XXX.pdf
D3914-42	D39XX_obsolete.pdf	18th May 2018	D2814-42	D2XXX.pdf
D3916-42	D39XX_obsolete.pdf	18th May 2018	D2816-42	D2XXX.pdf
D3918-42	D39XX_obsolete.pdf	18th May 2018	D2818-42	D2XXX.pdf
D3920-42	D39XX_obsolete.pdf	18th May 2018	D2820-42	D2XXX.pdf
D3924-42	D39XX_obsolete.pdf	18th May 2018	D2924-42	D2XXX.pdf
W109055C	Contact technical@harwin.com	18th May 2018	W2331-00	W2331.pdf
W109056C	Contact technical@harwin.com	18th May 2018	W2332-00	W2332.pdf
W2131-00	W2131_obsolete.pdf	18th May 2018	W2331-00	W2331.pdf
W2530-00	W2530_obsolete.pdf	18th May 2018	W2231-00	W2231.pdf
W2831-00	W2831_obsolete.pdf	18th May 2018	W2231-00	W2231.pdf
M105841C	Contact technical@harwin.com	Immediate	Not applicable	
M80-5T100M1-40-331	M80-5T100M1-40-331_obsolete.pdf	Immediate	M80-5000000M1-04-331-00-000	M80-5000000M1-XX-XXX-00-000.pdf
M80-5T100M1-50-331	M80-5T100M1-50-331_obsolete.pdf	Immediate	M80-5000000M1-05-331-00-000	M80-5000000M1-XX-XXX-00-000.pdf
M80-5T100M1-60-331	M80-5T100M1-60-331_obsolete.pdf	Immediate	M80-5000000M1-06-331-00-000	M80-5000000M1-XX-XXX-00-000.pdf
M80-4C100F2-40-327	M80-4C100F2-40-327_obsolete.pdf	Immediate	M80-4000000F2-04-327-00-000	M80-4000000F2-XX-XXX-00-000.pdf
M80-4C100F2-60-327	M80-4C100F2-60-327_obsolete.pdf	Immediate	M80-4000000F2-06-327-00-000	M80-4000000F2-XX-XXX-00-000.pdf
M80-306	M80-305-307.pdf	18th May 2018	M80-305	M80-305-307.pdf
M80-316	M80-315-317.pdf	18th May 2018	M80-315	M80-315-317.pdf
M80-330	M80-330_obsolete.pdf	18th May 2018	M80-331	M80-331-332.pdf
M80-4C10642F2-00-000-04-32D	M80-4C10642F2-00-000-04-32D_obsolete.pdf	18th May 2018	Contact technical@harwin.com	
M80-5S10605MG-02-330-02-330	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M80-400000000-02-306-00-000	M80-400000000-XX-XXX-00-000.pdf	18th May 2018	M80-400000000-02-305-00-000	M80-400000000-XX-XXX-00-000.pdf
M80-400000000-03-306-00-000	M80-400000000-XX-XXX-00-000.pdf	18th May 2018	M80-400000000-03-305-00-000	M80-400000000-XX-XXX-00-000.pdf
M80-400000000-04-306-00-000	M80-400000000-XX-XXX-00-000.pdf	18th May 2018	M80-400000000-04-305-00-000	M80-400000000-XX-XXX-00-000.pdf
M80-400000000-05-306-00-000	M80-400000000-XX-XXX-00-000.pdf	18th May 2018	M80-400000000-05-305-00-000	M80-400000000-XX-XXX-00-000.pdf
M80-400000000-06-306-00-000	M80-400000000-XX-XXX-00-000.pdf	18th May 2018	M80-400000000-06-305-00-000	M80-400000000-XX-XXX-00-000.pdf
M80-400000000-07-306-00-000	M80-400000000-XX-XXX-00-000.pdf	18th May 2018	M80-400000000-07-305-00-000	M80-400000000-XX-XXX-00-000.pdf
M80-400000000-08-306-00-000	M80-400000000-XX-XXX-00-000.pdf	18th May 2018	M80-400000000-08-305-00-000	M80-400000000-XX-XXX-00-000.pdf

