



Harwin plc
Fitzherbert Road
Farlington, Portsmouth
Hampshire PO6 1RT
United Kingdom

Reception: +44 (0)23 9231 4545
Sales Desk: +44 (0)23 9237 0451

Monday 5th March, 2018

Dear Customer,

Re: Obsolescence notification for Harwin product.

Please be advised that the following ranges are now obsolete. These items have a **Last Time Buy date of 7th September 2018** (approximately 6 months):

- M80-080 – Datamate Friction Latch
- B5743-1xx-M-T-R , B5743-2xx-M-T-R
- M80-667 series
- M80-748 series
- M80-763 series
- M80-781 series
- M80-804 series
- M80-805 series
- M80-814 series
- M80-815 series
- M80-816 series
- M80-817 series
- M80-827, M80-827P series
- M80-835 series
- M80-839 series
- M80-846 series
- M80-863 series
- M80-881 series
- M80-883 series
- Customer Special items with friction latches

Please see the following spreadsheet for a detailed list of affected items:

https://cdn.harwin.com/pdfs/Obsolescence_notification_spreadsheet_Harwin_Friction_Latch_Datamate_05_March_2018.xlsx

These items cover all Datamate L-Tek products that use the Friction Latch. Unfortunately, we are no longer able to support these product lines. In most cases, we recommend substitution for the unlatched equivalent L-Tek, although there is also the locking latch version available. Please see the attached spreadsheet for the recommended alternative part numbers.

If you have any further questions regarding this letter, please do not hesitate to contact us.

Yours faithfully,

The Product Management Team
technical@harwin.com

Obsolete Product Notification from Harwin

Part number being made obsolete	Drawing for obsolete product	Last Time buy date	Alternative product	Drawing for alternative product
M80-080	M80-080_obsolete.pdf	7th September 2018	M80-001	M80-001.pdf
B5743-102-M-T-R	M80-881_obsolete.pdf	7th September 2018	M80-8520242	M80-852.pdf
B5743-103-M-T-R	M80-881_obsolete.pdf	7th September 2018	M80-8520342	M80-852.pdf
B5743-104-M-T-R	M80-881_obsolete.pdf	7th September 2018	M80-8520442	M80-852.pdf
B5743-105-M-T-R	M80-881_obsolete.pdf	7th September 2018	M80-8520542	M80-852.pdf
B5743-106-M-T-R	M80-881_obsolete.pdf	7th September 2018	M80-8520642	M80-852.pdf
B5743-107-M-T-R	M80-881_obsolete.pdf	7th September 2018	M80-8520742	M80-852.pdf
B5743-117-M-T-R	M80-881_obsolete.pdf	7th September 2018	M80-8521742	M80-852.pdf
B5743-204-M-T-R	M80-815_obsolete.pdf	7th September 2018	M80-8540442	M80-854.pdf
B5743-206-M-T-R	M80-815_obsolete.pdf	7th September 2018	M80-8540642	M80-854.pdf
B5743-208-M-T-R	M80-815_obsolete.pdf	7th September 2018	M80-8540842	M80-854.pdf
B5743-210-M-T-R	M80-815_obsolete.pdf	7th September 2018	M80-8541042	M80-854.pdf
B5743-212-M-T-R	M80-815_obsolete.pdf	7th September 2018	M80-8541242	M80-854.pdf
B5743-214-M-T-R	M80-815_obsolete.pdf	7th September 2018	M80-8541442	M80-854.pdf
B5743-216-M-T-R	M80-815_obsolete.pdf	7th September 2018	M80-8541642	M80-854.pdf
B5743-218-M-T-R	M80-815_obsolete.pdf	7th September 2018	M80-8541842	M80-854.pdf
B5743-220-M-T-R	M80-815_obsolete.pdf	7th September 2018	M80-8542042	M80-854.pdf
B5743-226-M-T-R	M80-815_obsolete.pdf	7th September 2018	M80-8542642	M80-854.pdf
B5743-234-M-T-R	M80-815_obsolete.pdf	7th September 2018	M80-8543442	M80-854.pdf
B5743-244-M-T-R	M80-815_obsolete.pdf	7th September 2018	M80-8544442	M80-854.pdf
M80-6670442	M80-667_obsolete.pdf	7th September 2018	M80-6650442	M80-665.pdf
M80-6670445	M80-667_obsolete.pdf	7th September 2018	M80-6650445	M80-665.pdf
M80-6670642	M80-667_obsolete.pdf	7th September 2018	M80-6650642	M80-665.pdf
M80-6670645	M80-667_obsolete.pdf	7th September 2018	M80-6650645	M80-665.pdf
M80-6670842	M80-667_obsolete.pdf	7th September 2018	M80-6650842	M80-665.pdf
M80-6670845	M80-667_obsolete.pdf	7th September 2018	M80-6650845	M80-665.pdf
M80-6671042	M80-667_obsolete.pdf	7th September 2018	M80-6651042	M80-665.pdf
M80-6671045	M80-667_obsolete.pdf	7th September 2018	M80-6651045	M80-665.pdf
M80-6671242	M80-667_obsolete.pdf	7th September 2018	M80-6651242	M80-665.pdf
M80-6671245	M80-667_obsolete.pdf	7th September 2018	M80-6651245	M80-665.pdf
M80-6671422	M80-667_obsolete.pdf	7th September 2018	M80-6651442	M80-665.pdf
M80-6671442	M80-667_obsolete.pdf	7th September 2018	M80-6651442	M80-665.pdf
M80-6671445	M80-667_obsolete.pdf	7th September 2018	M80-6651445	M80-665.pdf
M80-6671622	M80-667_obsolete.pdf	7th September 2018	M80-6651642	M80-665.pdf
M80-6671642	M80-667_obsolete.pdf	7th September 2018	M80-6651642	M80-665.pdf
M80-6671645	M80-667_obsolete.pdf	7th September 2018	M80-6651645	M80-665.pdf
M80-6671822	M80-667_obsolete.pdf	7th September 2018	M80-6651842	M80-665.pdf
M80-6671842	M80-667_obsolete.pdf	7th September 2018	M80-6651842	M80-665.pdf
M80-6671845	M80-667_obsolete.pdf	7th September 2018	M80-6651845	M80-665.pdf
M80-6672022	M80-667_obsolete.pdf	7th September 2018	M80-6652042	M80-665.pdf
M80-6672042	M80-667_obsolete.pdf	7th September 2018	M80-6652042	M80-665.pdf
M80-6672045	M80-667_obsolete.pdf	7th September 2018	M80-6652045	M80-665.pdf
M80-6672622	M80-667_obsolete.pdf	7th September 2018	M80-6652642	M80-665.pdf
M80-6672642	M80-667_obsolete.pdf	7th September 2018	M80-6652642	M80-665.pdf
M80-6672645	M80-667_obsolete.pdf	7th September 2018	M80-6652645	M80-665.pdf
M80-6673422	M80-667_obsolete.pdf	7th September 2018	M80-6653442	M80-665.pdf
M80-6673442	M80-667_obsolete.pdf	7th September 2018	M80-6653442	M80-665.pdf
M80-6673445	M80-667_obsolete.pdf	7th September 2018	M80-6653445	M80-665.pdf
M80-7480222	Contact technical@harwin.com	7th September 2018	M80-8520242	M80-852.pdf
M80-7480242	Contact technical@harwin.com	7th September 2018	M80-8520242	M80-852.pdf
M80-7480245	Contact technical@harwin.com	7th September 2018	M80-8520245	M80-852.pdf
M80-7480322	Contact technical@harwin.com	7th September 2018	M80-8520342	M80-852.pdf
M80-7480342	Contact technical@harwin.com	7th September 2018	M80-8520342	M80-852.pdf
M80-7480345	Contact technical@harwin.com	7th September 2018	M80-8520345	M80-852.pdf
M80-7480422	Contact technical@harwin.com	7th September 2018	M80-8520442	M80-852.pdf
M80-7480442	Contact technical@harwin.com	7th September 2018	M80-8520442	M80-852.pdf
M80-7480445	Contact technical@harwin.com	7th September 2018	M80-8520445	M80-852.pdf

Obsolete Product Notification from Harwin

Part number being made obsolete	Drawing for obsolete product	Last Time buy date	Alternative product	Drawing for alternative product
M80-7480522	Contact technical@harwin.com	7th September 2018	M80-8520542	M80-852.pdf
M80-7480542	Contact technical@harwin.com	7th September 2018	M80-8520542	M80-852.pdf
M80-7480545	Contact technical@harwin.com	7th September 2018	M80-8520545	M80-852.pdf
M80-7480622	Contact technical@harwin.com	7th September 2018	M80-8520642	M80-852.pdf
M80-7480642	Contact technical@harwin.com	7th September 2018	M80-8520642	M80-852.pdf
M80-7480645	Contact technical@harwin.com	7th September 2018	M80-8520645	M80-852.pdf
M80-7480722	Contact technical@harwin.com	7th September 2018	M80-8520742	M80-852.pdf
M80-7480742	Contact technical@harwin.com	7th September 2018	M80-8520742	M80-852.pdf
M80-7480745	Contact technical@harwin.com	7th September 2018	M80-8520745	M80-852.pdf
M80-7481722	Contact technical@harwin.com	7th September 2018	M80-8521742	M80-852.pdf
M80-7481742	Contact technical@harwin.com	7th September 2018	M80-8521742	M80-852.pdf
M80-7481745	Contact technical@harwin.com	7th September 2018	M80-8521745	M80-852.pdf
M80-7482222	Contact technical@harwin.com	7th September 2018	M80-8542422	M80-852.pdf
M80-7482242	Contact technical@harwin.com	7th September 2018	M80-8542242	M80-852.pdf
M80-7482245	Contact technical@harwin.com	7th September 2018	M80-8542245	M80-852.pdf
M80-7630422	M80-763_obsolete.pdf	7th September 2018	M80-7540442	M80-754.pdf
M80-7630442	M80-763_obsolete.pdf	7th September 2018	M80-7540442	M80-754.pdf
M80-7630445	M80-763_obsolete.pdf	7th September 2018	M80-7540445	M80-754.pdf
M80-7630622	M80-763_obsolete.pdf	7th September 2018	M80-7540645	M80-754.pdf
M80-7630642	M80-763_obsolete.pdf	7th September 2018	M80-7540645	M80-754.pdf
M80-7630645	M80-763_obsolete.pdf	7th September 2018	M80-7540645	M80-754.pdf
M80-7630822	M80-763_obsolete.pdf	7th September 2018	M80-7540842	M80-754.pdf
M80-7630842	M80-763_obsolete.pdf	7th September 2018	M80-7540842	M80-754.pdf
M80-7630845	M80-763_obsolete.pdf	7th September 2018	M80-7540845	M80-754.pdf
M80-7631022	M80-763_obsolete.pdf	7th September 2018	M80-7541042	M80-754.pdf
M80-7631042	M80-763_obsolete.pdf	7th September 2018	M80-7541042	M80-754.pdf
M80-7631045	M80-763_obsolete.pdf	7th September 2018	M80-7541045	M80-754.pdf
M80-7631222	M80-763_obsolete.pdf	7th September 2018	M80-7541242	M80-754.pdf
M80-7631242	M80-763_obsolete.pdf	7th September 2018	M80-7541242	M80-754.pdf
M80-7631245	M80-763_obsolete.pdf	7th September 2018	M80-7541245	M80-754.pdf
M80-7631422	M80-763_obsolete.pdf	7th September 2018	M80-7541445	M80-754.pdf
M80-7631442	M80-763_obsolete.pdf	7th September 2018	M80-7541445	M80-754.pdf
M80-7631445	M80-763_obsolete.pdf	7th September 2018	M80-7541445	M80-754.pdf
M80-7631622	M80-763_obsolete.pdf	7th September 2018	M80-7541642	M80-754.pdf
M80-7631642	M80-763_obsolete.pdf	7th September 2018	M80-7541642	M80-754.pdf
M80-7631645	M80-763_obsolete.pdf	7th September 2018	M80-7541645	M80-754.pdf
M80-7631822	M80-763_obsolete.pdf	7th September 2018	M80-7541842	M80-754.pdf
M80-7631842	M80-763_obsolete.pdf	7th September 2018	M80-7541842	M80-754.pdf
M80-7631845	M80-763_obsolete.pdf	7th September 2018	M80-7541845	M80-754.pdf
M80-7632022	M80-763_obsolete.pdf	7th September 2018	M80-7542042	M80-754.pdf
M80-7632042	M80-763_obsolete.pdf	7th September 2018	M80-7542042	M80-754.pdf
M80-7632045	M80-763_obsolete.pdf	7th September 2018	M80-7542045	M80-754.pdf
M80-7632622	M80-763_obsolete.pdf	7th September 2018	M80-7542642	M80-754.pdf
M80-7632642	M80-763_obsolete.pdf	7th September 2018	M80-7542642	M80-754.pdf
M80-7632645	M80-763_obsolete.pdf	7th September 2018	M80-7542645	M80-754.pdf
M80-7633422	M80-763_obsolete.pdf	7th September 2018	M80-7543442	M80-754.pdf
M80-7633442	M80-763_obsolete.pdf	7th September 2018	M80-7543442	M80-754.pdf
M80-7633445	M80-763_obsolete.pdf	7th September 2018	M80-7543445	M80-754.pdf
M80-7634422	M80-763_obsolete.pdf	7th September 2018	M80-7544442	M80-754.pdf
M80-7634442	M80-763_obsolete.pdf	7th September 2018	M80-7544442	M80-754.pdf
M80-7634445	M80-763_obsolete.pdf	7th September 2018	M80-7544445	M80-754.pdf
M80-7810222	M80-781_obsolete.pdf	7th September 2018	M80-7520242	M80-752.pdf
M80-7810242	M80-781_obsolete.pdf	7th September 2018	M80-7520242	M80-752.pdf
M80-7810245	M80-781_obsolete.pdf	7th September 2018	M80-7520245	M80-752.pdf
M80-7810322	M80-781_obsolete.pdf	7th September 2018	M80-7520345	M80-752.pdf
M80-7810342	M80-781_obsolete.pdf	7th September 2018	M80-7520345	M80-752.pdf
M80-7810345	M80-781_obsolete.pdf	7th September 2018	M80-7520345	M80-752.pdf

Obsolete Product Notification from Harwin

Part number being made obsolete	Drawing for obsolete product	Last Time buy date	Alternative product	Drawing for alternative product
M80-7810422	M80-781_obsolete.pdf	7th September 2018	M80-7520445	M80-752.pdf
M80-7810442	M80-781_obsolete.pdf	7th September 2018	M80-7520445	M80-752.pdf
M80-7810445	M80-781_obsolete.pdf	7th September 2018	M80-7520445	M80-752.pdf
M80-7810522	M80-781_obsolete.pdf	7th September 2018	M80-7520542	M80-752.pdf
M80-7810542	M80-781_obsolete.pdf	7th September 2018	M80-7520542	M80-752.pdf
M80-7810545	M80-781_obsolete.pdf	7th September 2018	M80-7520545	M80-752.pdf
M80-7810622	M80-781_obsolete.pdf	7th September 2018	M80-7520642	M80-752.pdf
M80-7810642	M80-781_obsolete.pdf	7th September 2018	M80-7520642	M80-752.pdf
M80-7810645	M80-781_obsolete.pdf	7th September 2018	M80-7520645	M80-752.pdf
M80-7810722	M80-781_obsolete.pdf	7th September 2018	M80-7520742	M80-752.pdf
M80-7810742	M80-781_obsolete.pdf	7th September 2018	M80-7520742	M80-752.pdf
M80-7810745	M80-781_obsolete.pdf	7th September 2018	M80-7520745	M80-752.pdf
M80-7811722	M80-781_obsolete.pdf	7th September 2018	M80-7521742	M80-752.pdf
M80-7811742	M80-781_obsolete.pdf	7th September 2018	M80-7521742	M80-752.pdf
M80-7811745	M80-781_obsolete.pdf	7th September 2018	M80-7521745	M80-752.pdf
M80-7812222	M80-781_obsolete.pdf	7th September 2018	M80-7522242	M80-752.pdf
M80-7812242	M80-781_obsolete.pdf	7th September 2018	M80-7522242	M80-752.pdf
M80-7812245	M80-781_obsolete.pdf	7th September 2018	M80-7522245	M80-752.pdf
M80-8040205	M80-804_obsolete.pdf	7th September 2018	M80-8430245	M80-843.pdf
M80-8040222	M80-804_obsolete.pdf	7th September 2018	M80-8430242	M80-843.pdf
M80-8040305	M80-804_obsolete.pdf	7th September 2018	M80-8430345	M80-843.pdf
M80-8040322	M80-804_obsolete.pdf	7th September 2018	M80-8430342	M80-843.pdf
M80-8040405	M80-804_obsolete.pdf	7th September 2018	M80-8430445	M80-843.pdf
M80-8040422	M80-804_obsolete.pdf	7th September 2018	M80-8430442	M80-843.pdf
M80-8040505	M80-804_obsolete.pdf	7th September 2018	M80-8430545	M80-843.pdf
M80-8040522	M80-804_obsolete.pdf	7th September 2018	M80-8430542	M80-843.pdf
M80-8040605	M80-804_obsolete.pdf	7th September 2018	M80-8430645	M80-843.pdf
M80-8040622	M80-804_obsolete.pdf	7th September 2018	M80-8430642	M80-843.pdf
M80-8040705	M80-804_obsolete.pdf	7th September 2018	M80-8430745	M80-843.pdf
M80-8040722	M80-804_obsolete.pdf	7th September 2018	M80-8430742	M80-843.pdf
M80-8041705	M80-804_obsolete.pdf	7th September 2018	M80-8431745	M80-843.pdf
M80-8041722	M80-804_obsolete.pdf	7th September 2018	M80-8431742	M80-843.pdf
M80-8042205	M80-804_obsolete.pdf	7th September 2018	M80-8432245	M80-843.pdf
M80-8042222	M80-804_obsolete.pdf	7th September 2018	M80-8432242	M80-843.pdf
M80-8050205	M80-805_obsolete.pdf	7th September 2018	M80-8520245	M80-852.pdf
M80-8050222	M80-805_obsolete.pdf	7th September 2018	M80-8520242	M80-852.pdf
M80-8050305	M80-805_obsolete.pdf	7th September 2018	M80-8520345	M80-852.pdf
M80-8050322	M80-805_obsolete.pdf	7th September 2018	M80-8520342	M80-852.pdf
M80-8050405	M80-805_obsolete.pdf	7th September 2018	M80-8520445	M80-852.pdf
M80-8050422	M80-805_obsolete.pdf	7th September 2018	M80-8520442	M80-852.pdf
M80-8050505	M80-805_obsolete.pdf	7th September 2018	M80-8520545	M80-852.pdf
M80-8050522	M80-805_obsolete.pdf	7th September 2018	M80-8520542	M80-852.pdf
M80-8050605	M80-805_obsolete.pdf	7th September 2018	M80-8520645	M80-852.pdf
M80-8050622	M80-805_obsolete.pdf	7th September 2018	M80-8520642	M80-852.pdf
M80-8050705	M80-805_obsolete.pdf	7th September 2018	M80-8520745	M80-852.pdf
M80-8050722	M80-805_obsolete.pdf	7th September 2018	M80-8520742	M80-852.pdf
M80-8051705	M80-805_obsolete.pdf	7th September 2018	M80-8521745	M80-852.pdf
M80-8051722	M80-805_obsolete.pdf	7th September 2018	M80-8521742	M80-852.pdf
M80-8052205	M80-805_obsolete.pdf	7th September 2018	M80-8522245	M80-852.pdf
M80-8052222	M80-805_obsolete.pdf	7th September 2018	M80-8522242	M80-852.pdf
M80-8140405	M80-814_obsolete.pdf	7th September 2018	M80-8410445	M80-841.pdf
M80-8140422	M80-814_obsolete.pdf	7th September 2018	M80-8410442	M80-841.pdf
M80-8140605	M80-814_obsolete.pdf	7th September 2018	M80-8410645	M80-841.pdf
M80-8140622	M80-814_obsolete.pdf	7th September 2018	M80-8410642	M80-841.pdf
M80-8140805	M80-814_obsolete.pdf	7th September 2018	M80-8410845	M80-841.pdf
M80-8140822	M80-814_obsolete.pdf	7th September 2018	M80-8410842	M80-841.pdf
M80-8141005	M80-814_obsolete.pdf	7th September 2018	M80-8411045	M80-841.pdf

Obsolete Product Notification from Harwin

Part number being made obsolete	Drawing for obsolete product	Last Time buy date	Alternative product	Drawing for alternative product
M80-8141022	M80-814_obsolete.pdf	7th September 2018	M80-8411042	M80-841.pdf
M80-8141205	M80-814_obsolete.pdf	7th September 2018	M80-8411245	M80-841.pdf
M80-8141222	M80-814_obsolete.pdf	7th September 2018	M80-8411242	M80-841.pdf
M80-8141405	M80-814_obsolete.pdf	7th September 2018	M80-8411445	M80-841.pdf
M80-8141422	M80-814_obsolete.pdf	7th September 2018	M80-8411442	M80-841.pdf
M80-8141605	M80-814_obsolete.pdf	7th September 2018	M80-8411645	M80-841.pdf
M80-8141622	M80-814_obsolete.pdf	7th September 2018	M80-8411642	M80-841.pdf
M80-8141805	M80-814_obsolete.pdf	7th September 2018	M80-8411845	M80-841.pdf
M80-8142005	M80-814_obsolete.pdf	7th September 2018	M80-8412045	M80-841.pdf
M80-8142022	M80-814_obsolete.pdf	7th September 2018	M80-8412042	M80-841.pdf
M80-8142605	M80-814_obsolete.pdf	7th September 2018	M80-8412645	M80-841.pdf
M80-8142622	M80-814_obsolete.pdf	7th September 2018	M80-8412642	M80-841.pdf
M80-8143405	M80-814_obsolete.pdf	7th September 2018	M80-8413445	M80-841.pdf
M80-8143422	M80-814_obsolete.pdf	7th September 2018	M80-8413442	M80-841.pdf
M80-8144405	M80-814_obsolete.pdf	7th September 2018	M80-8414445	M80-841.pdf
M80-8144422	M80-814_obsolete.pdf	7th September 2018	M80-8414442	M80-841.pdf
M80-8150405	M80-815_obsolete.pdf	7th September 2018	M80-8540445	M80-854.pdf
M80-8150422	M80-815_obsolete.pdf	7th September 2018	M80-8540442	M80-854.pdf
M80-8150605	M80-815_obsolete.pdf	7th September 2018	M80-8540645	M80-854.pdf
M80-8150622	M80-815_obsolete.pdf	7th September 2018	M80-8540642	M80-854.pdf
M80-8150805	M80-815_obsolete.pdf	7th September 2018	M80-8540845	M80-854.pdf
M80-8150822	M80-815_obsolete.pdf	7th September 2018	M80-8540842	M80-854.pdf
M80-8151005	M80-815_obsolete.pdf	7th September 2018	M80-8541045	M80-854.pdf
M80-8151022	M80-815_obsolete.pdf	7th September 2018	M80-8541042	M80-854.pdf
M80-8151205	M80-815_obsolete.pdf	7th September 2018	M80-8541245	M80-854.pdf
M80-8151222	M80-815_obsolete.pdf	7th September 2018	M80-8541242	M80-854.pdf
M80-8151405	M80-815_obsolete.pdf	7th September 2018	M80-8541445	M80-854.pdf
M80-8151422	M80-815_obsolete.pdf	7th September 2018	M80-8541442	M80-854.pdf
M80-8151605	M80-815_obsolete.pdf	7th September 2018	M80-8541645	M80-854.pdf
M80-8151622	M80-815_obsolete.pdf	7th September 2018	M80-8541642	M80-854.pdf
M80-8151805	M80-815_obsolete.pdf	7th September 2018	M80-8541845	M80-854.pdf
M80-8151822	M80-815_obsolete.pdf	7th September 2018	M80-8541842	M80-854.pdf
M80-8152005	M80-815_obsolete.pdf	7th September 2018	M80-8542045	M80-854.pdf
M80-8152022	M80-815_obsolete.pdf	7th September 2018	M80-8542042	M80-854.pdf
M80-8152605	M80-815_obsolete.pdf	7th September 2018	M80-8542645	M80-854.pdf
M80-8152622	M80-815_obsolete.pdf	7th September 2018	M80-8542642	M80-854.pdf
M80-8153405	M80-815_obsolete.pdf	7th September 2018	M80-8543445	M80-854.pdf
M80-8153422	M80-815_obsolete.pdf	7th September 2018	M80-8543442	M80-854.pdf
M80-8154405	M80-815_obsolete.pdf	7th September 2018	M80-8544445	M80-854.pdf
M80-8154422	M80-815_obsolete.pdf	7th September 2018	M80-8544442	M80-854.pdf
M80-8160405	M80-816_obsolete.pdf	7th September 2018	M80-8120405	M80-812.pdf
M80-8160605	M80-816_obsolete.pdf	7th September 2018	M80-8120605	M80-812.pdf
M80-8160805	M80-816_obsolete.pdf	7th September 2018	M80-8120805	M80-812.pdf
M80-8161005	M80-816_obsolete.pdf	7th September 2018	M80-8121005	M80-812.pdf
M80-8161205	M80-816_obsolete.pdf	7th September 2018	M80-8121205	M80-812.pdf
M80-8170405	M80-817_obsolete.pdf	7th September 2018	M80-8130405	M80-813.pdf
M80-8170605	M80-817_obsolete.pdf	7th September 2018	M80-8130605	M80-813.pdf
M80-8171205	M80-817_obsolete.pdf	7th September 2018	M80-8131205	M80-813.pdf
M80-8270422P	M80-827P_obsolete.pdf	7th September 2018	M80-8260442P	M80-826P.pdf
M80-8270442	M80-827_obsolete.pdf	7th September 2018	M80-8260442	M80-826.pdf
M80-8270442P	M80-827P_obsolete.pdf	7th September 2018	M80-8260442P	M80-826P.pdf
M80-8270445	M80-827_obsolete.pdf	7th September 2018	M80-8260445	M80-826.pdf
M80-8270445P	M80-827P_obsolete.pdf	7th September 2018	M80-8260445P	M80-826P.pdf
M80-8270622	M80-827_obsolete.pdf	7th September 2018	M80-8260642	M80-826.pdf
M80-8270622P	M80-827P_obsolete.pdf	7th September 2018	M80-8260642P	M80-826P.pdf
M80-8270642	M80-827_obsolete.pdf	7th September 2018	M80-8260642	M80-826.pdf
M80-8270642P	M80-827P_obsolete.pdf	7th September 2018	M80-8260642P	M80-826P.pdf

Obsolete Product Notification from Harwin

Part number being made obsolete	Drawing for obsolete product	Last Time buy date	Alternative product	Drawing for alternative product
M80-8270645	M80-827_obsolete.pdf	7th September 2018	M80-8260645	M80-826.pdf
M80-8270645P	M80-827P_obsolete.pdf	7th September 2018	M80-8260645P	M80-826P.pdf
M80-8270822	M80-827_obsolete.pdf	7th September 2018	M80-8260842	M80-826.pdf
M80-8270822P	M80-827P_obsolete.pdf	7th September 2018	M80-8260842P	M80-826P.pdf
M80-8270842	M80-827_obsolete.pdf	7th September 2018	M80-8260842	M80-826.pdf
M80-8270842P	M80-827P_obsolete.pdf	7th September 2018	M80-8260842P	M80-826P.pdf
M80-8270845	M80-827_obsolete.pdf	7th September 2018	M80-8260845	M80-826.pdf
M80-8270845P	M80-827P_obsolete.pdf	7th September 2018	M80-8260845P	M80-826P.pdf
M80-8271022	M80-827_obsolete.pdf	7th September 2018	M80-8261042	M80-826.pdf
M80-8271022P	M80-827P_obsolete.pdf	7th September 2018	M80-8261042P	M80-826P.pdf
M80-8271042	M80-827_obsolete.pdf	7th September 2018	M80-8261042	M80-826.pdf
M80-8271042P	M80-827P_obsolete.pdf	7th September 2018	M80-8261042P	M80-826P.pdf
M80-8271045	M80-827_obsolete.pdf	7th September 2018	M80-8261045	M80-826.pdf
M80-8271045P	M80-827P_obsolete.pdf	7th September 2018	M80-8261045P	M80-826P.pdf
M80-8271222	M80-827_obsolete.pdf	7th September 2018	M80-8261242	M80-826.pdf
M80-8271222P	M80-827P_obsolete.pdf	7th September 2018	M80-8261242P	M80-826P.pdf
M80-8271242	M80-827_obsolete.pdf	7th September 2018	M80-8261242	M80-826.pdf
M80-8271242P	M80-827P_obsolete.pdf	7th September 2018	M80-8261242P	M80-826P.pdf
M80-8271245	M80-827_obsolete.pdf	7th September 2018	M80-8261245	M80-826.pdf
M80-8271245P	M80-827P_obsolete.pdf	7th September 2018	M80-8261245P	M80-826P.pdf
M80-8271422	M80-827_obsolete.pdf	7th September 2018	M80-8261442	M80-826.pdf
M80-8271422P	M80-827P_obsolete.pdf	7th September 2018	M80-8261442P	M80-826P.pdf
M80-8271442	M80-827_obsolete.pdf	7th September 2018	M80-8261442	M80-826.pdf
M80-8271442P	M80-827P_obsolete.pdf	7th September 2018	M80-8261442P	M80-826P.pdf
M80-8271445	M80-827_obsolete.pdf	7th September 2018	M80-8261445	M80-826.pdf
M80-8271445P	M80-827P_obsolete.pdf	7th September 2018	M80-8261445P	M80-826P.pdf
M80-8271622P	M80-827P_obsolete.pdf	7th September 2018	M80-8261642P	M80-826P.pdf
M80-8271642	M80-827_obsolete.pdf	7th September 2018	M80-8261642	M80-826.pdf
M80-8271642P	M80-827P_obsolete.pdf	7th September 2018	M80-8261642P	M80-826P.pdf
M80-8271645	M80-827_obsolete.pdf	7th September 2018	M80-8261645	M80-826.pdf
M80-8271645P	M80-827P_obsolete.pdf	7th September 2018	M80-8261645P	M80-826P.pdf
M80-8271822P	M80-827P_obsolete.pdf	7th September 2018	M80-8261842P	M80-826P.pdf
M80-8271842	M80-827_obsolete.pdf	7th September 2018	M80-8261842	M80-826.pdf
M80-8271842P	M80-827P_obsolete.pdf	7th September 2018	M80-8261842P	M80-826P.pdf
M80-8271845	M80-827_obsolete.pdf	7th September 2018	M80-8261845	M80-826.pdf
M80-8271845P	M80-827P_obsolete.pdf	7th September 2018	M80-8261845P	M80-826P.pdf
M80-8272022	M80-827_obsolete.pdf	7th September 2018	M80-8262042	M80-826.pdf
M80-8272022P	M80-827P_obsolete.pdf	7th September 2018	M80-8262042P	M80-826P.pdf
M80-8272042	M80-827_obsolete.pdf	7th September 2018	M80-8262042	M80-826.pdf
M80-8272042P	M80-827P_obsolete.pdf	7th September 2018	M80-8262042P	M80-826P.pdf
M80-8272045	M80-827_obsolete.pdf	7th September 2018	M80-8262045	M80-826.pdf
M80-8272045P	M80-827P_obsolete.pdf	7th September 2018	M80-8262045P	M80-826P.pdf
M80-8272622P	M80-827P_obsolete.pdf	7th September 2018	M80-8262642P	M80-826P.pdf
M80-8272642	M80-827_obsolete.pdf	7th September 2018	M80-8262642	M80-826.pdf
M80-8272642P	M80-827P_obsolete.pdf	7th September 2018	M80-8262642P	M80-826P.pdf
M80-8272645	M80-827_obsolete.pdf	7th September 2018	M80-8262645	M80-826.pdf
M80-8272645P	M80-827P_obsolete.pdf	7th September 2018	M80-8262645P	M80-826P.pdf
M80-8273422P	M80-827P_obsolete.pdf	7th September 2018	M80-8263442P	M80-826P.pdf
M80-8273442	M80-827_obsolete.pdf	7th September 2018	M80-8263442	M80-826.pdf
M80-8273442P	M80-827P_obsolete.pdf	7th September 2018	M80-8263442P	M80-826P.pdf
M80-8273445	M80-827_obsolete.pdf	7th September 2018	M80-8263445	M80-826.pdf
M80-8273445P	M80-827P_obsolete.pdf	7th September 2018	M80-8263445P	M80-826P.pdf
M80-8350222	M80-835_obsolete.pdf	7th September 2018	M80-8370242	M80-837.pdf
M80-8350242	M80-835_obsolete.pdf	7th September 2018	M80-8370242	M80-837.pdf
M80-8350245	M80-835_obsolete.pdf	7th September 2018	M80-8370245	M80-837.pdf
M80-8350322	M80-835_obsolete.pdf	7th September 2018	M80-8370342	M80-837.pdf
M80-8350342	M80-835_obsolete.pdf	7th September 2018	M80-8370342	M80-837.pdf

Obsolete Product Notification from Harwin

Part number being made obsolete	Drawing for obsolete product	Last Time buy date	Alternative product	Drawing for alternative product
M80-8350345	M80-835_obsolete.pdf	7th September 2018	M80-8370345	M80-837.pdf
M80-8350442	M80-835_obsolete.pdf	7th September 2018	M80-8370442	M80-837.pdf
M80-8350445	M80-835_obsolete.pdf	7th September 2018	M80-8370445	M80-837.pdf
M80-8350522	M80-835_obsolete.pdf	7th September 2018	M80-8370542	M80-837.pdf
M80-8350542	M80-835_obsolete.pdf	7th September 2018	M80-8370542	M80-837.pdf
M80-8350545	M80-835_obsolete.pdf	7th September 2018	M80-8370545	M80-837.pdf
M80-8350622	M80-835_obsolete.pdf	7th September 2018	M80-8370642	M80-837.pdf
M80-8350642	M80-835_obsolete.pdf	7th September 2018	M80-8370642	M80-837.pdf
M80-8350645	M80-835_obsolete.pdf	7th September 2018	M80-8370645	M80-837.pdf
M80-8350722	M80-835_obsolete.pdf	7th September 2018	M80-8370742	M80-837.pdf
M80-8350742	M80-835_obsolete.pdf	7th September 2018	M80-8370742	M80-837.pdf
M80-8350745	M80-835_obsolete.pdf	7th September 2018	M80-8370745	M80-837.pdf
M80-8351722	M80-835_obsolete.pdf	7th September 2018	M80-8371742	M80-837.pdf
M80-8351742	M80-835_obsolete.pdf	7th September 2018	M80-8371742	M80-837.pdf
M80-8351745	M80-835_obsolete.pdf	7th September 2018	M80-8371745	M80-837.pdf
M80-8352222	M80-835_obsolete.pdf	7th September 2018	M80-8372242	M80-837.pdf
M80-8352242	M80-835_obsolete.pdf	7th September 2018	M80-8372242	M80-837.pdf
M80-8352245	M80-835_obsolete.pdf	7th September 2018	M80-8372245	M80-837.pdf
M80-8390422	M80-839_obsolete.pdf	7th September 2018	M80-8410442	M80-841.pdf
M80-8390442	M80-839_obsolete.pdf	7th September 2018	M80-8410442	M80-841.pdf
M80-8390445	M80-839_obsolete.pdf	7th September 2018	M80-8410445	M80-841.pdf
M80-8390622	M80-839_obsolete.pdf	7th September 2018	M80-8410642	M80-841.pdf
M80-8390642	M80-839_obsolete.pdf	7th September 2018	M80-8410642	M80-841.pdf
M80-8390645	M80-839_obsolete.pdf	7th September 2018	M80-8410645	M80-841.pdf
M80-8390822	M80-839_obsolete.pdf	7th September 2018	M80-8410842	M80-841.pdf
M80-8390842	M80-839_obsolete.pdf	7th September 2018	M80-8410842	M80-841.pdf
M80-8390845	M80-839_obsolete.pdf	7th September 2018	M80-8410845	M80-841.pdf
M80-8391022	M80-839_obsolete.pdf	7th September 2018	M80-8411042	M80-841.pdf
M80-8391042	M80-839_obsolete.pdf	7th September 2018	M80-8411042	M80-841.pdf
M80-8391045	M80-839_obsolete.pdf	7th September 2018	M80-8411045	M80-841.pdf
M80-8391222	M80-839_obsolete.pdf	7th September 2018	M80-8411242	M80-841.pdf
M80-8391242	M80-839_obsolete.pdf	7th September 2018	M80-8411242	M80-841.pdf
M80-8391245	M80-839_obsolete.pdf	7th September 2018	M80-8411245	M80-841.pdf
M80-8391422	M80-839_obsolete.pdf	7th September 2018	M80-8411442	M80-841.pdf
M80-8391442	M80-839_obsolete.pdf	7th September 2018	M80-8411442	M80-841.pdf
M80-8391445	M80-839_obsolete.pdf	7th September 2018	M80-8411445	M80-841.pdf
M80-8391622	M80-839_obsolete.pdf	7th September 2018	M80-8411642	M80-841.pdf
M80-8391642	M80-839_obsolete.pdf	7th September 2018	M80-8411642	M80-841.pdf
M80-8391645	M80-839_obsolete.pdf	7th September 2018	M80-8411645	M80-841.pdf
M80-8391822	M80-839_obsolete.pdf	7th September 2018	M80-8411842	M80-841.pdf
M80-8391842	M80-839_obsolete.pdf	7th September 2018	M80-8411842	M80-841.pdf
M80-8391845	M80-839_obsolete.pdf	7th September 2018	M80-8411845	M80-841.pdf
M80-8392022	M80-839_obsolete.pdf	7th September 2018	M80-8412042	M80-841.pdf
M80-8392042	M80-839_obsolete.pdf	7th September 2018	M80-8412042	M80-841.pdf
M80-8392045	M80-839_obsolete.pdf	7th September 2018	M80-8412045	M80-841.pdf
M80-8392622	M80-839_obsolete.pdf	7th September 2018	M80-8412642	M80-841.pdf
M80-8392642	M80-839_obsolete.pdf	7th September 2018	M80-8412642	M80-841.pdf
M80-8392645	M80-839_obsolete.pdf	7th September 2018	M80-8412645	M80-841.pdf
M80-8393422	M80-839_obsolete.pdf	7th September 2018	M80-8413442	M80-841.pdf
M80-8393442	M80-839_obsolete.pdf	7th September 2018	M80-8413442	M80-841.pdf
M80-8393445	M80-839_obsolete.pdf	7th September 2018	M80-8413445	M80-841.pdf
M80-8394422	M80-839_obsolete.pdf	7th September 2018	M80-8414442	M80-841.pdf
M80-8394442	M80-839_obsolete.pdf	7th September 2018	M80-8414442	M80-841.pdf
M80-8394445	M80-839_obsolete.pdf	7th September 2018	M80-8414445	M80-841.pdf
M80-8460222	M80-846_obsolete.pdf	7th September 2018	M80-8430242	M80-843.pdf
M80-8460242	M80-846_obsolete.pdf	7th September 2018	M80-8430242	M80-843.pdf
M80-8460245	M80-846_obsolete.pdf	7th September 2018	M80-8430245	M80-843.pdf

Obsolete Product Notification from Harwin

Part number being made obsolete	Drawing for obsolete product	Last Time buy date	Alternative product	Drawing for alternative product
M80-8460322	M80-846_obsolete.pdf	7th September 2018	M80-8430342	M80-843.pdf
M80-8460342	M80-846_obsolete.pdf	7th September 2018	M80-8430342	M80-843.pdf
M80-8460345	M80-846_obsolete.pdf	7th September 2018	M80-8430345	M80-843.pdf
M80-8460422	M80-846_obsolete.pdf	7th September 2018	M80-8430442	M80-843.pdf
M80-8460442	M80-846_obsolete.pdf	7th September 2018	M80-8430442	M80-843.pdf
M80-8460445	M80-846_obsolete.pdf	7th September 2018	M80-8430445	M80-843.pdf
M80-8460522	M80-846_obsolete.pdf	7th September 2018	M80-8430542	M80-843.pdf
M80-8460542	M80-846_obsolete.pdf	7th September 2018	M80-8430542	M80-843.pdf
M80-8460545	M80-846_obsolete.pdf	7th September 2018	M80-8430545	M80-843.pdf
M80-8460622	M80-846_obsolete.pdf	7th September 2018	M80-8430642	M80-843.pdf
M80-8460642	M80-846_obsolete.pdf	7th September 2018	M80-8430642	M80-843.pdf
M80-8460645	M80-846_obsolete.pdf	7th September 2018	M80-8430645	M80-843.pdf
M80-8460722	M80-846_obsolete.pdf	7th September 2018	M80-8430742	M80-843.pdf
M80-8460742	M80-846_obsolete.pdf	7th September 2018	M80-8430742	M80-843.pdf
M80-8460745	M80-846_obsolete.pdf	7th September 2018	M80-8430745	M80-843.pdf
M80-8461722	M80-846_obsolete.pdf	7th September 2018	M80-8431742	M80-843.pdf
M80-8461742	M80-846_obsolete.pdf	7th September 2018	M80-8431742	M80-843.pdf
M80-8461745	M80-846_obsolete.pdf	7th September 2018	M80-8431745	M80-843.pdf
M80-8462222	M80-846_obsolete.pdf	7th September 2018	M80-8432242	M80-843.pdf
M80-8462242	M80-846_obsolete.pdf	7th September 2018	M80-8432242	M80-843.pdf
M80-8462245	M80-846_obsolete.pdf	7th September 2018	M80-8432245	M80-843.pdf
M80-8630422	M80-863_obsolete.pdf	7th September 2018	M80-8540442	M80-854.pdf
M80-8630442	M80-863_obsolete.pdf	7th September 2018	M80-8540442	M80-854.pdf
M80-8630445	M80-863_obsolete.pdf	7th September 2018	M80-8540445	M80-854.pdf
M80-8630622	M80-863_obsolete.pdf	7th September 2018	M80-8540642	M80-854.pdf
M80-8630642	M80-863_obsolete.pdf	7th September 2018	M80-8540642	M80-854.pdf
M80-8630645	M80-863_obsolete.pdf	7th September 2018	M80-8540645	M80-854.pdf
M80-8630822	M80-863_obsolete.pdf	7th September 2018	M80-8540842	M80-854.pdf
M80-8630842	M80-863_obsolete.pdf	7th September 2018	M80-8540842	M80-854.pdf
M80-8630845	M80-863_obsolete.pdf	7th September 2018	M80-8540845	M80-854.pdf
M80-8631022	M80-863_obsolete.pdf	7th September 2018	M80-8541042	M80-854.pdf
M80-8631042	M80-863_obsolete.pdf	7th September 2018	M80-8541042	M80-854.pdf
M80-8631045	M80-863_obsolete.pdf	7th September 2018	M80-8541045	M80-854.pdf
M80-8631222	M80-863_obsolete.pdf	7th September 2018	M80-8541242	M80-854.pdf
M80-8631242	M80-863_obsolete.pdf	7th September 2018	M80-8541242	M80-854.pdf
M80-8631245	M80-863_obsolete.pdf	7th September 2018	M80-8541245	M80-854.pdf
M80-8631422	M80-863_obsolete.pdf	7th September 2018	M80-8541442	M80-854.pdf
M80-8631442	M80-863_obsolete.pdf	7th September 2018	M80-8541442	M80-854.pdf
M80-8631445	M80-863_obsolete.pdf	7th September 2018	M80-8541445	M80-854.pdf
M80-8631622	M80-863_obsolete.pdf	7th September 2018	M80-8541642	M80-854.pdf
M80-8631642	M80-863_obsolete.pdf	7th September 2018	M80-8541642	M80-854.pdf
M80-8631645	M80-863_obsolete.pdf	7th September 2018	M80-8541645	M80-854.pdf
M80-8631822	M80-863_obsolete.pdf	7th September 2018	M80-8541842	M80-854.pdf
M80-8631842	M80-863_obsolete.pdf	7th September 2018	M80-8541842	M80-854.pdf
M80-8631845	M80-863_obsolete.pdf	7th September 2018	M80-8541845	M80-854.pdf
M80-8632022	M80-863_obsolete.pdf	7th September 2018	M80-8542042	M80-854.pdf
M80-8632042	M80-863_obsolete.pdf	7th September 2018	M80-8542042	M80-854.pdf
M80-8632045	M80-863_obsolete.pdf	7th September 2018	M80-8542045	M80-854.pdf
M80-8632622	M80-863_obsolete.pdf	7th September 2018	M80-8542642	M80-854.pdf
M80-8632642	M80-863_obsolete.pdf	7th September 2018	M80-8542642	M80-854.pdf
M80-8632645	M80-863_obsolete.pdf	7th September 2018	M80-8542645	M80-854.pdf
M80-8633422	M80-863_obsolete.pdf	7th September 2018	M80-8543442	M80-854.pdf
M80-8633442	M80-863_obsolete.pdf	7th September 2018	M80-8543442	M80-854.pdf
M80-8633445	M80-863_obsolete.pdf	7th September 2018	M80-8543445	M80-854.pdf
M80-8634422	M80-863_obsolete.pdf	7th September 2018	M80-8544442	M80-854.pdf
M80-8634442	M80-863_obsolete.pdf	7th September 2018	M80-8544442	M80-854.pdf
M80-8634445	M80-863_obsolete.pdf	7th September 2018	M80-8544445	M80-854.pdf

Obsolete Product Notification from Harwin

Part number being made obsolete	Drawing for obsolete product	Last Time buy date	Alternative product	Drawing for alternative product
M80-8810222	M80-881_obsolete.pdf	7th September 2018	M80-8520242	M80-852.pdf
M80-8810242	M80-881_obsolete.pdf	7th September 2018	M80-8520242	M80-852.pdf
M80-8810245	M80-881_obsolete.pdf	7th September 2018	M80-8520245	M80-852.pdf
M80-8810322	M80-881_obsolete.pdf	7th September 2018	M80-8520342	M80-852.pdf
M80-8810342	M80-881_obsolete.pdf	7th September 2018	M80-8520342	M80-852.pdf
M80-8810422	M80-881_obsolete.pdf	7th September 2018	M80-8520442	M80-852.pdf
M80-8810442	M80-881_obsolete.pdf	7th September 2018	M80-8520442	M80-852.pdf
M80-8810445	M80-881_obsolete.pdf	7th September 2018	M80-8520445	M80-852.pdf
M80-8810522	M80-881_obsolete.pdf	7th September 2018	M80-8520542	M80-852.pdf
M80-8810542	M80-881_obsolete.pdf	7th September 2018	M80-8520542	M80-852.pdf
M80-8810545	M80-881_obsolete.pdf	7th September 2018	M80-8520545	M80-852.pdf
M80-8810622	M80-881_obsolete.pdf	7th September 2018	M80-8520642	M80-852.pdf
M80-8810642	M80-881_obsolete.pdf	7th September 2018	M80-8520642	M80-852.pdf
M80-8810645	M80-881_obsolete.pdf	7th September 2018	M80-8520645	M80-852.pdf
M80-8810722	M80-881_obsolete.pdf	7th September 2018	M80-8520742	M80-852.pdf
M80-8810742	M80-881_obsolete.pdf	7th September 2018	M80-8520742	M80-852.pdf
M80-8810745	M80-881_obsolete.pdf	7th September 2018	M80-8520745	M80-852.pdf
M80-8811722	M80-881_obsolete.pdf	7th September 2018	M80-8521742	M80-852.pdf
M80-8811742	M80-881_obsolete.pdf	7th September 2018	M80-8521742	M80-852.pdf
M80-8811745	M80-881_obsolete.pdf	7th September 2018	M80-8521745	M80-852.pdf
M80-8812222	M80-881_obsolete.pdf	7th September 2018	M80-8522242	M80-852.pdf
M80-8812242	M80-881_obsolete.pdf	7th September 2018	M80-8522242	M80-852.pdf
M80-8812245	M80-881_obsolete.pdf	7th September 2018	M80-8522245	M80-852.pdf
M80-8830205	M80-883_obsolete.pdf	7th September 2018	M80-8080205	M80-808.pdf
M80-8830305	M80-883_obsolete.pdf	7th September 2018	M80-8080305	M80-808.pdf
M80-8830405	M80-883_obsolete.pdf	7th September 2018	M80-8080405	M80-808.pdf
M80-8830505	M80-883_obsolete.pdf	7th September 2018	M80-8080505	M80-808.pdf
M80-8830605	M80-883_obsolete.pdf	7th September 2018	M80-8080605	M80-808.pdf
M80-8830705	M80-883_obsolete.pdf	7th September 2018	M80-8080705	M80-808.pdf
M80-8840205	M80-884_obsolete.pdf	7th September 2018	M80-8090205	M80-809.pdf
M80-8840305	M80-884_obsolete.pdf	7th September 2018	M80-8090305	M80-809.pdf
M80-8840405	M80-884_obsolete.pdf	7th September 2018	M80-8090405	M80-809.pdf
M80-8840505	M80-884_obsolete.pdf	7th September 2018	M80-8090505	M80-809.pdf
M80-8840605	M80-884_obsolete.pdf	7th September 2018	M80-8090605	M80-809.pdf
M80-8840705	M80-884_obsolete.pdf	7th September 2018	M80-8090705	M80-809.pdf
M80C108489C-04	Contact technical@harwin.com	7th September 2018	Contact technical@harwin.com	
M80C108489C-06	Contact technical@harwin.com	7th September 2018	Contact technical@harwin.com	
M80C108489C-08	Contact technical@harwin.com	7th September 2018	Contact technical@harwin.com	
M80C108489C-10	Contact technical@harwin.com	7th September 2018	Contact technical@harwin.com	
M80C108489C-12	Contact technical@harwin.com	7th September 2018	Contact technical@harwin.com	
M80C108489C-14	Contact technical@harwin.com	7th September 2018	Contact technical@harwin.com	
M80C108489C-16	Contact technical@harwin.com	7th September 2018	Contact technical@harwin.com	
M80C108489C-18	Contact technical@harwin.com	7th September 2018	Contact technical@harwin.com	
M80C108489C-20	Contact technical@harwin.com	7th September 2018	Contact technical@harwin.com	
M80C108489C-26	Contact technical@harwin.com	7th September 2018	Contact technical@harwin.com	
M80C108489C-34	Contact technical@harwin.com	7th September 2018	Contact technical@harwin.com	
M80C108489C-44	Contact technical@harwin.com	7th September 2018	Contact technical@harwin.com	
M80C109272C	Contact technical@harwin.com	7th September 2018	Contact technical@harwin.com	
M80C150147C	Contact technical@harwin.com	7th September 2018	Contact technical@harwin.com	