



Harwin plc  
Fitzherbert Road  
Farlington, Portsmouth  
Hampshire PO6 1RT  
United Kingdom

Reception: +44 (0)23 9231 4545  
Sales Desk: +44 (0)23 9237 0451

Thursday 26<sup>th</sup> July, 2018

Dear Customer,

**Re: Obsolescence notification for Harwin product.**

Please be advised that the following product is now obsolete **with a last-time buy date of 28<sup>th</sup> September 2018:**

- S4011-46

The following ranges/products are now obsolete **with a last-time buy date of 26<sup>th</sup> October 2018:**

- M80-752 family
- W2222-00, W2330-00, W2331-00, W2332-00, Z1001-00

The following ranges/products are now obsolete **with immediate effect:**

- Datamate S-Tek – M80-4C1xxxxS1, M80-4D1xxxxS1, M80-5C1xxxxB1, M80-5D1xxxxB1, M80-5T1xxxxB1, M80-5T2xxxxB1
- R50-300 family
- W2231-00, W2232-00, W2531-00
- Z125-925 family
- H2172-xx
- Other Special items

Please see the following spreadsheet for a detailed list of affected items:  
[https://cdn.harwin.com/pdfs/Obsolescence\\_notification\\_spreadsheet\\_2018-07-26.xlsx](https://cdn.harwin.com/pdfs/Obsolescence_notification_spreadsheet_2018-07-26.xlsx)

Unfortunately, we are no longer able to support these product lines. Alternative items are available in some cases; please see the spreadsheet for the alternative part numbers.

If you have any further questions regarding this letter, please do not hesitate to contact us.

Yours faithfully,

The Product Change Team  
[technical@harwin.com](mailto:technical@harwin.com)

# Obsolete Product Notification from Harwin

Part number being made obsolete	Drawing for obsolete product	Last Time buy date	Alternative product	Drawing for alternative product
3425-3183	Contact technical@harwin.com	Immediate	<a href="#">H3183-01</a>	<a href="#">H3183.pdf</a>
D01C108511C	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
H105586C	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
H107925C	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
H108068C	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
H108433C	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
H2172-01	<a href="#">H2170-H2174.pdf</a>	Immediate	<a href="#">H2171-01</a>	<a href="#">H2170-H2174.pdf</a>
H2172-05	<a href="#">H2170-H2174.pdf</a>	Immediate	<a href="#">H2171-05</a>	<a href="#">H2170-H2174.pdf</a>
HD5556	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
HD5557	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
HD5688	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
HD5689	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
HD5690	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
HD5693	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
HD5698	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
HD5701	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
HD5792	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
HD5880-42	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
HD5881-xx	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
HD5917-42	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
HD5925-10	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
HD5930	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
HD5934	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
HD5940	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
HD5941	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
HD5942	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
HD5943	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
HD5964	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M106348C-SC	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M20-060040V0245	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M20-160025V3046	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M20-280036W0546	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M20-295080W0745	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M20C107497CR	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M22-035035W0405	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M22-045024V1005	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M22-058015W0305	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M22-062035W0505	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M22-075020V1805	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M22-1085087	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M30C108543C-25	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M50-041039T2245R	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M50C108942CR	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M80-4C10605S1	<a href="#">M80-4C1XXXXS1_obsolete.pdf</a>	Immediate	Contact technical@harwin.com	
M80-4C10642S1	<a href="#">M80-4C1XXXXS1_obsolete.pdf</a>	Immediate	Contact technical@harwin.com	
M80-4C11005S1	<a href="#">M80-4C1XXXXS1_obsolete.pdf</a>	Immediate	<a href="#">M80-9451002</a>	<a href="#">M80-945.pdf</a>
M80-4C11042S1	<a href="#">M80-4C1XXXXS1_obsolete.pdf</a>	Immediate	<a href="#">M80-9451002</a>	<a href="#">M80-945.pdf</a>
M80-4C11405S1	<a href="#">M80-4C1XXXXS1_obsolete.pdf</a>	Immediate	<a href="#">M80-9451402</a>	<a href="#">M80-945.pdf</a>
M80-4C11442S1	<a href="#">M80-4C1XXXXS1_obsolete.pdf</a>	Immediate	<a href="#">M80-9451402</a>	<a href="#">M80-945.pdf</a>
M80-4C12005S1	<a href="#">M80-4C1XXXXS1_obsolete.pdf</a>	Immediate	<a href="#">M80-9452002</a>	<a href="#">M80-945.pdf</a>
M80-4C12042S1	<a href="#">M80-4C1XXXXS1_obsolete.pdf</a>	Immediate	<a href="#">M80-9452002</a>	<a href="#">M80-945.pdf</a>
M80-4C12605S1	<a href="#">M80-4C1XXXXS1_obsolete.pdf</a>	Immediate	<a href="#">M80-9452602</a>	<a href="#">M80-945.pdf</a>
M80-4C12642S1	<a href="#">M80-4C1XXXXS1_obsolete.pdf</a>	Immediate	<a href="#">M80-9452602</a>	<a href="#">M80-945.pdf</a>
M80-4D10605S1	<a href="#">M80-4D1XXXXS1_obsolete.pdf</a>	Immediate	Contact technical@harwin.com	
M80-4D10642S1	<a href="#">M80-4D1XXXXS1_obsolete.pdf</a>	Immediate	Contact technical@harwin.com	
M80-4D11005S1	<a href="#">M80-4D1XXXXS1_obsolete.pdf</a>	Immediate	<a href="#">M80-9451002</a>	<a href="#">M80-945.pdf</a>
M80-4D11042S1	<a href="#">M80-4D1XXXXS1_obsolete.pdf</a>	Immediate	<a href="#">M80-9451002</a>	<a href="#">M80-945.pdf</a>
M80-4D11405S1	<a href="#">M80-4D1XXXXS1_obsolete.pdf</a>	Immediate	<a href="#">M80-9451402</a>	<a href="#">M80-945.pdf</a>
M80-4D11442S1	<a href="#">M80-4D1XXXXS1_obsolete.pdf</a>	Immediate	<a href="#">M80-9451402</a>	<a href="#">M80-945.pdf</a>
M80-4D12005S1	<a href="#">M80-4D1XXXXS1_obsolete.pdf</a>	Immediate	<a href="#">M80-9452002</a>	<a href="#">M80-945.pdf</a>
M80-4D12042S1	<a href="#">M80-4D1XXXXS1_obsolete.pdf</a>	Immediate	<a href="#">M80-9452002</a>	<a href="#">M80-945.pdf</a>
M80-4D12605S1	<a href="#">M80-4D1XXXXS1_obsolete.pdf</a>	Immediate	<a href="#">M80-9452602</a>	<a href="#">M80-945.pdf</a>
M80-4D12642S1	<a href="#">M80-4D1XXXXS1_obsolete.pdf</a>	Immediate	<a href="#">M80-9452602</a>	<a href="#">M80-945.pdf</a>
M80-5C10605B1	<a href="#">M80-5C1XXXXB1_obsolete.pdf</a>	Immediate	Contact technical@harwin.com	
M80-5C11005B1	<a href="#">M80-5C1XXXXB1_obsolete.pdf</a>	Immediate	<a href="#">M80-9061002</a>	<a href="#">M80-906.pdf</a>
M80-5C11405B1	<a href="#">M80-5C1XXXXB1_obsolete.pdf</a>	Immediate	<a href="#">M80-9061402</a>	<a href="#">M80-906.pdf</a>
M80-5C12005B1	<a href="#">M80-5C1XXXXB1_obsolete.pdf</a>	Immediate	<a href="#">M80-9062002</a>	<a href="#">M80-906.pdf</a>
M80-5C12605B1	<a href="#">M80-5C1XXXXB1_obsolete.pdf</a>	Immediate	<a href="#">M80-9062602</a>	<a href="#">M80-906.pdf</a>
M80-5D10605B1	<a href="#">M80-5D1XXXXB1_obsolete.pdf</a>	Immediate	Contact technical@harwin.com	
M80-5D11005B1	<a href="#">M80-5D1XXXXB1_obsolete.pdf</a>	Immediate	<a href="#">M80-9061002</a>	<a href="#">M80-906.pdf</a>

# Obsolete Product Notification from Harwin

Part number being made obsolete	Drawing for obsolete product	Last Time buy date	Alternative product	Drawing for alternative product
M80-5D11405B1	<a href="#">M80-5D1XXXXB1_obsolete.pdf</a>	Immediate	<a href="#">M80-9061402</a>	<a href="#">M80-906.pdf</a>
M80-5D12005B1	<a href="#">M80-5D1XXXXB1_obsolete.pdf</a>	Immediate	<a href="#">M80-9062002</a>	<a href="#">M80-906.pdf</a>
M80-5D12605B1	<a href="#">M80-5D1XXXXB1_obsolete.pdf</a>	Immediate	<a href="#">M80-9062602</a>	<a href="#">M80-906.pdf</a>
M80-5T10605B1	<a href="#">M80-5T1XXXXB1_obsolete.pdf</a>	Immediate	Contact technical@harwin.com	
M80-5T10622B1	<a href="#">M80-5T1XXXXB1_obsolete.pdf</a>	Immediate	Contact technical@harwin.com	
M80-5T10642B1	<a href="#">M80-5T1XXXXB1_obsolete.pdf</a>	Immediate	Contact technical@harwin.com	
M80-5T11005B1	<a href="#">M80-5T1XXXXB1_obsolete.pdf</a>	Immediate	<a href="#">M80-9061002</a>	<a href="#">M80-906.pdf</a>
M80-5T11022B1	<a href="#">M80-5T1XXXXB1_obsolete.pdf</a>	Immediate	<a href="#">M80-9061002</a>	<a href="#">M80-906.pdf</a>
M80-5T11042B1	<a href="#">M80-5T1XXXXB1_obsolete.pdf</a>	Immediate	<a href="#">M80-9061002</a>	<a href="#">M80-906.pdf</a>
M80-5T11405B1	<a href="#">M80-5T1XXXXB1_obsolete.pdf</a>	Immediate	<a href="#">M80-9061402</a>	<a href="#">M80-906.pdf</a>
M80-5T11422B1	<a href="#">M80-5T1XXXXB1_obsolete.pdf</a>	Immediate	<a href="#">M80-9061402</a>	<a href="#">M80-906.pdf</a>
M80-5T11442B1	<a href="#">M80-5T1XXXXB1_obsolete.pdf</a>	Immediate	<a href="#">M80-9061402</a>	<a href="#">M80-906.pdf</a>
M80-5T12005B1	<a href="#">M80-5T1XXXXB1_obsolete.pdf</a>	Immediate	<a href="#">M80-9062002</a>	<a href="#">M80-906.pdf</a>
M80-5T12022B1	<a href="#">M80-5T1XXXXB1_obsolete.pdf</a>	Immediate	<a href="#">M80-9062002</a>	<a href="#">M80-906.pdf</a>
M80-5T12042B1	<a href="#">M80-5T1XXXXB1_obsolete.pdf</a>	Immediate	<a href="#">M80-9062002</a>	<a href="#">M80-906.pdf</a>
M80-5T12605B1	<a href="#">M80-5T1XXXXB1_obsolete.pdf</a>	Immediate	<a href="#">M80-9062602</a>	<a href="#">M80-906.pdf</a>
M80-5T12622B1	<a href="#">M80-5T1XXXXB1_obsolete.pdf</a>	Immediate	<a href="#">M80-9062602</a>	<a href="#">M80-906.pdf</a>
M80-5T12642B1	<a href="#">M80-5T1XXXXB1_obsolete.pdf</a>	Immediate	<a href="#">M80-9062602</a>	<a href="#">M80-906.pdf</a>
M80-5T20605B1	<a href="#">M80-5T2XXXXB1_obsolete.pdf</a>	Immediate	Contact technical@harwin.com	
M80-5T20622B1	<a href="#">M80-5T2XXXXB1_obsolete.pdf</a>	Immediate	Contact technical@harwin.com	
M80-5T20642B1	<a href="#">M80-5T2XXXXB1_obsolete.pdf</a>	Immediate	Contact technical@harwin.com	
M80-5T21005B1	<a href="#">M80-5T2XXXXB1_obsolete.pdf</a>	Immediate	<a href="#">M80-9061002</a>	<a href="#">M80-906.pdf</a>
M80-5T21022B1	<a href="#">M80-5T2XXXXB1_obsolete.pdf</a>	Immediate	<a href="#">M80-9061002</a>	<a href="#">M80-906.pdf</a>
M80-5T21042B1	<a href="#">M80-5T2XXXXB1_obsolete.pdf</a>	Immediate	<a href="#">M80-9061002</a>	<a href="#">M80-906.pdf</a>
M80-5T21405B1	<a href="#">M80-5T2XXXXB1_obsolete.pdf</a>	Immediate	<a href="#">M80-9061402</a>	<a href="#">M80-906.pdf</a>
M80-5T21422B1	<a href="#">M80-5T2XXXXB1_obsolete.pdf</a>	Immediate	<a href="#">M80-9061402</a>	<a href="#">M80-906.pdf</a>
M80-5T21442B1	<a href="#">M80-5T2XXXXB1_obsolete.pdf</a>	Immediate	<a href="#">M80-9061402</a>	<a href="#">M80-906.pdf</a>
M80-5T22005B1	<a href="#">M80-5T2XXXXB1_obsolete.pdf</a>	Immediate	<a href="#">M80-9062002</a>	<a href="#">M80-906.pdf</a>
M80-5T22022B1	<a href="#">M80-5T2XXXXB1_obsolete.pdf</a>	Immediate	<a href="#">M80-9062002</a>	<a href="#">M80-906.pdf</a>
M80-5T22042B1	<a href="#">M80-5T2XXXXB1_obsolete.pdf</a>	Immediate	<a href="#">M80-9062002</a>	<a href="#">M80-906.pdf</a>
M80-5T22605B1	<a href="#">M80-5T2XXXXB1_obsolete.pdf</a>	Immediate	<a href="#">M80-9062602</a>	<a href="#">M80-906.pdf</a>
M80-5T22622B1	<a href="#">M80-5T2XXXXB1_obsolete.pdf</a>	Immediate	<a href="#">M80-9062602</a>	<a href="#">M80-906.pdf</a>
M80-5T22642B1	<a href="#">M80-5T2XXXXB1_obsolete.pdf</a>	Immediate	<a href="#">M80-9062602</a>	<a href="#">M80-906.pdf</a>
M80-7520242	<a href="#">M80-752_obsolete.pdf</a>	26th October 2018	<a href="#">M80-7820242</a>	<a href="#">M80-782.pdf</a>
M80-7520322	<a href="#">M80-752_obsolete.pdf</a>	26th October 2018	<a href="#">M80-7820342</a>	<a href="#">M80-782.pdf</a>
M80-7520422	<a href="#">M80-752_obsolete.pdf</a>	26th October 2018	<a href="#">M80-7820442</a>	<a href="#">M80-782.pdf</a>
M80-7520522	<a href="#">M80-752_obsolete.pdf</a>	26th October 2018	<a href="#">M80-7820542</a>	<a href="#">M80-782.pdf</a>
M80-7520542	<a href="#">M80-752_obsolete.pdf</a>	26th October 2018	<a href="#">M80-7820542</a>	<a href="#">M80-782.pdf</a>
M80-7520622	<a href="#">M80-752_obsolete.pdf</a>	26th October 2018	<a href="#">M80-7820642</a>	<a href="#">M80-782.pdf</a>
M80-7520642	<a href="#">M80-752_obsolete.pdf</a>	26th October 2018	<a href="#">M80-7820642</a>	<a href="#">M80-782.pdf</a>
M80-7520722	<a href="#">M80-752_obsolete.pdf</a>	26th October 2018	<a href="#">M80-7820742</a>	<a href="#">M80-782.pdf</a>
M80-7520742	<a href="#">M80-752_obsolete.pdf</a>	26th October 2018	<a href="#">M80-7820742</a>	<a href="#">M80-782.pdf</a>
M80-7521722	<a href="#">M80-752_obsolete.pdf</a>	26th October 2018	<a href="#">M80-7821742</a>	<a href="#">M80-782.pdf</a>
M80-7521742	<a href="#">M80-752_obsolete.pdf</a>	26th October 2018	<a href="#">M80-7821742</a>	<a href="#">M80-782.pdf</a>
M80-7522222	<a href="#">M80-752_obsolete.pdf</a>	26th October 2018	<a href="#">M80-7822242</a>	<a href="#">M80-782.pdf</a>
M80-7522242	<a href="#">M80-752_obsolete.pdf</a>	26th October 2018	<a href="#">M80-7822242</a>	<a href="#">M80-782.pdf</a>
M80C108780C-2242	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M80C108963C	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M80C108964C	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M90-7010845	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M90C109334C	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M90C109335C	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M90C109337C	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M90C109338C	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M90C150626C	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M90C150627C	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
R50-3000802	<a href="#">R50-300_obsolete.pdf</a>	Immediate	<a href="#">R40-3000802</a>	<a href="#">R40-300.pdf</a>
R50-3000902	<a href="#">R50-300_obsolete.pdf</a>	Immediate	<a href="#">R40-3000902</a>	<a href="#">R40-300.pdf</a>
R50-3001002	<a href="#">R50-300_obsolete.pdf</a>	Immediate	<a href="#">R40-3001002</a>	<a href="#">R40-300.pdf</a>
R50-3001102	<a href="#">R50-300_obsolete.pdf</a>	Immediate	<a href="#">R40-3001102</a>	<a href="#">R40-300.pdf</a>
R50-3001202	<a href="#">R50-300_obsolete.pdf</a>	Immediate	<a href="#">R40-3001202</a>	<a href="#">R40-300.pdf</a>
R50-3001302	<a href="#">R50-300_obsolete.pdf</a>	Immediate	<a href="#">R40-3001302</a>	<a href="#">R40-300.pdf</a>
R50-3001402	<a href="#">R50-300_obsolete.pdf</a>	Immediate	<a href="#">R40-3001402</a>	<a href="#">R40-300.pdf</a>
R50-3001502	<a href="#">R50-300_obsolete.pdf</a>	Immediate	<a href="#">R40-3001502</a>	<a href="#">R40-300.pdf</a>
R50-3001602	<a href="#">R50-300_obsolete.pdf</a>	Immediate	<a href="#">R40-3001602</a>	<a href="#">R40-300.pdf</a>
R50-3001802	<a href="#">R50-300_obsolete.pdf</a>	Immediate	<a href="#">R40-3001802</a>	<a href="#">R40-300.pdf</a>
R50-3002002	<a href="#">R50-300_obsolete.pdf</a>	Immediate	<a href="#">R40-3002002</a>	<a href="#">R40-300.pdf</a>
R50-3002502	<a href="#">R50-300_obsolete.pdf</a>	Immediate	<a href="#">R40-3002502</a>	<a href="#">R40-300.pdf</a>
R50-3003002	<a href="#">R50-300_obsolete.pdf</a>	Immediate	<a href="#">R40-3003002</a>	<a href="#">R40-300.pdf</a>
R50-3003502	<a href="#">R50-300_obsolete.pdf</a>	Immediate	<a href="#">R40-3003502</a>	<a href="#">R40-300.pdf</a>

## Obsolete Product Notification from Harwin

Part number being made obsolete	Drawing for obsolete product	Last Time buy date	Alternative product	Drawing for alternative product
R50-3004002	<a href="#">R50-300_obsolete.pdf</a>	Immediate	<a href="#">R40-3003502</a>	<a href="#">R40-300.pdf</a>
R50-3005002	<a href="#">R50-300_obsolete.pdf</a>	Immediate	<a href="#">R40-3003502</a>	<a href="#">R40-300.pdf</a>
S4011-46	<a href="#">S4011_obsolete.pdf</a>	28th September 2018	Contact technical@harwin.com	
W2222-00	<a href="#">W2222_obsolete.pdf</a>	26th October 2018	Contact technical@harwin.com	
W2231-00	<a href="#">W2231_obsolete.pdf</a>	Immediate	Contact technical@harwin.com	
W2232-00	<a href="#">W2232_obsolete.pdf</a>	Immediate	Contact technical@harwin.com	
W2330-00	<a href="#">W2330_obsolete.pdf</a>	26th October 2018	Contact technical@harwin.com	
W2331-00	<a href="#">W2331_obsolete.pdf</a>	26th October 2018	Contact technical@harwin.com	
W2332-00	<a href="#">W2332_obsolete.pdf</a>	26th October 2018	Contact technical@harwin.com	
W2531-00	<a href="#">W2531_obsolete.pdf</a>	Immediate	Contact technical@harwin.com	
Z1001-00	<a href="#">Z1001_obsolete.pdf</a>	26th October 2018	Contact technical@harwin.com	
Z125-9250600	Contact technical@harwin.com	Immediate	<a href="#">Z125-9260600</a>	<a href="#">Z125-926.pdf</a>
Z125-9251000	Contact technical@harwin.com	Immediate	<a href="#">Z125-9261000</a>	<a href="#">Z125-926.pdf</a>
Z125-9251200	Contact technical@harwin.com	Immediate	<a href="#">Z125-9261200</a>	<a href="#">Z125-926.pdf</a>
Z125-9251600	Contact technical@harwin.com	Immediate	<a href="#">Z125-9261600</a>	<a href="#">Z125-926.pdf</a>
Z125-9252000	Contact technical@harwin.com	Immediate	<a href="#">Z125-9262000</a>	<a href="#">Z125-926.pdf</a>
Z125-9252600	Contact technical@harwin.com	Immediate	<a href="#">Z125-9262600</a>	<a href="#">Z125-926.pdf</a>
Z125-9253400	Contact technical@harwin.com	Immediate	<a href="#">Z125-9263400</a>	<a href="#">Z125-926.pdf</a>
Z125-9255000	Contact technical@harwin.com	Immediate	<a href="#">Z125-9265000</a>	<a href="#">Z125-926.pdf</a>