



Harwin plc
Fitzherbert Road
Farlington, Portsmouth
Hampshire PO6 1RT
United Kingdom

Reception: +44 (0)23 9231 4545
Sales Desk: +44 (0)23 9237 0451

Thursday 31st January, 2019

Dear Customer,

Re: Obsolescence notification for Harwin product.

Please be advised that the following ranges are now obsolete with immediate effect:

- M402VF-3-038-05NR
- M80-402xxxxP – all products ending in P
- M80-412xxxxP – all products ending in P
- M80-422xxxxP – all products ending in P

Please see the following spreadsheet for a detailed list of affected items:

https://cdn.harwin.com/pdfs/Obsolescence_notification_spreadsheet_2019_01_31.xlsx

Unfortunately, we are no longer able to support these product lines. Alternative items are available for some items; please see the attached spreadsheet for the alternative part numbers.

If you have any further questions regarding this letter, please do not hesitate to contact us.

Yours faithfully,

The Product Change Team

technical@harwin.com

Obsolete Product Notification from Harwin

Part number being made obsolete	Drawing for obsolete product	Last Time buy date	Alternative product	Drawing for alternative product
M402VF-3-038-05NR	M402VF.pdf	Immediate	full part number	M402VF.pdf
M80-4020405P	M80-402P_obsolete.pdf	Immediate	M80-4020405	M80-402.pdf
M80-4020442P	M80-402P_obsolete.pdf	Immediate	M80-4020442	M80-402.pdf
M80-4020601P	M80-402P_obsolete.pdf	Immediate	M80-4020642	M80-402.pdf
M80-4020605P	M80-402P_obsolete.pdf	Immediate	M80-4020605	M80-402.pdf
M80-4020642P	M80-402P_obsolete.pdf	Immediate	M80-4020642	M80-402.pdf
M80-4020805P	M80-402P_obsolete.pdf	Immediate	M80-4020805	M80-402.pdf
M80-4020842P	M80-402P_obsolete.pdf	Immediate	M80-4020842	M80-402.pdf
M80-4021001P	M80-402P_obsolete.pdf	Immediate	M80-4021042	M80-402.pdf
M80-4021005P	M80-402P_obsolete.pdf	Immediate	M80-4021005	M80-402.pdf
M80-4021042P	M80-402P_obsolete.pdf	Immediate	M80-4021042	M80-402.pdf
M80-4021401P	M80-402P_obsolete.pdf	Immediate	M80-4021442	M80-402.pdf
M80-4021405P	M80-402P_obsolete.pdf	Immediate	M80-4021405	M80-402.pdf
M80-4021442P	M80-402P_obsolete.pdf	Immediate	M80-4021442	M80-402.pdf
M80-4022001P	M80-402P_obsolete.pdf	Immediate	M80-4022042	M80-402.pdf
M80-4022005P	M80-402P_obsolete.pdf	Immediate	M80-4022005	M80-402.pdf
M80-4022042P	M80-402P_obsolete.pdf	Immediate	M80-4022042	M80-402.pdf
M80-4022601P	M80-402P_obsolete.pdf	Immediate	M80-4022642	M80-402.pdf
M80-4022605P	M80-402P_obsolete.pdf	Immediate	M80-4022605	M80-402.pdf
M80-4022642P	M80-402P_obsolete.pdf	Immediate	M80-4022642	M80-402.pdf
M80-4023401P	M80-402P_obsolete.pdf	Immediate	M80-4023442	M80-402.pdf
M80-4023405P	M80-402P_obsolete.pdf	Immediate	M80-4023405	M80-402.pdf
M80-4023442P	M80-402P_obsolete.pdf	Immediate	M80-4023442	M80-402.pdf
M80-4024201P	M80-402P_obsolete.pdf	Immediate	M80-4024242	M80-402.pdf
M80-4024205P	M80-402P_obsolete.pdf	Immediate	M80-4024205	M80-402.pdf
M80-4024242P	M80-402P_obsolete.pdf	Immediate	M80-4024242	M80-402.pdf
M80-4025001P	M80-402P_obsolete.pdf	Immediate	M80-4025042	M80-402.pdf
M80-4025005P	M80-402P_obsolete.pdf	Immediate	M80-4025005	M80-402.pdf
M80-4025042P	M80-402P_obsolete.pdf	Immediate	M80-4025042	M80-402.pdf
M80-4120601P	M80-412P_obsolete.pdf	Immediate	M80-4120642	M80-412.pdf
M80-4120605P	M80-412P_obsolete.pdf	Immediate	M80-4120605	M80-412.pdf
M80-4120642P	M80-412P_obsolete.pdf	Immediate	M80-4120642	M80-412.pdf
M80-4121001P	M80-412P_obsolete.pdf	Immediate	M80-4121042	M80-412.pdf
M80-4121005P	M80-412P_obsolete.pdf	Immediate	M80-4121005	M80-412.pdf
M80-4121042P	M80-412P_obsolete.pdf	Immediate	M80-4121042	M80-412.pdf
M80-4121401P	M80-412P_obsolete.pdf	Immediate	M80-4121442	M80-412.pdf
M80-4121405P	M80-412P_obsolete.pdf	Immediate	M80-4121405	M80-412.pdf
M80-4121442P	M80-412P_obsolete.pdf	Immediate	M80-4121442	M80-412.pdf
M80-4122001P	M80-412P_obsolete.pdf	Immediate	M80-4122042	M80-412.pdf
M80-4122005P	M80-412P_obsolete.pdf	Immediate	M80-4122005	M80-412.pdf
M80-4122042P	M80-412P_obsolete.pdf	Immediate	M80-4122042	M80-412.pdf
M80-4122601P	M80-412P_obsolete.pdf	Immediate	M80-4122642	M80-412.pdf
M80-4122605P	M80-412P_obsolete.pdf	Immediate	M80-4122605	M80-412.pdf
M80-4122642P	M80-412P_obsolete.pdf	Immediate	M80-4122642	M80-412.pdf
M80-4123401P	M80-412P_obsolete.pdf	Immediate	M80-4123442	M80-412.pdf
M80-4123405P	M80-412P_obsolete.pdf	Immediate	M80-4123405	M80-412.pdf
M80-4123442P	M80-412P_obsolete.pdf	Immediate	M80-4123442	M80-412.pdf
M80-4124201P	M80-412P_obsolete.pdf	Immediate	M80-4124242	M80-412.pdf
M80-4124205P	M80-412P_obsolete.pdf	Immediate	M80-4124205	M80-412.pdf
M80-4124242P	M80-412P_obsolete.pdf	Immediate	M80-4124242	M80-412.pdf
M80-4125001P	M80-412P_obsolete.pdf	Immediate	M80-4125042	M80-412.pdf
M80-4125005P	M80-412P_obsolete.pdf	Immediate	M80-4125005	M80-412.pdf
M80-4125042P	M80-412P_obsolete.pdf	Immediate	M80-4125042	M80-412.pdf
M80-4220401P	M80-422.pdf	Immediate	M80-4220442	M80-422.pdf
M80-4220405P	M80-422.pdf	Immediate	M80-4220405	M80-422.pdf
M80-4220442P	M80-422.pdf	Immediate	M80-4220442	M80-422.pdf
M80-4220601P	M80-422.pdf	Immediate	M80-4220642	M80-422.pdf
M80-4220605P	M80-422.pdf	Immediate	M80-4220605	M80-422.pdf
M80-4220642P	M80-422.pdf	Immediate	M80-4220642	M80-422.pdf
M80-4220801P	M80-422.pdf	Immediate	M80-4220842	M80-422.pdf
M80-4220805P	M80-422.pdf	Immediate	M80-4220805	M80-422.pdf
M80-4220842P	M80-422.pdf	Immediate	M80-4220842	M80-422.pdf
M80-4221001P	M80-422.pdf	Immediate	M80-4221042	M80-422.pdf
M80-4221005P	M80-422.pdf	Immediate	M80-4221005	M80-422.pdf
M80-4221042P	M80-422.pdf	Immediate	M80-4221042	M80-422.pdf
M80-4221201P	M80-422.pdf	Immediate	M80-4221242	M80-422.pdf
M80-4221205P	M80-422.pdf	Immediate	M80-4221205	M80-422.pdf

Obsolete Product Notification from Harwin

Part number being made obsolete	Drawing for obsolete product	Last Time buy date	Alternative product	Drawing for alternative product
M80-4221242P	M80-422.pdf	Immediate	M80-4221242	M80-422.pdf
M80-4221401P	M80-422.pdf	Immediate	M80-4221442	M80-422.pdf
M80-4221405P	M80-422.pdf	Immediate	M80-4221405	M80-422.pdf
M80-4221442P	M80-422.pdf	Immediate	M80-4221442	M80-422.pdf
M80-4221601P	M80-422.pdf	Immediate	M80-4221642	M80-422.pdf
M80-4221605P	M80-422.pdf	Immediate	M80-4221605	M80-422.pdf
M80-4221642P	M80-422.pdf	Immediate	M80-4221642	M80-422.pdf
M80-4221801P	M80-422.pdf	Immediate	M80-4221842	M80-422.pdf
M80-4221805P	M80-422.pdf	Immediate	M80-4221805	M80-422.pdf
M80-4221842P	M80-422.pdf	Immediate	M80-4221842	M80-422.pdf
M80-4222001P	M80-422.pdf	Immediate	M80-4222042	M80-422.pdf
M80-4222005P	M80-422.pdf	Immediate	M80-4222005	M80-422.pdf
M80-4222042P	M80-422.pdf	Immediate	M80-4222042	M80-422.pdf
M80-4222201P	M80-422.pdf	Immediate	M80-4222242	M80-422.pdf
M80-4222205P	M80-422.pdf	Immediate	M80-4222205	M80-422.pdf
M80-4222242P	M80-422.pdf	Immediate	M80-4222242	M80-422.pdf
M80-4222401P	M80-422.pdf	Immediate	M80-4222442	M80-422.pdf
M80-4222405P	M80-422.pdf	Immediate	M80-4222405	M80-422.pdf
M80-4222442P	M80-422.pdf	Immediate	M80-4222442	M80-422.pdf
M80-4222601P	M80-422.pdf	Immediate	M80-4222642	M80-422.pdf
M80-4222605P	M80-422.pdf	Immediate	M80-4222605	M80-422.pdf
M80-4222642P	M80-422.pdf	Immediate	M80-4222642	M80-422.pdf
M80-4222801P	M80-422.pdf	Immediate	M80-4222842	M80-422.pdf
M80-4222805P	M80-422.pdf	Immediate	M80-4222805	M80-422.pdf
M80-4222842P	M80-422.pdf	Immediate	M80-4222842	M80-422.pdf
M80-4223001P	M80-422.pdf	Immediate	M80-4223042	M80-422.pdf
M80-4223005P	M80-422.pdf	Immediate	M80-4223005	M80-422.pdf
M80-4223042P	M80-422.pdf	Immediate	M80-4223042	M80-422.pdf
M80-4223201P	M80-422.pdf	Immediate	M80-4223242	M80-422.pdf
M80-4223205P	M80-422.pdf	Immediate	M80-4223205	M80-422.pdf
M80-4223242P	M80-422.pdf	Immediate	M80-4223242	M80-422.pdf
M80-4223401P	M80-422.pdf	Immediate	M80-4223442	M80-422.pdf
M80-4223405P	M80-422.pdf	Immediate	M80-4223405	M80-422.pdf
M80-4223442P	M80-422.pdf	Immediate	M80-4223442	M80-422.pdf
M80-4223601P	M80-422.pdf	Immediate	M80-4223642	M80-422.pdf
M80-4223605P	M80-422.pdf	Immediate	M80-4223605	M80-422.pdf
M80-4223642P	M80-422.pdf	Immediate	M80-4223642	M80-422.pdf
M80-4223801P	M80-422.pdf	Immediate	M80-4223842	M80-422.pdf
M80-4223805P	M80-422.pdf	Immediate	M80-4223805	M80-422.pdf
M80-4223842P	M80-422.pdf	Immediate	M80-4223842	M80-422.pdf
M80-4224001P	M80-422.pdf	Immediate	M80-4224042	M80-422.pdf
M80-4224005P	M80-422.pdf	Immediate	M80-4224005	M80-422.pdf
M80-4224042P	M80-422.pdf	Immediate	M80-4224042	M80-422.pdf
M80-4224201P	M80-422.pdf	Immediate	M80-4224242	M80-422.pdf
M80-4224205P	M80-422.pdf	Immediate	M80-4224205	M80-422.pdf
M80-4224242P	M80-422.pdf	Immediate	M80-4224242	M80-422.pdf
M80-4224401P	M80-422.pdf	Immediate	M80-4224442	M80-422.pdf
M80-4224405P	M80-422.pdf	Immediate	M80-4224405	M80-422.pdf
M80-4224442P	M80-422.pdf	Immediate	M80-4224442	M80-422.pdf
M80-4224601P	M80-422.pdf	Immediate	M80-4224642	M80-422.pdf
M80-4224605P	M80-422.pdf	Immediate	M80-4224605	M80-422.pdf
M80-4224642P	M80-422.pdf	Immediate	M80-4224642	M80-422.pdf
M80-4224801P	M80-422.pdf	Immediate	M80-4224842	M80-422.pdf
M80-4224805P	M80-422.pdf	Immediate	M80-4224805	M80-422.pdf
M80-4224842P	M80-422.pdf	Immediate	M80-4224842	M80-422.pdf
M80-4225001P	M80-422.pdf	Immediate	M80-4225042	M80-422.pdf
M80-4225005P	M80-422.pdf	Immediate	M80-4225005	M80-422.pdf
M80-4225042P	M80-422.pdf	Immediate	M80-4225042	M80-422.pdf