



Harwin plc
Fitzherbert Road
Farlington, Portsmouth
Hampshire PO6 1RT
United Kingdom

Reception: +44 (0)23 9231 4545
Sales Desk: +44 (0)23 9237 0451

Thursday 5th May, 2022

Dear Customer,

Re: Obsolescence notification for Harwin product.

Please be advised that the following part numbers are now obsolete with immediate effect. Unfortunately, we are no longer able to support this packing variation on these product ranges.

- M40-302xx46 (loose or strip)
- **NOTE: M40-302xx46R products are not affected, and are still available**

The following part numbers are now obsolete with with immediate effect. Unfortunately, we are no longer able to support this product.

- M22-221xx46

Please see the following spreadsheet for a detailed list of affected items and their suggested alternatives:

https://cdn.harwin.com/pdfs/Obsolescence_notification_spreadsheet_2022-05-05.xlsx

If you have any further questions regarding this letter, please do not hesitate to contact us.

Yours faithfully,

The Product Change Team
technical@harwin.com

Obsolete Product Notification from Harwin

Part number being made obsolete	Drawing for obsolete product	Last Time buy date	Alternative product	Drawing for alternative product
M22-2210246	M22-221_obsolete.pdf	Immediate	M22-2200246	M22-220.pdf
M22-2210846	M22-221_obsolete.pdf	Immediate	M22-2030846	M22-203.pdf
M40-3020546	M40-302_obsolete.pdf	Immediate	M40-3020546R	M40-302R.pdf
M40-3020646	M40-302_obsolete.pdf	Immediate	M40-3020646R	M40-302R.pdf
M40-3020746	M40-302_obsolete.pdf	Immediate	M40-3020746R	M40-302R.pdf
M40-3020846	M40-302_obsolete.pdf	Immediate	M40-3020846R	M40-302R.pdf
M40-3021046	M40-302_obsolete.pdf	Immediate	M40-3021046R	M40-302R.pdf
M40-3021246	M40-302_obsolete.pdf	Immediate	M40-3021246R	M40-302R.pdf
M40-3021546	M40-302_obsolete.pdf	Immediate	M40-3021546R	M40-302R.pdf