



May 18, 2011

Dear Customer,

Please be advised that with immediate effect we will no longer be able to supply the following components:

M509-5391142

We are informing you of this change because you have either purchased this product from us in the past or you are on our Product Change Notification circulation list.

If you have any questions, do please contact me at the e-mail address below.

Yours sincerely,

A handwritten signature in black ink, which appears to read 'Wendy Bourne', is shown on a light grey background.

Wendy Jane Bourne, BEng
Technical Marketing Engineer
technical@harwin.co.uk