



Harwin plc
Fitzherbert Road
Farlington, Portsmouth
Hampshire PO6 1RT
United Kingdom

Reception: +44 (0)23 9231 4545
Sales Desk: +44 (0)23 9237 0451
Fax: +44 (0)23 9231 4590

Monday 25th July, 2016

Dear Customer,

Re: Product Change Notification for Harwin product.

As part of our continuous product improvement program, Harwin has corrected the plating finish and updated M80-5T12005M2-02-331-02-331 – 2mm pitch Datamate Mix-Tek Male Connector.

The changes involved were as follows:

- Previously, although the part number specified an all-gold finish on the male signal pins, the product had been specified on the Technical Drawing as Gold on the contact area, Tin on the tails. This has now been corrected back to the all-gold finish on the drawing – all future builds of this product will be all-gold.
- The packing has been changed from individual packs to tubes. The Technical Drawing had previously stated Trays – this has been corrected.
- The board mount nuts are now supplied not assembled to the product.
- Other minor changes have been carried out to bring the drawing specification in line with the latest [Component Specification for Datamate](#).

If you have any further questions regarding this letter, please do not hesitate to contact us.

Yours faithfully,

The Product Management Team
technical@harwin.com