



Harwin plc
Fitzherbert Road
Farlington, Portsmouth
Hampshire PO6 1RT
United Kingdom

Reception: +44 (0)23 9231 4545
Sales Desk: +44 (0)23 9237 0451
Fax: +44 (0)23 9231 4590

Monday 5th November, 2012

Dear Customer,

Re: Obsolescence notification for Harwin product.

Please be advised that the following Female Horizontal Datamate products are now obsolete with immediate effect. Some existing stock is available, and will be available until stocks are exhausted. Please contact quote@harwin.co.uk if you wish to purchase any of the existing stock.

- M80-430xxxx
- M80-431xxxx
- M80-435xxxx
- M80-436xxxx
- M80-440xxxx
- M80-441xxxx
- M80-445xxxx
- M80-446xxxx

Please see the attached spreadsheet for a complete list of affected items. Unfortunately, we are no longer able to support these product lines.

If you have any further questions regarding this letter, please do not hesitate to contact us.

Yours faithfully,

The Product Management Team
technical@harwin.com

Obsolete Product Notification from Harwin

Part number being made obsolete	Last Time Buy date
M80-4300605	Immediate
M80-4300622	Immediate
M80-4300642	Immediate
M80-4300805	Immediate
M80-4300822	Immediate
M80-4300842	Immediate
M80-4301005	Immediate
M80-4301022	Immediate
M80-4301042	Immediate
M80-4301205	Immediate
M80-4301222	Immediate
M80-4301242	Immediate
M80-4301405	Immediate
M80-4301422	Immediate
M80-4301442	Immediate
M80-4302005	Immediate
M80-4302022	Immediate
M80-4302042	Immediate
M80-4302605	Immediate
M80-4302622	Immediate
M80-4302642	Immediate
M80-4303405	Immediate
M80-4303422	Immediate
M80-4303442	Immediate
M80-4310605	Immediate
M80-4310622	Immediate
M80-4310642	Immediate
M80-4310805	Immediate
M80-4310822	Immediate
M80-4310842	Immediate
M80-4311005	Immediate
M80-4311022	Immediate
M80-4311042	Immediate
M80-4311205	Immediate
M80-4311222	Immediate
M80-4311242	Immediate
M80-4311405	Immediate
M80-4311422	Immediate
M80-4311442	Immediate
M80-4312005	Immediate
M80-4312022	Immediate
M80-4312042	Immediate
M80-4312605	Immediate
M80-4312622	Immediate
M80-4312642	Immediate
M80-4313405	Immediate
M80-4313422	Immediate
M80-4313442	Immediate
M80-4350605	Immediate
M80-4350622	Immediate
M80-4350642	Immediate
M80-4350805	Immediate

Obsolete Product Notification from Harwin

Part number being made obsolete	Last Time Buy date
M80-4350822	Immediate
M80-4350842	Immediate
M80-4351005	Immediate
M80-4351022	Immediate
M80-4351042	Immediate
M80-4351205	Immediate
M80-4351222	Immediate
M80-4351242	Immediate
M80-4351405	Immediate
M80-4351422	Immediate
M80-4351442	Immediate
M80-4352005	Immediate
M80-4352022	Immediate
M80-4352042	Immediate
M80-4352605	Immediate
M80-4352622	Immediate
M80-4352642	Immediate
M80-4353405	Immediate
M80-4353422	Immediate
M80-4353442	Immediate
M80-4360605	Immediate
M80-4360622	Immediate
M80-4360642	Immediate
M80-4360805	Immediate
M80-4360822	Immediate
M80-4360842	Immediate
M80-4361005	Immediate
M80-4361022	Immediate
M80-4361042	Immediate
M80-4361205	Immediate
M80-4361222	Immediate
M80-4361242	Immediate
M80-4361405	Immediate
M80-4361422	Immediate
M80-4361442	Immediate
M80-4362005	Immediate
M80-4362022	Immediate
M80-4362042	Immediate
M80-4362605	Immediate
M80-4362622	Immediate
M80-4362642	Immediate
M80-4363405	Immediate
M80-4363422	Immediate
M80-4363442	Immediate
M80-4400605	Immediate
M80-4400622	Immediate
M80-4400642	Immediate
M80-4400805	Immediate
M80-4400822	Immediate
M80-4400842	Immediate
M80-4401005	Immediate
M80-4401022	Immediate

Obsolete Product Notification from Harwin

Part number being made obsolete	Last Time Buy date
M80-4401042	Immediate
M80-4401205	Immediate
M80-4401222	Immediate
M80-4401242	Immediate
M80-4401405	Immediate
M80-4401422	Immediate
M80-4401442	Immediate
M80-4402005	Immediate
M80-4402022	Immediate
M80-4402042	Immediate
M80-4402605	Immediate
M80-4402622	Immediate
M80-4402642	Immediate
M80-4403405	Immediate
M80-4403422	Immediate
M80-4403442	Immediate
M80-4410605	Immediate
M80-4410622	Immediate
M80-4410642	Immediate
M80-4410805	Immediate
M80-4410822	Immediate
M80-4410842	Immediate
M80-4411005	Immediate
M80-4411022	Immediate
M80-4411042	Immediate
M80-4411205	Immediate
M80-4411222	Immediate
M80-4411242	Immediate
M80-4411405	Immediate
M80-4411422	Immediate
M80-4411442	Immediate
M80-4412005	Immediate
M80-4412022	Immediate
M80-4412042	Immediate
M80-4412605	Immediate
M80-4412622	Immediate
M80-4412642	Immediate
M80-4413405	Immediate
M80-4413422	Immediate
M80-4413442	Immediate
M80-4450605	Immediate
M80-4450622	Immediate
M80-4450642	Immediate
M80-4450805	Immediate
M80-4450822	Immediate
M80-4450842	Immediate
M80-4451005	Immediate
M80-4451022	Immediate
M80-4451042	Immediate
M80-4451205	Immediate
M80-4451222	Immediate
M80-4451242	Immediate

Obsolete Product Notification from Harwin

Part number being made obsolete	Last Time Buy date
M80-4451405	Immediate
M80-4451422	Immediate
M80-4451442	Immediate
M80-4452005	Immediate
M80-4452022	Immediate
M80-4452042	Immediate
M80-4452605	Immediate
M80-4452622	Immediate
M80-4452642	Immediate
M80-4453405	Immediate
M80-4453422	Immediate
M80-4453442	Immediate
M80-4460605	Immediate
M80-4460622	Immediate
M80-4460642	Immediate
M80-4460805	Immediate
M80-4460822	Immediate
M80-4460842	Immediate
M80-4461005	Immediate
M80-4461022	Immediate
M80-4461042	Immediate
M80-4461205	Immediate
M80-4461222	Immediate
M80-4461242	Immediate
M80-4461405	Immediate
M80-4461422	Immediate
M80-4461442	Immediate
M80-4462005	Immediate
M80-4462022	Immediate
M80-4462042	Immediate
M80-4462605	Immediate
M80-4462622	Immediate
M80-4462642	Immediate
M80-4463405	Immediate
M80-4463422	Immediate
M80-4463442	Immediate