



Harwin plc
Fitzherbert Road
Farlington, Portsmouth
Hampshire PO6 1RT
United Kingdom

Reception: +44 (0)23 9231 4545
Sales Desk: +44 (0)23 9237 0451
Fax: +44 (0)23 9231 4590

Wednesday 9th July, 2014

Dear Customer,

Re: Obsolescence notification for Harwin product.

Please be advised that there are a number of ranges and individual items that are now obsolete. Some are with immediate effect, and some are with a last time buy date of 9th October, 2014. Please see the attached spreadsheet (that has 2 pages) for a complete list of affected items. The larger ranges that may be of most interest are:

- M20-960 and M20-961 series (2.54mm pitch extended pin headers)
- M22-265, M22-266, M22-267, M22-268 series (2mm pitch extended pin headers)
- S505 and S506 series

Unfortunately, we are no longer able to support these product lines. Alternative items are available in some cases; please see the attached spreadsheet for the alternative part numbers. In particular, identical pin headers to the obsolete standard extended ones can be supplied – by using the Pin Header Variant numbering. Details are in the spreadsheet.

If you have any further questions regarding this letter, please do not hesitate to contact us.

Yours faithfully,

The Product Management Team
technical@harwin.com

Obsolete Product Notification from Harwin - Standard

Part number being made obsolete	Drawing for obsolete product	Last Time Buy?	Alternative product	Drawing for alternative product
R4351-02	R4351-R4354 obsolete.pdf	No - immediate	No alternative	
R4352-02	R4351-R4354 obsolete.pdf	No - immediate	No alternative	
R4353-02	R4351-R4354 obsolete.pdf	No - immediate	No alternative	
R4354-02	R4351-R4354 obsolete.pdf	No - immediate	No alternative	
S505-46	S505 obsolete.pdf	No - immediate	No alternative	
S506-46	S505 obsolete.pdf	No - immediate	No alternative	
M20-9600245	M20-960 obsolete.pdf	Until 9th Oct 2014	M20-072168F0245	HF159-F.pdf
M20-9600246	M20-960 obsolete.pdf	Until 9th Oct 2014	M20-072168F0246	HF159-F.pdf
M20-9600345	M20-960 obsolete.pdf	Until 9th Oct 2014	M20-072168F0345	HF159-F.pdf
M20-9600346	M20-960 obsolete.pdf	Until 9th Oct 2014	M20-072168F0346	HF159-F.pdf
M20-9600445	M20-960 obsolete.pdf	Until 9th Oct 2014	M20-072168F0445	HF159-F.pdf
M20-9600446	M20-960 obsolete.pdf	Until 9th Oct 2014	M20-072168F0446	HF159-F.pdf
M20-9600545	M20-960 obsolete.pdf	Until 9th Oct 2014	M20-072168F0545	HF159-F.pdf
M20-9600546	M20-960 obsolete.pdf	Until 9th Oct 2014	M20-072168F0546	HF159-F.pdf
M20-9600645	M20-960 obsolete.pdf	Until 9th Oct 2014	M20-072168F0645	HF159-F.pdf
M20-9600646	M20-960 obsolete.pdf	Until 9th Oct 2014	M20-072168F0646	HF159-F.pdf
M20-9600745	M20-960 obsolete.pdf	Until 9th Oct 2014	M20-072168F0745	HF159-F.pdf
M20-9600746	M20-960 obsolete.pdf	Until 9th Oct 2014	M20-072168F0746	HF159-F.pdf
M20-9600845	M20-960 obsolete.pdf	Until 9th Oct 2014	M20-072168F0845	HF159-F.pdf
M20-9600846	M20-960 obsolete.pdf	Until 9th Oct 2014	M20-072168F0846	HF159-F.pdf
M20-9600945	M20-960 obsolete.pdf	Until 9th Oct 2014	M20-072168F0945	HF159-F.pdf
M20-9600946	M20-960 obsolete.pdf	Until 9th Oct 2014	M20-072168F0946	HF159-F.pdf
M20-9601045	M20-960 obsolete.pdf	Until 9th Oct 2014	M20-072168F1045	HF159-F.pdf
M20-9601046	M20-960 obsolete.pdf	Until 9th Oct 2014	M20-072168F1046	HF159-F.pdf
M20-9601145	M20-960 obsolete.pdf	Until 9th Oct 2014	M20-072168F1145	HF159-F.pdf
M20-9601146	M20-960 obsolete.pdf	Until 9th Oct 2014	M20-072168F1146	HF159-F.pdf
M20-9601245	M20-960 obsolete.pdf	Until 9th Oct 2014	M20-072168F1245	HF159-F.pdf
M20-9601246	M20-960 obsolete.pdf	Until 9th Oct 2014	M20-072168F1246	HF159-F.pdf
M20-9601345	M20-960 obsolete.pdf	Until 9th Oct 2014	M20-072168F1345	HF159-F.pdf
M20-9601346	M20-960 obsolete.pdf	Until 9th Oct 2014	M20-072168F1346	HF159-F.pdf
M20-9601445	M20-960 obsolete.pdf	Until 9th Oct 2014	M20-072168F1445	HF159-F.pdf
M20-9601446	M20-960 obsolete.pdf	Until 9th Oct 2014	M20-072168F1446	HF159-F.pdf
M20-9601545	M20-960 obsolete.pdf	Until 9th Oct 2014	M20-072168F1545	HF159-F.pdf
M20-9601546	M20-960 obsolete.pdf	Until 9th Oct 2014	M20-072168F1546	HF159-F.pdf
M20-9601645	M20-960 obsolete.pdf	Until 9th Oct 2014	M20-072168F1645	HF159-F.pdf
M20-9601646	M20-960 obsolete.pdf	Until 9th Oct 2014	M20-072168F1646	HF159-F.pdf
M20-9601745	M20-960 obsolete.pdf	Until 9th Oct 2014	M20-072168F1745	HF159-F.pdf
M20-9601746	M20-960 obsolete.pdf	Until 9th Oct 2014	M20-072168F1746	HF159-F.pdf
M20-9601845	M20-960 obsolete.pdf	Until 9th Oct 2014	M20-072168F1845	HF159-F.pdf
M20-9601846	M20-960 obsolete.pdf	Until 9th Oct 2014	M20-072168F1846	HF159-F.pdf
M20-9601945	M20-960 obsolete.pdf	Until 9th Oct 2014	M20-072168F1945	HF159-F.pdf
M20-9601946	M20-960 obsolete.pdf	Until 9th Oct 2014	M20-072168F1946	HF159-F.pdf
M20-9602045	M20-960 obsolete.pdf	Until 9th Oct 2014	M20-072168F2045	HF159-F.pdf
M20-9602046	M20-960 obsolete.pdf	Until 9th Oct 2014	M20-072168F2046	HF159-F.pdf
M20-9602145	M20-960 obsolete.pdf	Until 9th Oct 2014	M20-072168F2145	HF159-F.pdf
M20-9602146	M20-960 obsolete.pdf	Until 9th Oct 2014	M20-072168F2146	HF159-F.pdf
M20-9602245	M20-960 obsolete.pdf	Until 9th Oct 2014	M20-072168F2245	HF159-F.pdf
M20-9602246	M20-960 obsolete.pdf	Until 9th Oct 2014	M20-072168F2246	HF159-F.pdf
M20-9602345	M20-960 obsolete.pdf	Until 9th Oct 2014	M20-072168F2345	HF159-F.pdf
M20-9602346	M20-960 obsolete.pdf	Until 9th Oct 2014	M20-072168F2346	HF159-F.pdf
M20-9602445	M20-960 obsolete.pdf	Until 9th Oct 2014	M20-072168F2445	HF159-F.pdf
M20-9602446	M20-960 obsolete.pdf	Until 9th Oct 2014	M20-072168F2446	HF159-F.pdf
M20-9602545	M20-960 obsolete.pdf	Until 9th Oct 2014	M20-072168F2545	HF159-F.pdf
M20-9602546	M20-960 obsolete.pdf	Until 9th Oct 2014	M20-072168F2546	HF159-F.pdf
M20-9602645	M20-960 obsolete.pdf	Until 9th Oct 2014	M20-072168F2645	HF159-F.pdf
M20-9602646	M20-960 obsolete.pdf	Until 9th Oct 2014	M20-072168F2646	HF159-F.pdf
M20-9602745	M20-960 obsolete.pdf	Until 9th Oct 2014	M20-072168F2745	HF159-F.pdf
M20-9602746	M20-960 obsolete.pdf	Until 9th Oct 2014	M20-072168F2746	HF159-F.pdf
M20-9602845	M20-960 obsolete.pdf	Until 9th Oct 2014	M20-072168F2845	HF159-F.pdf
M20-9602846	M20-960 obsolete.pdf	Until 9th Oct 2014	M20-072168F2846	HF159-F.pdf
M20-9602945	M20-960 obsolete.pdf	Until 9th Oct 2014	M20-072168F2945	HF159-F.pdf
M20-9602946	M20-960 obsolete.pdf	Until 9th Oct 2014	M20-072168F2946	HF159-F.pdf

Obsolete Product Notification from Harwin - Standard

[illegible]

Obsolete Product Notification from Harwin - Standard

Part number being made obsolete	Drawing for obsolete product	Last Time Buy?	Alternative product	Drawing for alternative product
M20-9612245	M20-961_obsolete.pdf	Until 9th Oct 2014	M20-072168E2245	HF159-E.pdf
M20-9612246	M20-961_obsolete.pdf	Until 9th Oct 2014	M20-072168E2246	HF159-E.pdf
M20-9612345	M20-961_obsolete.pdf	Until 9th Oct 2014	M20-072168E2345	HF159-E.pdf
M20-9612346	M20-961_obsolete.pdf	Until 9th Oct 2014	M20-072168E2346	HF159-E.pdf
M20-9612445	M20-961_obsolete.pdf	Until 9th Oct 2014	M20-072168E2445	HF159-E.pdf
M20-9612446	M20-961_obsolete.pdf	Until 9th Oct 2014	M20-072168E2446	HF159-E.pdf
M20-9612545	M20-961_obsolete.pdf	Until 9th Oct 2014	M20-072168E2545	HF159-E.pdf
M20-9612546	M20-961_obsolete.pdf	Until 9th Oct 2014	M20-072168E2546	HF159-E.pdf
M20-9612645	M20-961_obsolete.pdf	Until 9th Oct 2014	M20-072168E2645	HF159-E.pdf
M20-9612646	M20-961_obsolete.pdf	Until 9th Oct 2014	M20-072168E2646	HF159-E.pdf
M20-9612745	M20-961_obsolete.pdf	Until 9th Oct 2014	M20-072168E2745	HF159-E.pdf
M20-9612746	M20-961_obsolete.pdf	Until 9th Oct 2014	M20-072168E2746	HF159-E.pdf
M20-9612845	M20-961_obsolete.pdf	Until 9th Oct 2014	M20-072168E2845	HF159-E.pdf
M20-9612846	M20-961_obsolete.pdf	Until 9th Oct 2014	M20-072168E2846	HF159-E.pdf
M20-9612945	M20-961_obsolete.pdf	Until 9th Oct 2014	M20-072168E2945	HF159-E.pdf
M20-9612946	M20-961_obsolete.pdf	Until 9th Oct 2014	M20-072168E2946	HF159-E.pdf
M20-9613045	M20-961_obsolete.pdf	Until 9th Oct 2014	M20-072168E3045	HF159-E.pdf
M20-9613046	M20-961_obsolete.pdf	Until 9th Oct 2014	M20-072168E3046	HF159-E.pdf
M20-9613145	M20-961_obsolete.pdf	Until 9th Oct 2014	M20-072168E3145	HF159-E.pdf
M20-9613146	M20-961_obsolete.pdf	Until 9th Oct 2014	M20-072168E3146	HF159-E.pdf
M20-9613245	M20-961_obsolete.pdf	Until 9th Oct 2014	M20-072168E3245	HF159-E.pdf
M20-9613246	M20-961_obsolete.pdf	Until 9th Oct 2014	M20-072168E3246	HF159-E.pdf
M20-9613345	M20-961_obsolete.pdf	Until 9th Oct 2014	M20-072168E3345	HF159-E.pdf
M20-9613346	M20-961_obsolete.pdf	Until 9th Oct 2014	M20-072168E3346	HF159-E.pdf
M20-9613445	M20-961_obsolete.pdf	Until 9th Oct 2014	M20-072168E3445	HF159-E.pdf
M20-9613446	M20-961_obsolete.pdf	Until 9th Oct 2014	M20-072168E3446	HF159-E.pdf
M20-9613545	M20-961_obsolete.pdf	Until 9th Oct 2014	M20-072168E3545	HF159-E.pdf
M20-9613546	M20-961_obsolete.pdf	Until 9th Oct 2014	M20-072168E3546	HF159-E.pdf
M20-9613645	M20-961_obsolete.pdf	Until 9th Oct 2014	M20-072168E3645	HF159-E.pdf
M20-9613646	M20-961_obsolete.pdf	Until 9th Oct 2014	M20-072168E3646	HF159-E.pdf
M20-9613745	M20-961_obsolete.pdf	Until 9th Oct 2014	M20-072168E3745	HF159-E.pdf
M20-9613746	M20-961_obsolete.pdf	Until 9th Oct 2014	M20-072168E3746	HF159-E.pdf
M20-9613845	M20-961_obsolete.pdf	Until 9th Oct 2014	M20-072168E3845	HF159-E.pdf
M20-9613846	M20-961_obsolete.pdf	Until 9th Oct 2014	M20-072168E3846	HF159-E.pdf
M20-9613945	M20-961_obsolete.pdf	Until 9th Oct 2014	M20-072168E3945	HF159-E.pdf
M20-9613946	M20-961_obsolete.pdf	Until 9th Oct 2014	M20-072168E3946	HF159-E.pdf
M20-9614045	M20-961_obsolete.pdf	Until 9th Oct 2014	M20-072168E4045	HF159-E.pdf
M20-9614046	M20-961_obsolete.pdf	Until 9th Oct 2014	M20-072168E4046	HF159-E.pdf
M22-2650205	M22-265_obsolete.pdf	Until 9th Oct 2014	M22-035060K0205	HF160-K.pdf
M22-2650246	M22-265_obsolete.pdf	Until 9th Oct 2014	M22-035060K0246	HF160-K.pdf
M22-2650305	M22-265_obsolete.pdf	Until 9th Oct 2014	M22-035060K0305	HF160-K.pdf
M22-2650346	M22-265_obsolete.pdf	Until 9th Oct 2014	M22-035060K0346	HF160-K.pdf
M22-2650405	M22-265_obsolete.pdf	Until 9th Oct 2014	M22-035060K0405	HF160-K.pdf
M22-2650446	M22-265_obsolete.pdf	Until 9th Oct 2014	M22-035060K0446	HF160-K.pdf
M22-2650505	M22-265_obsolete.pdf	Until 9th Oct 2014	M22-035060K0505	HF160-K.pdf
M22-2650546	M22-265_obsolete.pdf	Until 9th Oct 2014	M22-035060K0546	HF160-K.pdf
M22-2650605	M22-265_obsolete.pdf	Until 9th Oct 2014	M22-035060K0605	HF160-K.pdf
M22-2650646	M22-265_obsolete.pdf	Until 9th Oct 2014	M22-035060K0646	HF160-K.pdf
M22-2650705	M22-265_obsolete.pdf	Until 9th Oct 2014	M22-035060K0705	HF160-K.pdf
M22-2650746	M22-265_obsolete.pdf	Until 9th Oct 2014	M22-035060K0746	HF160-K.pdf
M22-2650805	M22-265_obsolete.pdf	Until 9th Oct 2014	M22-035060K0805	HF160-K.pdf
M22-2650846	M22-265_obsolete.pdf	Until 9th Oct 2014	M22-035060K0846	HF160-K.pdf
M22-2650905	M22-265_obsolete.pdf	Until 9th Oct 2014	M22-035060K0905	HF160-K.pdf
M22-2650946	M22-265_obsolete.pdf	Until 9th Oct 2014	M22-035060K0946	HF160-K.pdf
M22-2651005	M22-265_obsolete.pdf	Until 9th Oct 2014	M22-035060K1005	HF160-K.pdf
M22-2651046	M22-265_obsolete.pdf	Until 9th Oct 2014	M22-035060K1046	HF160-K.pdf
M22-2651105	M22-265_obsolete.pdf	Until 9th Oct 2014	M22-035060K1105	HF160-K.pdf
M22-2651146	M22-265_obsolete.pdf	Until 9th Oct 2014	M22-035060K1146	HF160-K.pdf
M22-2651205	M22-265_obsolete.pdf	Until 9th Oct 2014	M22-035060K1205	HF160-K.pdf
M22-2651246	M22-265_obsolete.pdf	Until 9th Oct 2014	M22-035060K1246	HF160-K.pdf
M22-2651305	M22-265_obsolete.pdf	Until 9th Oct 2014	M22-035060K1305	HF160-K.pdf
M22-2651346	M22-265_obsolete.pdf	Until 9th Oct 2014	M22-035060K1346	HF160-K.pdf

Obsolete Product Notification from Harwin - Standard

[illegible]

Obsolete Product Notification from Harwin - Standard

[illegible]

Obsolete Product Notification from Harwin - Standard

[illegible]

Obsolete Product Notification from Harwin - Standard

[illegible]

Obsolete Product Notification from Harwin - Standard

Part number being made obsolete	Drawing for obsolete product	Last Time Buy?	Alternative product	Drawing for alternative product
M22-2674005	M22-267_obsolete.pdf	Until 9th Oct 2014	M22-035120K4005	HF160-K.pdf
M22-2674046	M22-267_obsolete.pdf	Until 9th Oct 2014	M22-035120K4046	HF160-K.pdf
M22-2674105	M22-267_obsolete.pdf	Until 9th Oct 2014	M22-035120K4105	HF160-K.pdf
M22-2674146	M22-267_obsolete.pdf	Until 9th Oct 2014	M22-035120K4146	HF160-K.pdf
M22-2674205	M22-267_obsolete.pdf	Until 9th Oct 2014	M22-035120K4205	HF160-K.pdf
M22-2674246	M22-267_obsolete.pdf	Until 9th Oct 2014	M22-035120K4246	HF160-K.pdf
M22-2674305	M22-267_obsolete.pdf	Until 9th Oct 2014	M22-035120K4305	HF160-K.pdf
M22-2674346	M22-267_obsolete.pdf	Until 9th Oct 2014	M22-035120K4346	HF160-K.pdf
M22-2674405	M22-267_obsolete.pdf	Until 9th Oct 2014	M22-035120K4405	HF160-K.pdf
M22-2674446	M22-267_obsolete.pdf	Until 9th Oct 2014	M22-035120K4446	HF160-K.pdf
M22-2674505	M22-267_obsolete.pdf	Until 9th Oct 2014	M22-035120K4505	HF160-K.pdf
M22-2674546	M22-267_obsolete.pdf	Until 9th Oct 2014	M22-035120K4546	HF160-K.pdf
M22-2674605	M22-267_obsolete.pdf	Until 9th Oct 2014	M22-035120K4605	HF160-K.pdf
M22-2674646	M22-267_obsolete.pdf	Until 9th Oct 2014	M22-035120K4646	HF160-K.pdf
M22-2674705	M22-267_obsolete.pdf	Until 9th Oct 2014	M22-035120K4705	HF160-K.pdf
M22-2674746	M22-267_obsolete.pdf	Until 9th Oct 2014	M22-035120K4746	HF160-K.pdf
M22-2674805	M22-267_obsolete.pdf	Until 9th Oct 2014	M22-035120K4805	HF160-K.pdf
M22-2674846	M22-267_obsolete.pdf	Until 9th Oct 2014	M22-035120K4846	HF160-K.pdf
M22-2674905	M22-267_obsolete.pdf	Until 9th Oct 2014	M22-035120K4905	HF160-K.pdf
M22-2674946	M22-267_obsolete.pdf	Until 9th Oct 2014	M22-035120K4946	HF160-K.pdf
M22-2675005	M22-267_obsolete.pdf	Until 9th Oct 2014	M22-035120K5005	HF160-K.pdf
M22-2675046	M22-267_obsolete.pdf	Until 9th Oct 2014	M22-035120K5046	HF160-K.pdf
M22-2680205	M22-268_obsolete.pdf	Until 9th Oct 2014	M22-035120L0205	HF160-L.pdf
M22-2680246	M22-268_obsolete.pdf	Until 9th Oct 2014	M22-035120L0246	HF160-L.pdf
M22-2680305	M22-268_obsolete.pdf	Until 9th Oct 2014	M22-035120L0305	HF160-L.pdf
M22-2680346	M22-268_obsolete.pdf	Until 9th Oct 2014	M22-035120L0346	HF160-L.pdf
M22-2680405	M22-268_obsolete.pdf	Until 9th Oct 2014	M22-035120L0405	HF160-L.pdf
M22-2680446	M22-268_obsolete.pdf	Until 9th Oct 2014	M22-035120L0446	HF160-L.pdf
M22-2680505	M22-268_obsolete.pdf	Until 9th Oct 2014	M22-035120L0505	HF160-L.pdf
M22-2680546	M22-268_obsolete.pdf	Until 9th Oct 2014	M22-035120L0546	HF160-L.pdf
M22-2680605	M22-268_obsolete.pdf	Until 9th Oct 2014	M22-035120L1205	HF160-L.pdf
M22-2680646	M22-268_obsolete.pdf	Until 9th Oct 2014	M22-035120L0646	HF160-L.pdf
M22-2680705	M22-268_obsolete.pdf	Until 9th Oct 2014	M22-035120L0705	HF160-L.pdf
M22-2680746	M22-268_obsolete.pdf	Until 9th Oct 2014	M22-035120L0746	HF160-L.pdf
M22-2680805	M22-268_obsolete.pdf	Until 9th Oct 2014	M22-035120L0805	HF160-L.pdf
M22-2680846	M22-268_obsolete.pdf	Until 9th Oct 2014	M22-035120L0846	HF160-L.pdf
M22-2680905	M22-268_obsolete.pdf	Until 9th Oct 2014	M22-035120L0905	HF160-L.pdf
M22-2680946	M22-268_obsolete.pdf	Until 9th Oct 2014	M22-035120L0946	HF160-L.pdf
M22-2681005	M22-268_obsolete.pdf	Until 9th Oct 2014	M22-035120L1005	HF160-L.pdf
M22-2681046	M22-268_obsolete.pdf	Until 9th Oct 2014	M22-035120L1046	HF160-L.pdf
M22-2681105	M22-268_obsolete.pdf	Until 9th Oct 2014	M22-035120L1105	HF160-L.pdf
M22-2681146	M22-268_obsolete.pdf	Until 9th Oct 2014	M22-035120L1146	HF160-L.pdf
M22-2681205	M22-268_obsolete.pdf	Until 9th Oct 2014	M22-035120L1205	HF160-L.pdf
M22-2681246	M22-268_obsolete.pdf	Until 9th Oct 2014	M22-035120L1246	HF160-L.pdf
M22-2681305	M22-268_obsolete.pdf	Until 9th Oct 2014	M22-035120L1305	HF160-L.pdf
M22-2681346	M22-268_obsolete.pdf	Until 9th Oct 2014	M22-035120L1346	HF160-L.pdf
M22-2681405	M22-268_obsolete.pdf	Until 9th Oct 2014	M22-035120L1405	HF160-L.pdf
M22-2681446	M22-268_obsolete.pdf	Until 9th Oct 2014	M22-035120L1446	HF160-L.pdf
M22-2681505	M22-268_obsolete.pdf	Until 9th Oct 2014	M22-035120L1505	HF160-L.pdf
M22-2681546	M22-268_obsolete.pdf	Until 9th Oct 2014	M22-035120L1546	HF160-L.pdf
M22-2681605	M22-268_obsolete.pdf	Until 9th Oct 2014	M22-035120L1605	HF160-L.pdf
M22-2681646	M22-268_obsolete.pdf	Until 9th Oct 2014	M22-035120L1646	HF160-L.pdf
M22-2681705	M22-268_obsolete.pdf	Until 9th Oct 2014	M22-035120L1705	HF160-L.pdf
M22-2681746	M22-268_obsolete.pdf	Until 9th Oct 2014	M22-035120L1746	HF160-L.pdf
M22-2681805	M22-268_obsolete.pdf	Until 9th Oct 2014	M22-035120L1805	HF160-L.pdf
M22-2681846	M22-268_obsolete.pdf	Until 9th Oct 2014	M22-035120L1846	HF160-L.pdf
M22-2681905	M22-268_obsolete.pdf	Until 9th Oct 2014	M22-035120L1905	HF160-L.pdf
M22-2681946	M22-268_obsolete.pdf	Until 9th Oct 2014	M22-035120L1946	HF160-L.pdf
M22-2682005	M22-268_obsolete.pdf	Until 9th Oct 2014	M22-035120L2005	HF160-L.pdf
M22-2682046	M22-268_obsolete.pdf	Until 9th Oct 2014	M22-035120L2046	HF160-L.pdf
M22-2682105	M22-268_obsolete.pdf	Until 9th Oct 2014	M22-035120L2105	HF160-L.pdf
M22-2682146	M22-268_obsolete.pdf	Until 9th Oct 2014	M22-035120L2146	HF160-L.pdf

Obsolete Product Notification from Harwin - Standard

[illegible]

Obsolete Product Notification from Harwin - Special

Part number being made obsolete	Drawing for obsolete product	Last Time Buy?	Alternative product
JT3402DS18-22A-F15	No drawing	No - immediate	No alternative
JT3402DS18-22P-F15	No drawing	No - immediate	No alternative
JT3402DS18-4B-F15	No drawing	No - immediate	No alternative
JT3402DS22-18A-F15	No drawing	No - immediate	No alternative
JT3402DS22-18B-F15	No drawing	No - immediate	No alternative
JT3402DS22-18BX-F15	No drawing	No - immediate	No alternative
JT3402DS22-2A-F15	No drawing	No - immediate	No alternative
JT3402DS24-28A-F15	No drawing	No - immediate	No alternative
JT3402DS24-28B-F15	No drawing	No - immediate	No alternative
JT3402DS24-28BW-F15	No drawing	No - immediate	No alternative
JT3402DS24-28BX-F15	No drawing	No - immediate	No alternative
JT3402DS24-28BZ-F15	No drawing	No - immediate	No alternative
JT3402DS28-21A-F15	No drawing	No - immediate	No alternative
JT3402DS28-21B-F15	No drawing	No - immediate	No alternative
JT3402DS28-21P-F15	No drawing	No - immediate	No alternative
JT3402DS32-22AW-F15	No drawing	No - immediate	No alternative
JT3402DS32-22B-F15	No drawing	No - immediate	No alternative
JT3402DS32-22BY-F15	No drawing	No - immediate	No alternative
JT3402DS36-5A-F15	No drawing	No - immediate	No alternative
JT3402DS40-56A-F15	No drawing	No - immediate	No alternative
JT3402DS40-56AW-F15	No drawing	No - immediate	No alternative
JT3402DS40-56AX-F15	No drawing	No - immediate	No alternative
JT3402DS40-56AY-F15	No drawing	No - immediate	No alternative
JT3402DS40-56B-F15	No drawing	No - immediate	No alternative
JT3402DS40-56BW-F15	No drawing	No - immediate	No alternative
JT3402DS40-56BX-F15	No drawing	No - immediate	No alternative
JT3402DS40-56BY-F15	No drawing	No - immediate	No alternative
JT3402DS40-56BZ-F15	No drawing	No - immediate	No alternative
JT3406DS18-22S-F15	No drawing	No - immediate	No alternative
JT3406DS18-4P-F15	No drawing	No - immediate	No alternative
JT3406DS22-18P-F15	No drawing	No - immediate	No alternative
JT3406DS22-18PX-F15	No drawing	No - immediate	No alternative
JT3406DS22-18S-F15	No drawing	No - immediate	No alternative
JT3406DS22-2S-F15	No drawing	No - immediate	No alternative
JT3406DS24-28P-F15	No drawing	No - immediate	No alternative
JT3406DS24-28PW-F15	No drawing	No - immediate	No alternative
JT3406DS24-28PX-F15	No drawing	No - immediate	No alternative
JT3406DS24-28PZ-F15	No drawing	No - immediate	No alternative
JT3406DS24-28S-F15	No drawing	No - immediate	No alternative
JT3406DS28-21P-F15	No drawing	No - immediate	No alternative
JT3406DS28-21S-F15	No drawing	No - immediate	No alternative
JT3406DS32-22P-F15	No drawing	No - immediate	No alternative
JT3406DS32-22PY-F15	No drawing	No - immediate	No alternative
JT3406DS32-22SW-F15	No drawing	No - immediate	No alternative
JT3406DS36-5S-F15	No drawing	No - immediate	No alternative
JT3406DS40-56P-F15	No drawing	No - immediate	No alternative
JT3406DS40-56PW-F15	No drawing	No - immediate	No alternative
JT3406DS40-56PX-F15	No drawing	No - immediate	No alternative
JT3406DS40-56PY-F15	No drawing	No - immediate	No alternative
JT3406DS40-56PZ-F15	No drawing	No - immediate	No alternative
JT3406DS40-56S-F15	No drawing	No - immediate	No alternative
JT3406DS40-56SW-F15	No drawing	No - immediate	No alternative
JT3406DS40-56SX-F15	No drawing	No - immediate	No alternative
JT3406DS40-56SY-F15	No drawing	No - immediate	No alternative
MS25043-14D	No drawing	No - immediate	No alternative
MS3402D18-1P	No drawing	No - immediate	No alternative
MS3402D18-22P	No drawing	No - immediate	No alternative
MS3402D18-4PW	No drawing	No - immediate	No alternative
MS3402D18-4PX	No drawing	No - immediate	No alternative
MS3402D18-4PY	No drawing	No - immediate	No alternative
MS3402D18-4S	No drawing	No - immediate	No alternative
MS3402D22-18P	No drawing	No - immediate	No alternative

Obsolete Product Notification from Harwin - Special

Part number being made obsolete	Drawing for obsolete product	Last Time Buy?	Alternative product
MS3402D22-18S	No drawing	No - immediate	No alternative
MS3402D22-18SX	No drawing	No - immediate	No alternative
MS3402D22-2P	No drawing	No - immediate	No alternative
MS3402D24-28P	No drawing	No - immediate	No alternative
MS3402D24-28S	No drawing	No - immediate	No alternative
MS3402D24-28SW	No drawing	No - immediate	No alternative
MS3402D24-28SX	No drawing	No - immediate	No alternative
MS3402D24-28SZ	No drawing	No - immediate	No alternative
MS3402D28-21P	No drawing	No - immediate	No alternative
MS3402D28-21S	No drawing	No - immediate	No alternative
MS3402D32-22PW	No drawing	No - immediate	No alternative
MS3402D32-22S	No drawing	No - immediate	No alternative
MS3402D32-22SY	No drawing	No - immediate	No alternative
MS3402D36-5P	No drawing	No - immediate	No alternative
MS3402D40-56P	No drawing	No - immediate	No alternative
MS3402D40-56PW	No drawing	No - immediate	No alternative
MS3402D40-56PX	No drawing	No - immediate	No alternative
MS3402D40-56PY	No drawing	No - immediate	No alternative
MS3402D40-56S	No drawing	No - immediate	No alternative
MS3402D40-56SW	No drawing	No - immediate	No alternative
MS3402D40-56SX	No drawing	No - immediate	No alternative
MS3402D40-56SY	No drawing	No - immediate	No alternative
MS3402D40-56SZ	No drawing	No - immediate	No alternative
MS3402DS18-22A	No drawing	No - immediate	No alternative
MS3402DS18-4B	No drawing	No - immediate	No alternative
MS3402DS22-18A	No drawing	No - immediate	No alternative
MS3402DS22-18B	No drawing	No - immediate	No alternative
MS3402DS22-18BX	No drawing	No - immediate	No alternative
MS3402DS22-2A	No drawing	No - immediate	No alternative
MS3402DS24-28A	No drawing	No - immediate	No alternative
MS3402DS24-28B	No drawing	No - immediate	No alternative
MS3402DS24-28BW	No drawing	No - immediate	No alternative
MS3402DS24-28BX	No drawing	No - immediate	No alternative
MS3402DS24-28BZ	No drawing	No - immediate	No alternative
MS3402DS28-21A	No drawing	No - immediate	No alternative
MS3402DS28-21B	No drawing	No - immediate	No alternative
MS3402DS32-22AW	No drawing	No - immediate	No alternative
MS3402DS32-22B	No drawing	No - immediate	No alternative
MS3402DS32-22BY	No drawing	No - immediate	No alternative
MS3402DS36-5A	No drawing	No - immediate	No alternative
MS3402DS40-56A	No drawing	No - immediate	No alternative
MS3402DS40-56AW	No drawing	No - immediate	No alternative
MS3402DS40-56AX	No drawing	No - immediate	No alternative
MS3402DS40-56AY	No drawing	No - immediate	No alternative
MS3402DS40-56B	No drawing	No - immediate	No alternative
MS3402DS40-56BW	No drawing	No - immediate	No alternative
MS3402DS40-56BX	No drawing	No - immediate	No alternative
MS3402DS40-56BY	No drawing	No - immediate	No alternative
MS3402DS40-56BZ	No drawing	No - immediate	No alternative
MS3404D18-4S	No drawing	No - immediate	No alternative
MS3404D22-18S	No drawing	No - immediate	No alternative
MS3404D22-18SX	No drawing	No - immediate	No alternative
MS3404D24-28S	No drawing	No - immediate	No alternative
MS3404D24-28SW	No drawing	No - immediate	No alternative
MS3404D24-28SX	No drawing	No - immediate	No alternative
MS3404D24-28SZ	No drawing	No - immediate	No alternative
MS3404D28-21S	No drawing	No - immediate	No alternative
MS3404D32-22S	No drawing	No - immediate	No alternative
MS3404D32-22SY	No drawing	No - immediate	No alternative
MS3404D40-56P	No drawing	No - immediate	No alternative
MS3404D40-56PW	No drawing	No - immediate	No alternative
MS3404D40-56S	No drawing	No - immediate	No alternative

Obsolete Product Notification from Harwin - Special

Part number being made obsolete	Drawing for obsolete product	Last Time Buy?	Alternative product
MS3404D40-56SW	No drawing	No - immediate	No alternative
MS3404D40-56SX	No drawing	No - immediate	No alternative
MS3404D40-56SY	No drawing	No - immediate	No alternative
MS3404D40-56SZ	No drawing	No - immediate	No alternative
MS3406D18-1S	No drawing	No - immediate	No alternative
MS3406D18-22S	No drawing	No - immediate	No alternative
MS3406D18-4P	No drawing	No - immediate	No alternative
MS3406D18-4SW	No drawing	No - immediate	No alternative
MS3406D18-4SX	No drawing	No - immediate	No alternative
MS3406D18-4SY	No drawing	No - immediate	No alternative
MS3406D22-18P	No drawing	No - immediate	No alternative
MS3406D22-18PX	No drawing	No - immediate	No alternative
MS3406D22-18S	No drawing	No - immediate	No alternative
MS3406D22-2S	No drawing	No - immediate	No alternative
MS3406D24-28P	No drawing	No - immediate	No alternative
MS3406D24-28PW	No drawing	No - immediate	No alternative
MS3406D24-28PX	No drawing	No - immediate	No alternative
MS3406D24-28PZ	No drawing	No - immediate	No alternative
MS3406D24-28S	No drawing	No - immediate	No alternative
MS3406D28-21P	No drawing	No - immediate	No alternative
MS3406D28-21PW	No drawing	No - immediate	No alternative
MS3406D28-21PX	No drawing	No - immediate	No alternative
MS3406D28-21S	No drawing	No - immediate	No alternative
MS3406D28-PX	No drawing	No - immediate	No alternative
MS3406D32-22P	No drawing	No - immediate	No alternative
MS3406D32-22PY	No drawing	No - immediate	No alternative
MS3406D32-22SW	No drawing	No - immediate	No alternative
MS3406D36-5S	No drawing	No - immediate	No alternative
MS3406D36-5SX	No drawing	No - immediate	No alternative
MS3406D36-5SY	No drawing	No - immediate	No alternative
MS3406D40-56P	No drawing	No - immediate	No alternative
MS3406D40-56PW	No drawing	No - immediate	No alternative
MS3406D40-56PX	No drawing	No - immediate	No alternative
MS3406D40-56PY	No drawing	No - immediate	No alternative
MS3406D40-56PZ	No drawing	No - immediate	No alternative
MS3406D40-56S	No drawing	No - immediate	No alternative
MS3406D40-56SW	No drawing	No - immediate	No alternative
MS3406D40-56SX	No drawing	No - immediate	No alternative
MS3406D40-56SY	No drawing	No - immediate	No alternative
MS3406DS18-22S	No drawing	No - immediate	No alternative
MS3406DS18-4P	No drawing	No - immediate	No alternative
MS3406DS22-18P	No drawing	No - immediate	No alternative
MS3406DS22-18PX	No drawing	No - immediate	No alternative
MS3406DS22-18S	No drawing	No - immediate	No alternative
MS3406DS22-2S	No drawing	No - immediate	No alternative
MS3406DS24-28P	No drawing	No - immediate	No alternative
MS3406DS24-28PW	No drawing	No - immediate	No alternative
MS3406DS24-28PX	No drawing	No - immediate	No alternative
MS3406DS24-28PZ	No drawing	No - immediate	No alternative
MS3406DS24-28S	No drawing	No - immediate	No alternative
MS3406DS28-21P	No drawing	No - immediate	No alternative
MS3406DS28-21S	No drawing	No - immediate	No alternative
MS3406DS32-22P	No drawing	No - immediate	No alternative
MS3406DS32-22PY	No drawing	No - immediate	No alternative
MS3406DS32-22SW	No drawing	No - immediate	No alternative
MS3406DS36-5S	No drawing	No - immediate	No alternative
MS3406DS40-56P	No drawing	No - immediate	No alternative
MS3406DS40-56PW	No drawing	No - immediate	No alternative
MS3406DS40-56PX	No drawing	No - immediate	No alternative
MS3406DS40-56PY	No drawing	No - immediate	No alternative
MS3406DS40-56PZ	No drawing	No - immediate	No alternative
MS3406DS40-56S	No drawing	No - immediate	No alternative

Obsolete Product Notification from Harwin - Special

Part number being made obsolete	Drawing for obsolete product	Last Time Buy?	Alternative product
MS3406DS40-56SW	No drawing	No - immediate	No alternative
MS3406DS40-56SX	No drawing	No - immediate	No alternative
MS3406DS40-56SY	No drawing	No - immediate	No alternative
C106672C-1	Contact technical@harwin.com	No - immediate	No alternative
C106672C-2	Contact technical@harwin.com	No - immediate	No alternative
C106672C-TL	Contact technical@harwin.com	No - immediate	No alternative
C107387C-1	Contact technical@harwin.com	No - immediate	No alternative
C107387C-2	Contact technical@harwin.com	No - immediate	No alternative
H106666C	Contact technical@harwin.com	No - immediate	No alternative
H106667C	Contact technical@harwin.com	No - immediate	No alternative
H106693C	Contact technical@harwin.com	No - immediate	No alternative
H106693C-00	Contact technical@harwin.com	No - immediate	No alternative
H106693C-1	Contact technical@harwin.com	No - immediate	No alternative
H106693C-2	Contact technical@harwin.com	No - immediate	No alternative
H106693C-HT	Contact technical@harwin.com	No - immediate	No alternative
H106693C-SC	Contact technical@harwin.com	No - immediate	No alternative
H106694C	Contact technical@harwin.com	No - immediate	No alternative
H106694C-00	Contact technical@harwin.com	No - immediate	No alternative
H106695C	Contact technical@harwin.com	No - immediate	No alternative
H106696C	Contact technical@harwin.com	No - immediate	No alternative
H106696C-00	Contact technical@harwin.com	No - immediate	No alternative
H106696C-1	Contact technical@harwin.com	No - immediate	No alternative
H106696C-1HT	Contact technical@harwin.com	No - immediate	No alternative
H106696C-2	Contact technical@harwin.com	No - immediate	No alternative
H106696C-3	Contact technical@harwin.com	No - immediate	No alternative
H106696C-DIP	Contact technical@harwin.com	No - immediate	No alternative
H106696C-HT	Contact technical@harwin.com	No - immediate	No alternative
H107388C-00	Contact technical@harwin.com	No - immediate	No alternative
H107388C-1	Contact technical@harwin.com	No - immediate	No alternative
H107388C-2	Contact technical@harwin.com	No - immediate	No alternative
H107388C-3	Contact technical@harwin.com	No - immediate	No alternative
H107388C-HT	Contact technical@harwin.com	No - immediate	No alternative
M106670C	Contact technical@harwin.com	No - immediate	No alternative
M106689C	Contact technical@harwin.com	No - immediate	No alternative
M106690C	Contact technical@harwin.com	No - immediate	No alternative
M106691C	Contact technical@harwin.com	No - immediate	No alternative
M107211C	Contact technical@harwin.com	No - immediate	No alternative
M107212C	Contact technical@harwin.com	No - immediate	No alternative
M107382C	Contact technical@harwin.com	No - immediate	No alternative
M107382CA	Contact technical@harwin.com	No - immediate	No alternative
M107382CB	Contact technical@harwin.com	No - immediate	No alternative
M107383C	Contact technical@harwin.com	No - immediate	No alternative
M107383CA	Contact technical@harwin.com	No - immediate	No alternative
M107384C	Contact technical@harwin.com	No - immediate	No alternative
M107385C	Contact technical@harwin.com	No - immediate	No alternative
M107385CA	Contact technical@harwin.com	No - immediate	No alternative
M107385CB	Contact technical@harwin.com	No - immediate	No alternative
M107386C	Contact technical@harwin.com	No - immediate	No alternative
M107603C	Contact technical@harwin.com	No - immediate	No alternative
M107604C	Contact technical@harwin.com	No - immediate	No alternative
M107616C	Contact technical@harwin.com	No - immediate	No alternative
C106672C-TL	No drawing	No - immediate	No alternative
C107098CTL1	No drawing	No - immediate	No alternative
C107527C-TL	No drawing	No - immediate	No alternative
D104760C REWORK	No drawing	No - immediate	No alternative
H105404CTL	No drawing	No - immediate	No alternative
H105788CTL	No drawing	No - immediate	No alternative
H106682C-TL	No drawing	No - immediate	No alternative
H106696C-DIP	No drawing	No - immediate	No alternative
H106971CT	No drawing	No - immediate	No alternative

Obsolete Product Notification from Harwin - Special

Part number being made obsolete	Drawing for obsolete product	Last Time Buy?	Alternative product
H107456C-TL	No drawing	No - immediate	No alternative
HD4323-TL	No drawing	No - immediate	No alternative
M105195CTL	No drawing	No - immediate	No alternative
M107078C-TL	No drawing	No - immediate	No alternative
M107212C-TL	No drawing	No - immediate	No alternative
M107382CTL	No drawing	No - immediate	No alternative
MOULD TOOL (RAYMARINE)	No drawing	No - immediate	No alternative
PINFIXTURE	No drawing	No - immediate	No alternative
Q106778CTL	No drawing	No - immediate	No alternative
T107131C	No drawing	No - immediate	No alternative
T107381CTL1	No drawing	No - immediate	No alternative
T107381CTL2	No drawing	No - immediate	No alternative
T107381CTL3	No drawing	No - immediate	No alternative
TD1376/A-3	No drawing	No - immediate	No alternative
TD1376/B-1	No drawing	No - immediate	No alternative
TD1376/B-2	No drawing	No - immediate	No alternative
TD1376/B-5	No drawing	No - immediate	No alternative
TD5731TL1	No drawing	No - immediate	No alternative
TD5731TL2	No drawing	No - immediate	No alternative
TD8042TL1	No drawing	No - immediate	No alternative
TD8042TL2	No drawing	No - immediate	No alternative
TD8042TL3	No drawing	No - immediate	No alternative
TL102045C	No drawing	No - immediate	No alternative
TL107213C	No drawing	No - immediate	No alternative
TL107217C	No drawing	No - immediate	No alternative
TL107343C	No drawing	No - immediate	No alternative
TL107344C	No drawing	No - immediate	No alternative
TLC106933C	No drawing	No - immediate	No alternative
TLC106990C	No drawing	No - immediate	No alternative
TLC107019C	No drawing	No - immediate	No alternative
TLC107020C	No drawing	No - immediate	No alternative
TLC107028C	No drawing	No - immediate	No alternative
TLP107038C	No drawing	No - immediate	No alternative
TOOLCHARGE1	No drawing	No - immediate	No alternative
TOOLCHARGE2	No drawing	No - immediate	No alternative
TOOLCHARGE3	No drawing	No - immediate	No alternative
TOOLCHARGE4	No drawing	No - immediate	No alternative
TOOLCHARGE5	No drawing	No - immediate	No alternative
TOOLCHARGE6	No drawing	No - immediate	No alternative
TOOLCHARGE7	No drawing	No - immediate	No alternative
TOOLPO040198-MG	No drawing	No - immediate	No alternative
L101715C	Contact technical@harwin.com	No - immediate	No alternative
L102045C	Contact technical@harwin.com	No - immediate	No alternative
L103037C	Contact technical@harwin.com	No - immediate	No alternative
A101715C	Contact technical@harwin.com	No - immediate	No alternative
A102045C	No drawing	No - immediate	No alternative
A103037C	No drawing	No - immediate	No alternative
C107936C	Contact technical@harwin.com	No - immediate	No alternative
C107937C	Contact technical@harwin.com	No - immediate	No alternative
C107938C	Contact technical@harwin.com	No - immediate	No alternative
C107939C	Contact technical@harwin.com	No - immediate	No alternative
C107946C	Contact technical@harwin.com	No - immediate	No alternative
C107948C-10-20	Contact technical@harwin.com	No - immediate	No alternative
C107949C-10	Contact technical@harwin.com	No - immediate	No alternative
H107930C	Contact technical@harwin.com	No - immediate	No alternative
H107933C	Contact technical@harwin.com	No - immediate	No alternative
H108154C	Contact technical@harwin.com	No - immediate	No alternative
H108155C	Contact technical@harwin.com	No - immediate	No alternative
H108155C-1	Contact technical@harwin.com	No - immediate	No alternative
HD5648	Contact technical@harwin.com	No - immediate	No alternative

Obsolete Product Notification from Harwin - Special

Part number being made obsolete	Drawing for obsolete product	Last Time Buy?	Alternative product
M107928C	Contact technical@harwin.com	No - immediate	No alternative
M107928C-2	Contact technical@harwin.com	No - immediate	No alternative
M107928C-PRE	Contact technical@harwin.com	No - immediate	No alternative
M107929C	Contact technical@harwin.com	No - immediate	No alternative
M107929C-PRE	Contact technical@harwin.com	No - immediate	No alternative
M107931C	Contact technical@harwin.com	No - immediate	No alternative
M107931C-PRE	Contact technical@harwin.com	No - immediate	No alternative
M107932C	Contact technical@harwin.com	No - immediate	No alternative
M107934C	Contact technical@harwin.com	No - immediate	No alternative
M107934C-PRE	Contact technical@harwin.com	No - immediate	No alternative
M107935C	Contact technical@harwin.com	No - immediate	No alternative
M107940C	Contact technical@harwin.com	No - immediate	No alternative
M107941C	Contact technical@harwin.com	No - immediate	No alternative
M107943C	Contact technical@harwin.com	No - immediate	No alternative
M107944C	Contact technical@harwin.com	No - immediate	No alternative
MMM1856	Contact technical@harwin.com	No - immediate	No alternative