



Harwin plc
Fitzherbert Road
Farlington, Portsmouth
Hampshire PO6 1RT
United Kingdom

Reception: +44 (0)23 9231 4545
Sales Desk: +44 (0)23 9237 0451
Fax: +44 (0)23 9231 4590

Monday 17th November, 2014

Dear Customer,

Re: Obsolescence notification for Harwin product.

Please be advised that there are a few items from the M60-606 series that are now obsolete. These items are obsolete with immediate effect, with no possibility for last time buy. Please see the attached spreadsheet for a complete list of affected items, and suggested alternatives:

- M60-606 – 20+20, 30+30, 40+40 and 50+50 contact versions

Unfortunately, we are no longer able to support these product lines. Alternative items are available; please see the attached spreadsheet for the alternative part numbers.

If you have any further questions regarding this letter, please do not hesitate to contact us.

Yours faithfully,

The Product Management Team
technical@harwin.com

Obsolete Product Notification from Harwin

Part number being made obsolete	Drawing for obsolete product	Last Time Buy?	Alternative product	Drawing for alternative product
M60-6062045	M60-606_obsolete.pdf	No - immediate	M60-6052045	M60-605.pdf
M60-6063045	M60-606_obsolete.pdf	No - immediate	M60-6053045	M60-605.pdf
M60-6064045	M60-606_obsolete.pdf	No - immediate	M60-6054045	M60-605.pdf
M60-6065045	M60-606_obsolete.pdf	No - immediate	M60-6055045	M60-605.pdf