



Harwin plc
Fitzherbert Road
Farlington, Portsmouth
Hampshire PO6 1RT
United Kingdom

Reception: +44 (0)23 9231 4545
Sales Desk: +44 (0)23 9237 0451
Fax: +44 (0)23 9231 4590

Friday 26th February, 2016

Dear Customer,

Re: Obsolescence notification for Harwin product.

Please be advised that there are a number of individual items that are now obsolete. All of the items are obsolete with immediate effect. Stocks may remain of a few items, but most of these have not been manufactured in some time. Please see the attached spreadsheet for a complete list of affected items (there are two sheets in the spreadsheet, please check both). Here is a summary of affected standard ranges:

- M80-4000000FE-xx-xxx-00-000
- M80-4000000FG-xx-xxx-00-000
- M80-618, M80-619, M80-620, M80-621, M80-821, M80-927, M80-928
- A selection of Datamate Mix Tek in the old numbering system – e.g. M80-4C106F2-04-327 (note, these part numbers can be replicated using the current numbering system, see the attached spreadsheet for details)
- Various Datamate customer specials and development products

Unfortunately, we are no longer able to support these product lines.

If you have any further questions regarding this letter, please do not hesitate to contact us.

Yours faithfully,

The Product Management Team
technical@harwin.com

If you have not been sent the accompanying spreadsheet, please request it from the contact that sent you this letter.

Obsolete Product Notification from Harwin - Standard

[illegible]

Obsolete Product Notification from Harwin - Standard

[illegible]

Obsolete Product Notification from Harwin - Standard

[illegible]

Obsolete Product Notification from Harwin - Standard

[illegible]

Obsolete Product Notification from Harwin - Standard

[illegible]

Obsolete Product Notification from Harwin - Standard

[illegible]

Obsolete Product Notification from Harwin - Standard

[illegible]

Obsolete Product Notification from Harwin - Standard

[illegible]

Obsolete Product Notification from Harwin - Standard

Part number being made obsolete	Drawing for obsolete product	Last Time Buy?	Alternative product	Drawing for alternative product
M80-4000000FG-12-32B-00-000	M80-4000000FG-XX-XXX-00-000_obsolete.pdf	No - immediate	M80-4000000F2-12-32B-00-000	M80-4000000F2-XX-XXX-00-000.pdf
M80-4000000FG-12-32C-00-000	M80-4000000FG-XX-XXX-00-000_obsolete.pdf	No - immediate	M80-4000000F2-12-32C-00-000	M80-4000000F2-XX-XXX-00-000.pdf
M80-4C104F1-22-000	M80-4C104F1-22-000_obsolete.pdf	No - immediate	M80-4C10442F1-02-000-02-000	Contact technical@harwin.com
M80-4C104F1-40-000	M80-4C104F1-40-000_obsolete.pdf	No - immediate	M80-4C10442F1-04-000-00-000	Contact technical@harwin.com
M80-4C106F1-20-306	M80-4C106F1-20-306_obsolete.pdf	No - immediate	M80-4C10642F1-02-306-00-000	Contact technical@harwin.com
M80-4C106F2-04-327	M80-4C106F2-04-327_obsolete.pdf	No - immediate	M80-4C10642F2-00-000-04-327	Contact technical@harwin.com
M80-4D104F1-02-326	M80-4D104F1-02-326_obsolete.pdf	No - immediate	M80-4D10442F1-00-000-02-326	Contact technical@harwin.com
M80-4D104F1-11-327	M80-4D104F1-11-327_obsolete.pdf	No - immediate	M80-4D10442F1-01-327-01-327	Contact technical@harwin.com
M80-4D104F1-20-326	M80-4D104F1-20-326_obsolete.pdf	No - immediate	M80-4D10442F1-02-326-00-000	Contact technical@harwin.com
M80-4D106F1-04-327	M80-4D106F1-04-327_obsolete.pdf	No - immediate	M80-4D10642F1-00-000-04-327	M80-4D10642F1-00-000-04-327.pdf
M80-4D110F1-12-305	M80-4D110F1-12-305_obsolete.pdf	No - immediate	M80-4D11042F1-01-305-02-305	Contact technical@harwin.com
M80-4D110F2-30-327	M80-4D110F2-30-327_obsolete.pdf	No - immediate	M80-4D11005F2-03-327-00-000	M80-4D11005F2-03-327-00-000.pdf
M80-4T100F1-66-321	M80-4T100F1-66-321_obsolete.pdf	No - immediate	M80-4000000F1-12-321-00-000	M80-4000000F1-XX-XXX-00-000.pdf
M80-4T11000-03-321	M80-4T11000-03-321_obsolete.pdf	No - immediate	M80-4T1100100-00-000-03-321	Contact technical@harwin.com
M80-4T11000-12-301	M80-4T11000-12-301_obsolete.pdf	No - immediate	M80-4T1100100-01-301-02-301	Contact technical@harwin.com
M80-4T110F1-03-301	M80-4T110F1-03-301_obsolete.pdf	No - immediate	M80-4T11001F1-00-000-03-301	Contact technical@harwin.com
M80-4T12000-21-301	M80-4T12000-21-301_obsolete.pdf	No - immediate	M80-4T1200100-02-301-01-301	Contact technical@harwin.com
M80-4T22800-30-302	M80-4T22800-30-302_obsolete.pdf	No - immediate	M80-4T2280100-03-302-00-000	Contact technical@harwin.com
M80-6180322	M80-618_obsolete.pdf	No - immediate	M80-7930342	M80-793.pdf
M80-6190322	M80-619_obsolete.pdf	No - immediate	M80-7920342	M80-792.pdf
M80-6200822	M80-620_obsolete.pdf	No - immediate	M80-7910842	M80-791.pdf
M80-6210822	M80-621_obsolete.pdf	No - immediate	M80-7710842	M80-771.pdf
M80-7103022	M80-710.pdf	No - immediate	M80-7102442	M80-710.pdf
M80-7103042	M80-710.pdf	No - immediate	M80-7102442	M80-710.pdf
M80-7104222	M80-710.pdf	No - immediate	M80-7102442	M80-710.pdf
M80-7104242	M80-710.pdf	No - immediate	M80-7102442	M80-710.pdf
M80-7110622	M80-711.pdf	No - immediate	M80-7111542	M80-711.pdf
M80-7110642	M80-711.pdf	No - immediate	M80-7111542	M80-711.pdf
M80-7113022	M80-711.pdf	No - immediate	M80-7112442	M80-711.pdf
M80-7113042	M80-711.pdf	No - immediate	M80-7112442	M80-711.pdf
M80-7114222	M80-711.pdf	No - immediate	M80-7112442	M80-711.pdf
M80-7114242	M80-711.pdf	No - immediate	M80-7112442	M80-711.pdf
M80-7140601	M80-714.pdf	No - immediate	M80-7142442	M80-714.pdf
M80-7140605	M80-714.pdf	No - immediate	M80-7142442	M80-714.pdf
M80-7141501	M80-714.pdf	No - immediate	M80-7142442	M80-714.pdf
M80-7141505	M80-714.pdf	No - immediate	M80-7142442	M80-714.pdf
M80-7143001	M80-714.pdf	No - immediate	M80-7142442	M80-714.pdf
M80-7143005	M80-714.pdf	No - immediate	M80-7142442	M80-714.pdf
M80-7144201	M80-714.pdf	No - immediate	M80-7142442	M80-714.pdf
M80-7144205	M80-714.pdf	No - immediate	M80-7142442	M80-714.pdf
M80-7152405	M80-715.pdf	No - immediate	M80-7151505	M80-715.pdf

Obsolete Product Notification from Harwin - Standard

Part number being made obsolete	Drawing for obsolete product	Last Time Buy?	Alternative product	Drawing for alternative product
M80-7153005	M80-715.pdf	No - immediate	M80-7164205	M80-716.pdf
M80-7154205	M80-715.pdf	No - immediate	M80-7164205	M80-716.pdf
M80-7161505	M80-716.pdf	No - immediate	M80-7151505	M80-715.pdf
M80-7162405	M80-716.pdf	No - immediate	M80-7164205	M80-716.pdf
M80-7163005	M80-716.pdf	No - immediate	M80-7164205	M80-716.pdf
M80-7170601	M80-717.pdf	No - immediate	M80-7142442	M80-714.pdf
M80-7171501	M80-717.pdf	No - immediate	M80-7142442	M80-714.pdf
M80-7171505	M80-717.pdf	No - immediate	M80-7142442	M80-714.pdf
M80-7172401	M80-717.pdf	No - immediate	M80-7142442	M80-714.pdf
M80-7173001	M80-717.pdf	No - immediate	M80-7142442	M80-714.pdf
M80-7173005	M80-717.pdf	No - immediate	M80-7142442	M80-714.pdf
M80-7174201	M80-717.pdf	No - immediate	M80-7142442	M80-714.pdf
M80-7174205	M80-717.pdf	No - immediate	M80-7142442	M80-714.pdf
M80-7180605	M80-718.pdf	No - immediate	M80-7150605	M80-715.pdf
M80-7181505	M80-718.pdf	No - immediate	M80-7151505	M80-715.pdf
M80-7182405	M80-718.pdf	No - immediate	M80-7164205	M80-716.pdf
M80-7183005	M80-718.pdf	No - immediate	M80-7164205	M80-716.pdf
M80-8210422	M80-821_obsolete.pdf	No - immediate	M80-7810442	M80-781.pdf
M80-9270322	M80-927_obsolete.pdf	No - immediate	M80-9260342	M80-926.pdf
M80-9270342	M80-927_obsolete.pdf	No - immediate	M80-9260342	M80-926.pdf
M80-9270345	M80-927_obsolete.pdf	No - immediate	M80-9260342	M80-926.pdf
M80-9270422	M80-927_obsolete.pdf	No - immediate	M80-9260442	M80-926.pdf
M80-9270442	M80-927_obsolete.pdf	No - immediate	M80-9260442	M80-926.pdf
M80-9270445	M80-927_obsolete.pdf	No - immediate	M80-9260442	M80-926.pdf
M80-9270522	M80-927_obsolete.pdf	No - immediate	M80-9260542	M80-926.pdf
M80-9270542	M80-927_obsolete.pdf	No - immediate	M80-9260542	M80-926.pdf
M80-9270545	M80-927_obsolete.pdf	No - immediate	M80-9260542	M80-926.pdf
M80-9270622	M80-927_obsolete.pdf	No - immediate	M80-9260642	M80-926.pdf
M80-9270642	M80-927_obsolete.pdf	No - immediate	M80-9260642	M80-926.pdf
M80-9270645	M80-927_obsolete.pdf	No - immediate	M80-9260642	M80-926.pdf
M80-9270722	M80-927_obsolete.pdf	No - immediate	M80-9260742	M80-926.pdf
M80-9270742	M80-927_obsolete.pdf	No - immediate	M80-9260742	M80-926.pdf
M80-9270745	M80-927_obsolete.pdf	No - immediate	M80-9260742	M80-926.pdf
M80-9271722	M80-927_obsolete.pdf	No - immediate	M80-9261742	M80-926.pdf
M80-9271742	M80-927_obsolete.pdf	No - immediate	M80-9261742	M80-926.pdf
M80-9271745	M80-927_obsolete.pdf	No - immediate	M80-9261742	M80-926.pdf
M80-9272222	M80-927_obsolete.pdf	No - immediate	M80-9262242	M80-926.pdf
M80-9272242	M80-927_obsolete.pdf	No - immediate	M80-9262242	M80-926.pdf
M80-9272245	M80-927_obsolete.pdf	No - immediate	M80-9262242	M80-926.pdf
M80-9280322	M80-928_obsolete.pdf	No - immediate	M80-9260342	M80-926.pdf
M80-9280342	M80-928_obsolete.pdf	No - immediate	M80-9260342	M80-926.pdf

Obsolete Product Notification from Harwin - Standard

Part number being made obsolete	Drawing for obsolete product	Last Time Buy?	Alternative product	Drawing for alternative product
M80-9280345	M80-928_obsolete.pdf	No - immediate	M80-9260342	M80-926.pdf
M80-9280422	M80-928_obsolete.pdf	No - immediate	M80-9260442	M80-926.pdf
M80-9280442	M80-928_obsolete.pdf	No - immediate	M80-9260442	M80-926.pdf
M80-9280445	M80-928_obsolete.pdf	No - immediate	M80-9260442	M80-926.pdf
M80-9280522	M80-928_obsolete.pdf	No - immediate	M80-9260542	M80-926.pdf
M80-9280542	M80-928_obsolete.pdf	No - immediate	M80-9260542	M80-926.pdf
M80-9280545	M80-928_obsolete.pdf	No - immediate	M80-9260542	M80-926.pdf
M80-9280622	M80-928_obsolete.pdf	No - immediate	M80-9260642	M80-926.pdf
M80-9280642	M80-928_obsolete.pdf	No - immediate	M80-9260642	M80-926.pdf
M80-9280645	M80-928_obsolete.pdf	No - immediate	M80-9260642	M80-926.pdf
M80-9280722	M80-928_obsolete.pdf	No - immediate	M80-9260742	M80-926.pdf
M80-9280742	M80-928_obsolete.pdf	No - immediate	M80-9260742	M80-926.pdf
M80-9280745	M80-928_obsolete.pdf	No - immediate	M80-9260742	M80-926.pdf
M80-9281722	M80-928_obsolete.pdf	No - immediate	M80-9261742	M80-926.pdf
M80-9281742	M80-928_obsolete.pdf	No - immediate	M80-9261742	M80-926.pdf
M80-9281745	M80-928_obsolete.pdf	No - immediate	M80-9261742	M80-926.pdf
M80-9282222	M80-928_obsolete.pdf	No - immediate	M80-9262242	M80-926.pdf
M80-9282242	M80-928_obsolete.pdf	No - immediate	M80-9262242	M80-926.pdf
M80-9282245	M80-928_obsolete.pdf	No - immediate	M80-9262242	M80-926.pdf

Obsolete Product Notification from Harwin - Special

Part number being made obsolete	Drawing for obsolete product	Last Time Buy?
C105698C	Contact technical@harwin.com	No - immediate
C105699C	Contact technical@harwin.com	No - immediate
C105821C	Contact technical@harwin.com	No - immediate
HD4482	Contact technical@harwin.com	No - immediate
HD4528	Contact technical@harwin.com	No - immediate
HD4539	Contact technical@harwin.com	No - immediate
HD4540	Contact technical@harwin.com	No - immediate
HD4547	Contact technical@harwin.com	No - immediate
HD4548	Contact technical@harwin.com	No - immediate
HD4565	Contact technical@harwin.com	No - immediate
HD4566	Contact technical@harwin.com	No - immediate
HD4603	Contact technical@harwin.com	No - immediate
HD4604	Contact technical@harwin.com	No - immediate
HD4605	Contact technical@harwin.com	No - immediate
HD4606	Contact technical@harwin.com	No - immediate
HD4665	Contact technical@harwin.com	No - immediate
HD4666	Contact technical@harwin.com	No - immediate
HD4741	Contact technical@harwin.com	No - immediate
HD4742	Contact technical@harwin.com	No - immediate
HD4743	Contact technical@harwin.com	No - immediate
HD4744	Contact technical@harwin.com	No - immediate
HD4750	Contact technical@harwin.com	No - immediate
HD4759	Contact technical@harwin.com	No - immediate
HD4760	Contact technical@harwin.com	No - immediate
HD4978	Contact technical@harwin.com	No - immediate
HD4979	Contact technical@harwin.com	No - immediate
HD5952-42	Contact technical@harwin.com	No - immediate
HD5952-45	Contact technical@harwin.com	No - immediate
HD5953-06	Contact technical@harwin.com	No - immediate
HD5953-08	Contact technical@harwin.com	No - immediate
HD5953-10	Contact technical@harwin.com	No - immediate
HD5953-12	Contact technical@harwin.com	No - immediate
HD5953-14	Contact technical@harwin.com	No - immediate
HD5953-20	Contact technical@harwin.com	No - immediate
HD5953-26	Contact technical@harwin.com	No - immediate
HD5953-34	Contact technical@harwin.com	No - immediate
HD5953-42	Contact technical@harwin.com	No - immediate
HD5953-50	Contact technical@harwin.com	No - immediate
HD5967-42	Contact technical@harwin.com	No - immediate
HD5967-45	Contact technical@harwin.com	No - immediate
HD5968-42	Contact technical@harwin.com	No - immediate
HD5968-45	Contact technical@harwin.com	No - immediate
HD5969-XX	Contact technical@harwin.com	No - immediate
HD6010-42	Contact technical@harwin.com	No - immediate
HD6010-45	Contact technical@harwin.com	No - immediate
HD6010B-42	Contact technical@harwin.com	No - immediate
HD6010B-45	Contact technical@harwin.com	No - immediate
HD6200A-M80-263-06-00-00	Contact technical@harwin.com	No - immediate
HD62014-M80-273-06-00-00	Contact technical@harwin.com	No - immediate
HD6201A-M80-273-06-00-00	Contact technical@harwin.com	No - immediate
HD6317	Contact technical@harwin.com	No - immediate
HD6318	Contact technical@harwin.com	No - immediate
HD6356	Contact technical@harwin.com	No - immediate
HD6368	Contact technical@harwin.com	No - immediate
HD6436	Contact technical@harwin.com	No - immediate
HD6497	Contact technical@harwin.com	No - immediate
HD6498	Contact technical@harwin.com	No - immediate
HD6499	Contact technical@harwin.com	No - immediate
HD6500	Contact technical@harwin.com	No - immediate
HD6538	Contact technical@harwin.com	No - immediate
HD6539	Contact technical@harwin.com	No - immediate
HD6598	Contact technical@harwin.com	No - immediate

Obsolete Product Notification from Harwin - Special

Part number being made obsolete	Drawing for obsolete product	Last Time Buy?
M104689C	Contact technical@harwin.com	No - immediate
M104805C	Contact technical@harwin.com	No - immediate
M104864C	Contact technical@harwin.com	No - immediate
M104865C	Contact technical@harwin.com	No - immediate
M104866C	Contact technical@harwin.com	No - immediate
M104867C	Contact technical@harwin.com	No - immediate
M104921C	Contact technical@harwin.com	No - immediate
M104922C	Contact technical@harwin.com	No - immediate
M105195C	Contact technical@harwin.com	No - immediate
M105671C	Contact technical@harwin.com	No - immediate
M105813C	Contact technical@harwin.com	No - immediate
M105814C	Contact technical@harwin.com	No - immediate
M105815C	Contact technical@harwin.com	No - immediate
M105816C	Contact technical@harwin.com	No - immediate
M105817C	Contact technical@harwin.com	No - immediate
M105818C	Contact technical@harwin.com	No - immediate
M106186C	Contact technical@harwin.com	No - immediate
M106299C	Contact technical@harwin.com	No - immediate
M106548C	Contact technical@harwin.com	No - immediate
M108363C	Contact technical@harwin.com	No - immediate
M80C106782C	Contact technical@harwin.com	No - immediate
M80C106783C	Contact technical@harwin.com	No - immediate
M80C106817C	Contact technical@harwin.com	No - immediate
M80C106831C	Contact technical@harwin.com	No - immediate
M80C106832C	Contact technical@harwin.com	No - immediate
M80C106833C	Contact technical@harwin.com	No - immediate
M80C106861C	Contact technical@harwin.com	No - immediate
M80C106957C	Contact technical@harwin.com	No - immediate
M80C106958C	Contact technical@harwin.com	No - immediate
M80C107026C	Contact technical@harwin.com	No - immediate
M80C107027C	Contact technical@harwin.com	No - immediate
M80C107068C	Contact technical@harwin.com	No - immediate
M80C107089C	Contact technical@harwin.com	No - immediate
M80C107090C	Contact technical@harwin.com	No - immediate
M80C107125C	Contact technical@harwin.com	No - immediate
M80C107130C	Contact technical@harwin.com	No - immediate
M80C107135C	Contact technical@harwin.com	No - immediate
M80C107143C	Contact technical@harwin.com	No - immediate
M80C107144C	Contact technical@harwin.com	No - immediate
M80C107145C	Contact technical@harwin.com	No - immediate
M80C107146C	Contact technical@harwin.com	No - immediate
M80C107147C	Contact technical@harwin.com	No - immediate
M80C107148C	Contact technical@harwin.com	No - immediate
M80C107149C	Contact technical@harwin.com	No - immediate
M80C107150C	Contact technical@harwin.com	No - immediate
M80C107151C	Contact technical@harwin.com	No - immediate
M80C107152C	Contact technical@harwin.com	No - immediate
M80C107153C	Contact technical@harwin.com	No - immediate
M80C107333C	Contact technical@harwin.com	No - immediate
M80C107356C	Contact technical@harwin.com	No - immediate
M80C107393CTL	Contact technical@harwin.com	No - immediate
M80C107442C	Contact technical@harwin.com	No - immediate
M80C107452C	Contact technical@harwin.com	No - immediate
M80C107453C	Contact technical@harwin.com	No - immediate
M80C107460C	Contact technical@harwin.com	No - immediate
M80C107476C	Contact technical@harwin.com	No - immediate
M80C107590C	Contact technical@harwin.com	No - immediate
M80C107591C	Contact technical@harwin.com	No - immediate
M80C107592C	Contact technical@harwin.com	No - immediate
M80C107628C	Contact technical@harwin.com	No - immediate
M80C107633C	Contact technical@harwin.com	No - immediate
M80C107702C	Contact technical@harwin.com	No - immediate

Obsolete Product Notification from Harwin - Special

Part number being made obsolete	Drawing for obsolete product	Last Time Buy?
M80C107703C	Contact technical@harwin.com	No - immediate
M80C107809C	Contact technical@harwin.com	No - immediate
M80C107832C	Contact technical@harwin.com	No - immediate
M80C107833C	Contact technical@harwin.com	No - immediate
M80C107843C	Contact technical@harwin.com	No - immediate
M80C107921C	Contact technical@harwin.com	No - immediate
M80C107924C	Contact technical@harwin.com	No - immediate
M80C107926C	Contact technical@harwin.com	No - immediate
M80C107927C	Contact technical@harwin.com	No - immediate
M80C107992C	Contact technical@harwin.com	No - immediate
M80C108135C	Contact technical@harwin.com	No - immediate
M80C108186C	Contact technical@harwin.com	No - immediate
M80C108225C	Contact technical@harwin.com	No - immediate
M80C108342C	Contact technical@harwin.com	No - immediate
M80C108348C	Contact technical@harwin.com	No - immediate
M80C108353C	Contact technical@harwin.com	No - immediate
M80C108358C	Contact technical@harwin.com	No - immediate
M80C108422C	Contact technical@harwin.com	No - immediate
M80C108435C-PRE	Contact technical@harwin.com	No - immediate
M80C108436C-PRE	Contact technical@harwin.com	No - immediate
M80C108459C	Contact technical@harwin.com	No - immediate
M80C108460C	Contact technical@harwin.com	No - immediate
M80C108488C	Contact technical@harwin.com	No - immediate
M80C108536C	Contact technical@harwin.com	No - immediate
M80C108573C	Contact technical@harwin.com	No - immediate
M80C108574C	Contact technical@harwin.com	No - immediate
M80C108650C	Contact technical@harwin.com	No - immediate
M80C108725C	Contact technical@harwin.com	No - immediate
M80C108726C	Contact technical@harwin.com	No - immediate
M80C108735C	Contact technical@harwin.com	No - immediate
M80C108743C	Contact technical@harwin.com	No - immediate
M80C108745C	Contact technical@harwin.com	No - immediate
M80C150040C	Contact technical@harwin.com	No - immediate
M80C150098C	Contact technical@harwin.com	No - immediate
M80C150173C-12	Contact technical@harwin.com	No - immediate
M80F8681422	Contact technical@harwin.com	No - immediate
M80M8142022	Contact technical@harwin.com	No - immediate
M83C108627C	Contact technical@harwin.com	No - immediate
M83C108627CL	Contact technical@harwin.com	No - immediate
M83C108628C	Contact technical@harwin.com	No - immediate
M83C108631C	Contact technical@harwin.com	No - immediate
M83C108632C	Contact technical@harwin.com	No - immediate
M83C108632CL	Contact technical@harwin.com	No - immediate
M83C108636C	Contact technical@harwin.com	No - immediate
M83C108636CL	Contact technical@harwin.com	No - immediate