



Harwin plc
Fitzherbert Road
Farlington, Portsmouth
Hampshire PO6 1RT
United Kingdom

Reception: +44 (0)23 9231 4545
Sales Desk: +44 (0)23 9237 0451
Fax: +44 (0)23 9231 4590

Tuesday 12th April, 2016

Dear Customer,

Re: Obsolescence notification for Harwin product.

Please be advised that there are a number of individual items that are now obsolete. Some of these items have a Last Time Buy date of 12th July 2016:

- M80-4C100F1-40-306
- M80-4D1120500-02-306-01-327
- M80-4C10642FC-02-306-03-326
- M80-4D1120500-02-327-01-306

The rest of the items are obsolete with immediate effect:

- M402VF-3-032-06NR
- M402VM-3-030-06NR
- M402VM-3-038-04NR
- M402VF-3-034-07NR
- M402VM-3-032-04NR

Stocks may remain of a few items, please contact your normal Harwin Sales contact or distributor. Please see the attached spreadsheet for a complete list of affected items. Unfortunately, we are no longer able to support these products.

If you have any further questions regarding this letter, please do not hesitate to contact us.

Yours faithfully,

The Product Management Team
technical@harwin.com

If you have not been sent the accompanying spreadsheet, please request it from the contact that sent you this letter.

Obsolete Product Notification from Harwin

Part number being made obsolete	Drawing for obsolete product	Last Time Buy?	Alternative product	Drawing for alternative product
M402VF-3-032-06NR	M402VF.pdf	No - immediate	M402VF-3-032-05NR	M402VF.pdf
M402VF-3-034-07NR	M402VF.pdf	No - immediate	M402VF-3-032-05NR	M402VF.pdf
M402VM-3-030-06NR	M402VM.pdf	No - immediate	M402VM-3-080-04NR	M402VM.pdf
M402VM-3-032-04NR	M402VM.pdf	No - immediate	M402VM-3-080-04NR	M402VM.pdf
M402VM-3-038-04NR	M402VM.pdf	No - immediate	M402VM-3-080-04NR	M402VM.pdf
M80-4C100F1-40-306	M80-4C100F1-40-306_obsolete.pdf	12th July 2016	M80-4000000F1-04-306-00-000	M80-4000000F1-XX-XXX-00-000.pdf
M80-4C10642FC-02-306-03-326	M80-4C10642FC-02-306-03-326_obsolete.pdf	12th July 2016	Contact technical@harwin.com	
M80-4D1120500-02-306-01-327	M80-4D1120500-02-306-01-327_obsolete.pdf	12th July 2016	Contact technical@harwin.com	
M80-4D1120500-02-327-01-306	M80-4D1120500-02-327-01-306_obsolete.pdf	12th July 2016	Contact technical@harwin.com	