



Harwin plc
Fitzherbert Road
Farlington, Portsmouth
Hampshire PO6 1RT
United Kingdom

Reception: +44 (0)23 9231 4545
Sales Desk: +44 (0)23 9237 0451
Fax: +44 (0)23 9231 4590

Wednesday 7th December, 2016

Dear Customer,

Re: Obsolescence notification for Harwin product.

Please be advised that there are a number of items that are now obsolete. All items covered by this notification are obsolete with immediate effect. They include:

- 7-201/251 pins
- Various customer specials not ordered for some time
- M80-036 and M80-037 series

These items have not been ordered in some time and are not expected to cause anyone significant issues. Please see the attached spreadsheet for a complete list of affected items (**there are 2 pages to the spreadsheet**, Standard and Custom products). Unfortunately, we are no longer able to support these products.

If you have any further questions regarding this letter, please do not hesitate to contact us.

Yours faithfully,

The Product Change Team
technical@harwin.com

If you have not been sent the accompanying spreadsheet, please request it from the contact that sent you this letter.

Obsolete Product Notification from Harwin - Standard

Part number being made obsolete	Drawing for obsolete product	Last Time Buy?	Alternative product
7-201F3300	Contact technical@harwin.com	No - immediate	Contact technical@harwin.com
7-201F3900	Contact technical@harwin.com	No - immediate	Contact technical@harwin.com
7-201F5100	Contact technical@harwin.com	No - immediate	Contact technical@harwin.com
7-201F5500	Contact technical@harwin.com	No - immediate	Contact technical@harwin.com
7-201F7300	Contact technical@harwin.com	No - immediate	Contact technical@harwin.com
7-251F133000	Contact technical@harwin.com	No - immediate	Contact technical@harwin.com
7-251F142000	Contact technical@harwin.com	No - immediate	Contact technical@harwin.com
7-251F6600	Contact technical@harwin.com	No - immediate	Contact technical@harwin.com
7-251F9600	Contact technical@harwin.com	No - immediate	Contact technical@harwin.com
M80-0360498	Contact technical@harwin.com	No - immediate	Contact technical@harwin.com
M80-0360698	Contact technical@harwin.com	No - immediate	Contact technical@harwin.com
M80-0360898	Contact technical@harwin.com	No - immediate	Contact technical@harwin.com
M80-0361098	Contact technical@harwin.com	No - immediate	Contact technical@harwin.com
M80-0361298	Contact technical@harwin.com	No - immediate	Contact technical@harwin.com
M80-0361498	Contact technical@harwin.com	No - immediate	Contact technical@harwin.com
M80-0361698	Contact technical@harwin.com	No - immediate	Contact technical@harwin.com
M80-0361898	Contact technical@harwin.com	No - immediate	Contact technical@harwin.com
M80-0362098	Contact technical@harwin.com	No - immediate	Contact technical@harwin.com
M80-0362698	Contact technical@harwin.com	No - immediate	Contact technical@harwin.com
M80-0363498	Contact technical@harwin.com	No - immediate	Contact technical@harwin.com
M80-0370298	Contact technical@harwin.com	No - immediate	Contact technical@harwin.com
M80-0370398	Contact technical@harwin.com	No - immediate	Contact technical@harwin.com
M80-0370498	Contact technical@harwin.com	No - immediate	Contact technical@harwin.com
M80-0370598	Contact technical@harwin.com	No - immediate	Contact technical@harwin.com
M80-0370698	Contact technical@harwin.com	No - immediate	Contact technical@harwin.com
M80-0370798	Contact technical@harwin.com	No - immediate	Contact technical@harwin.com
M80-0371798	Contact technical@harwin.com	No - immediate	Contact technical@harwin.com

Obsolete Product Notification from Harwin - Special

Part number being made obsolete	Drawing for obsolete product	Last Time Buy?	Alternative product
006659E	Contact technical@harwin.com	No - immediate	Contact technical@harwin.com
6191-0007	Contact technical@harwin.com	No - immediate	Contact technical@harwin.com
D107488C	Contact technical@harwin.com	No - immediate	Contact technical@harwin.com
H106640C	Contact technical@harwin.com	No - immediate	Contact technical@harwin.com
H108946C	Contact technical@harwin.com	No - immediate	Contact technical@harwin.com
H108947C	Contact technical@harwin.com	No - immediate	Contact technical@harwin.com
H3102-05	Contact technical@harwin.com	No - immediate	Contact technical@harwin.com
H3147-05	Contact technical@harwin.com	No - immediate	Contact technical@harwin.com
H3147-06S	Contact technical@harwin.com	No - immediate	Contact technical@harwin.com
R106614C	Contact technical@harwin.com	No - immediate	Contact technical@harwin.com
R106743C	Contact technical@harwin.com	No - immediate	Contact technical@harwin.com
R106809C	Contact technical@harwin.com	No - immediate	Contact technical@harwin.com
R106826C	Contact technical@harwin.com	No - immediate	Contact technical@harwin.com
R106837C	Contact technical@harwin.com	No - immediate	Contact technical@harwin.com
R106876C	Contact technical@harwin.com	No - immediate	Contact technical@harwin.com
R107120C	Contact technical@harwin.com	No - immediate	Contact technical@harwin.com
R108604C	Contact technical@harwin.com	No - immediate	Contact technical@harwin.com