



Harwin plc
Fitzherbert Road
Farlington, Portsmouth
Hampshire PO6 1RT
United Kingdom

Reception: +44 (0)23 9231 4545
Sales Desk: +44 (0)23 9237 0451
Fax: +44 (0)23 9231 4590

Monday 4th December, 2017

Dear Customer,

Re: Obsolescence notification for Harwin product.

Please be advised that there are a number of items that are now obsolete. A few items covered by this notification are obsolete **with immediate effect**. They include:

- M60C109207C, M60C109208C, M80C109200C
- P20-0245R, P20-0545R

The remainder of the items have a **Last Time Buy date of Friday, 2nd March 2018** – these include:

- H3482, H3484, H3486 series
- All K36xx and K37xx items
- Spacer series R40-400, R40-661, R4751-R4757, R60-300, R6161-R6169, R6302-R6307, R6650-R6657, R6691-R6697, R8280
- A list of customer special products

Please see the following spreadsheet for a detailed list of affected items:

https://cdn.harwin.com/pdfs/Obsolescence_notification_spreadsheet_Products_December_2017.xlsx

Unfortunately, we are no longer able to support these products.

If you have any further questions regarding this letter, please do not hesitate to contact us.

Yours faithfully,

The Product Change Team
technical@harwin.com

Obsolete Product Notification from Harwin

Part number being made obsolete	Drawing for obsolete product	Last Time Buy?	Alternative product	Drawing for alternative product
3414-0442	Contact technical@harwin.com	02-Mar-18	M20-7890442	M20-789.pdf
3414-0642	Contact technical@harwin.com	02-Mar-18	M20-7890642	M20-789.pdf
D01C108002C	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
D108814C	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
D73064-42	D73064_obsolete.pdf	02-Mar-18	D2864-42	D2XXX.pdf
E5366-000011	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
H103022C	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
H105692C	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
H106071C	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
H106785C	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
H107310C	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
H107671C	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
H108252C	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
H108615C	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
H108674C	Contact technical@harwin.com	02-Mar-18	H2101A01	H2101A01.pdf
H108691C	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
H108706C	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
H108767C	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
H108788C	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
H108793C	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
H108794C-124-01	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
H108794C-160-01	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
H108803C	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
H108822C	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
H108839C	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
H108844C	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
H108852C	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
H108948C	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
H3153B01	Contact technical@harwin.com	02-Mar-18	H3153-01	H3153.pdf
H3161B01	Contact technical@harwin.com	02-Mar-18	H3161-01	H3161.pdf
H3482-01	H3482_obsolete.pdf	02-Mar-18	H3191-01	H3191.pdf
H3482-01R	H3482R_obsolete.pdf	02-Mar-18	H3191-01	H3191.pdf
H3482-42	H3482_obsolete.pdf	02-Mar-18	H3191-01	H3191.pdf
H3482-42R	H3482R_obsolete.pdf	02-Mar-18	H3191-01	H3191.pdf
H3482-46	H3482_obsolete.pdf	02-Mar-18	H3191-01	H3191.pdf
H3484-42	H3484_obsolete.pdf	02-Mar-18	H3185-01	H3185.pdf
H3484-42R	H3484R_obsolete.pdf	02-Mar-18	H3185-01	H3185.pdf
H3486-42	H3486_obsolete.pdf	02-Mar-18	H3492-01	H3492.pdf
H3486-42R	H3486R_obsolete.pdf	02-Mar-18	H3492-01	H3492.pdf
K3600-91	K3600_obsolete.pdf	02-Mar-18	Contact technical@harwin.com	
K3601-91	K3601_obsolete.pdf	02-Mar-18	Contact technical@harwin.com	
K3602-46	K3602_obsolete.pdf	02-Mar-18	Contact technical@harwin.com	
K3603-46	K3603_obsolete.pdf	02-Mar-18	Contact technical@harwin.com	
K3604-46	K3604_obsolete.pdf	02-Mar-18	Contact technical@harwin.com	
K3605-00	K3605_obsolete.pdf	02-Mar-18	Contact technical@harwin.com	
K3700-91	K3700_obsolete.pdf	02-Mar-18	Contact technical@harwin.com	
K3701-91	K3701_obsolete.pdf	02-Mar-18	Contact technical@harwin.com	
M106148C-SC	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M108169C	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M108525C	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M108528C	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M109083C	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M109084C	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M109196C	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M20-000101V1046	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M20-025025V1245	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M20-030350E1646	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M20-058030H0645	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M20-060045J0645	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M20-060070E0246	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M20-065030W0546	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M20-067030W1745	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M20-070070V0245	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M20-070270F0645	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	

Obsolete Product Notification from Harwin

Part number being made obsolete	Drawing for obsolete product	Last Time Buy?	Alternative product	Drawing for alternative product
M20-085030V2045	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M20-085120F2545	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M20-095030W1045	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M20-105032J0845	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M20-110030W1346	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M20-110035V1046	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M20-130030V0245	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M20-130060W0846	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M20-135030W0645	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M20-139030V0446	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M20-140090F0445	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M20-150020V0845	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M20-181060V2046	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M20-215030W1046	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M20C107496C	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M20C108817C	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M20C108835CR	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M20C108836C	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M20C109029C	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M22-025028J0246	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M22-030040E0405	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M22-030150F0846	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M22-030254F0946	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M22-039035J0405	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M22-039095F0746	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M22-040040J0546	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M22-045000S1105R	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M22-055030W0505	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M22-055100F1605	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M22-060240F1106	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M22-062000S1005	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M22-065030V0505	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M22-070025V1005	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M22-075030W0205	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M22-075030W0405	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M22-082031J3245	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M22-085035J0405	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M22-100085W0205	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M22-119030H0446	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M22-129035J0505	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M22C106844C	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M22C106845C	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M22C108983CR	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M22C109003CR	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M22C109221C	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M22C150226C	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M22F3011200	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M22F3020400	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M50-015070W0445	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M50-030050T5045	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M50-030057F0345	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M50-038030J0545	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M50-038030J3045	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M50-041039T2245	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M50-041103T1045	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M50-041103T2545	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M50-050070W0845	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M50-147116W0645	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M50C107411C	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M50C107783C	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M50C108140C	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M50C108507C-05	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M50C108507C-06	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M50C108507C-25	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	

Obsolete Product Notification from Harwin

Part number being made obsolete	Drawing for obsolete product	Last Time Buy?	Alternative product	Drawing for alternative product
M50C108507CR-05	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M50C108507CR-06	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M50C108507CR-25	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M50C108514C-05-135	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M50C108514C-06-170	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M50C108514C-25-080-A	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M50C108514C-25-085	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M50C108984CR-08	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M50C108984CR-10	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M50C108984CR-20	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M50C150239C	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M52-031030V1545	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M52-040023V1545	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M52-078000P0445	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M52-078050V1545	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M52-078050W0245	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
M60C109207C	Contact technical@harwin.com	No - immediate	Contact technical@harwin.com	
M60C109208C	Contact technical@harwin.com	No - immediate	Contact technical@harwin.com	
M80C109200C	Contact technical@harwin.com	No - immediate	Contact technical@harwin.com	
M80C150099C	Contact technical@harwin.com	02-Mar-18	M80-7912042	M80-791.pdf
M80C150101C	Contact technical@harwin.com	02-Mar-18	M80-7911242	M80-791.pdf
MM800571HW-20	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
MM800571HW-40	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
MM800656HW-20	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
MM800656HW-40	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
P109028C	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
P20-0245R	P20-0245R_obsolete.pdf	No - immediate	P20-0345R	P20-0345R.pdf
P20-0545R	P20-0545R_obsolete.pdf	No - immediate	P20-0445R	P20-0445R.pdf
PH2R15-105GB3.9/2.8/1.5-U	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
PH2R15-109GB3.9/2.8/1.5-U	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
PH2S15-103GB3.9/2.8-U	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
R104516C	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
R104873C	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
R104874C	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
R104875C	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
R105989C	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
R106111C	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
R106711C	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
R106742C	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
R106777C	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
R106808C	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
R106843C	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
R106920C	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
R106934C	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
R1087-03	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
R1087-03-SC	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
R30B3000502	Contact technical@harwin.com	02-Mar-18	R30-3000502	R30-300.pdf
R30B3001002	Contact technical@harwin.com	02-Mar-18	R30-3001002	R30-300.pdf
R30B3002502	Contact technical@harwin.com	02-Mar-18	R30-3002502	R30-300.pdf
R30B4000502	Contact technical@harwin.com	02-Mar-18	R30-4000502	R30-400.pdf
R30B4001002	Contact technical@harwin.com	02-Mar-18	R30-4001002	R30-400.pdf
R30B4001402	Contact technical@harwin.com	02-Mar-18	R30-4001402	R30-400.pdf
R30B4002002	Contact technical@harwin.com	02-Mar-18	R30-4002002	R30-400.pdf
R30BV3001502	Contact technical@harwin.com	02-Mar-18	R30-3001502	R30-300.pdf
R30BV3002002	Contact technical@harwin.com	02-Mar-18	R30-3002002	R30-300.pdf
R40-4000502	R40-400_obsolete.pdf	02-Mar-18	R30-4000502	R30-400.pdf
R40-4000602	R40-400_obsolete.pdf	02-Mar-18	R30-4000602	R30-400.pdf
R40-4000802	R40-400_obsolete.pdf	02-Mar-18	R30-4000802	R30-400.pdf
R40-4001002	R40-400_obsolete.pdf	02-Mar-18	R30-4001002	R30-400.pdf
R40-4001202	R40-400_obsolete.pdf	02-Mar-18	R30-4001202	R30-400.pdf
R40-4001402	R40-400_obsolete.pdf	02-Mar-18	R30-4001402	R30-400.pdf
R40-4001602	R40-400_obsolete.pdf	02-Mar-18	R30-4001602	R30-400.pdf
R40-4001802	R40-400_obsolete.pdf	02-Mar-18	R30-4001802	R30-400.pdf
R40-4002002	R40-400_obsolete.pdf	02-Mar-18	R30-4002002	R30-400.pdf

Obsolete Product Notification from Harwin

Part number being made obsolete	Drawing for obsolete product	Last Time Buy?	Alternative product	Drawing for alternative product
R40-4002502	R40-400_obsolete.pdf	02-Mar-18	R30-4002502	R30-400.pdf
R40-6610300	R40-661_obsolete.pdf	02-Mar-18	R40-6710394	R40-671.pdf
R40-6610400	R40-661_obsolete.pdf	02-Mar-18	R40-6710394	R40-671.pdf
R40-6610500	R40-661_obsolete.pdf	02-Mar-18	R40-6710594	R40-671.pdf
R40-6610600	R40-661_obsolete.pdf	02-Mar-18	R40-6710694	R40-671.pdf
R40-6610700	R40-661_obsolete.pdf	02-Mar-18	R40-6710694	R40-671.pdf
R40-6610800	R40-661_obsolete.pdf	02-Mar-18	R40-6710894	R40-671.pdf
R40-6610900	R40-661_obsolete.pdf	02-Mar-18	R40-6710894	R40-671.pdf
R40-6611000	R40-661_obsolete.pdf	02-Mar-18	R40-6711094	R40-671.pdf
R40-6611100	R40-661_obsolete.pdf	02-Mar-18	R40-6711194	R40-671.pdf
R40-6611200	R40-661_obsolete.pdf	02-Mar-18	R40-6711294	R40-671.pdf
R40-6611300	R40-661_obsolete.pdf	02-Mar-18	R40-6711294	R40-671.pdf
R40-6611400	R40-661_obsolete.pdf	02-Mar-18	R40-6711294	R40-671.pdf
R40-6611500	R40-661_obsolete.pdf	02-Mar-18	R40-6711594	R40-671.pdf
R40-6611600	R40-661_obsolete.pdf	02-Mar-18	R40-6711594	R40-671.pdf
R40-6611800	R40-661_obsolete.pdf	02-Mar-18	R40-6711894	R40-671.pdf
R40-6612000	R40-661_obsolete.pdf	02-Mar-18	R40-6711894	R40-671.pdf
R40-6612500	R40-661_obsolete.pdf	02-Mar-18	R40-6711894	R40-671.pdf
R40-6613000	R40-661_obsolete.pdf	02-Mar-18	R40-6711894	R40-671.pdf
R4751-02	R4751-R4757_obsolete.pdf	02-Mar-18	R30-1000602	R30-100.pdf
R4752-02	R4751-R4757_obsolete.pdf	02-Mar-18	R30-1000902	R30-100.pdf
R4753-02	R4751-R4757_obsolete.pdf	02-Mar-18	R30-1001202	R30-100.pdf
R4754-02	R4751-R4757_obsolete.pdf	02-Mar-18	R30-1001602	R30-100.pdf
R4755-02	R4751-R4757_obsolete.pdf	02-Mar-18	R30-1001802	R30-100.pdf
R4756-02	R4751-R4757_obsolete.pdf	02-Mar-18	R30-1002202	R30-100.pdf
R4757-02	R4751-R4757_obsolete.pdf	02-Mar-18	R30-1002502	R30-100.pdf
R60-3001002	R60-300_obsolete.pdf	02-Mar-18	R50-3001002	R50-300.pdf
R60-3001102	R60-300_obsolete.pdf	02-Mar-18	R50-3001102	R50-300.pdf
R60-3001202	R60-300_obsolete.pdf	02-Mar-18	R50-3001202	R50-300.pdf
R60-3001302	R60-300_obsolete.pdf	02-Mar-18	R50-3001302	R50-300.pdf
R60-3001402	R60-300_obsolete.pdf	02-Mar-18	R50-3001402	R50-300.pdf
R60-3001502	R60-300_obsolete.pdf	02-Mar-18	R50-3001502	R50-300.pdf
R60-3001602	R60-300_obsolete.pdf	02-Mar-18	R50-3001602	R50-300.pdf
R60-3001802	R60-300_obsolete.pdf	02-Mar-18	R50-3001802	R50-300.pdf
R60-3002002	R60-300_obsolete.pdf	02-Mar-18	R50-3002002	R50-300.pdf
R60-3002502	R60-300_obsolete.pdf	02-Mar-18	R50-3002502	R50-300.pdf
R60-3003002	R60-300_obsolete.pdf	02-Mar-18	R50-3003002	R50-300.pdf
R60-3003502	R60-300_obsolete.pdf	02-Mar-18	R50-3003502	R50-300.pdf
R60-3004002	R60-300_obsolete.pdf	02-Mar-18	R50-3004002	R50-300.pdf
R60-3005002	R60-300_obsolete.pdf	02-Mar-18	R50-3004002	R50-300.pdf
R6161-02	R6161-R6169_obsolete.pdf	02-Mar-18	R30-6010402	R30-601.pdf
R6162-02	R6161-R6169_obsolete.pdf	02-Mar-18	R30-6010602	R30-601.pdf
R6163-02	R6161-R6169_obsolete.pdf	02-Mar-18	R30-6010802	R30-601.pdf
R6164-02	R6161-R6169_obsolete.pdf	02-Mar-18	R30-6011002	R30-601.pdf
R6165-02	R6161-R6169_obsolete.pdf	02-Mar-18	R30-6011202	R30-601.pdf
R6166-02	R6161-R6169_obsolete.pdf	02-Mar-18	R30-6011402	R30-601.pdf
R6167-02	R6161-R6169_obsolete.pdf	02-Mar-18	R30-6011602	R30-601.pdf
R6168-02	R6161-R6169_obsolete.pdf	02-Mar-18	R30-6011802	R30-601.pdf
R6169-02	R6161-R6169_obsolete.pdf	02-Mar-18	R30-6012002	R30-601.pdf
R6302-02	R630X.pdf	02-Mar-18	R30-5000602	R30-500.pdf
R6303-02	R630X.pdf	02-Mar-18	R30-5000802	R30-500.pdf
R6304-02	R630X.pdf	02-Mar-18	R30-5001002	R30-500.pdf
R6305-02	R630X.pdf	02-Mar-18	R30-5001202	R30-500.pdf
R6306-02	R630X.pdf	02-Mar-18	R30-5001402	R30-500.pdf
R6307-02	R630X.pdf	02-Mar-18	R30-5001602	R30-500.pdf
R6650-02	R6650-R6657_obsolete.pdf	02-Mar-18	R30-5000402	R30-500.pdf
R6651-02	R6650-R6657_obsolete.pdf	02-Mar-18	R30-5000602	R30-500.pdf
R6652-02	R6650-R6657_obsolete.pdf	02-Mar-18	R30-5000902	R30-500.pdf
R6653-02	R6650-R6657_obsolete.pdf	02-Mar-18	R30-5001202	R30-500.pdf
R6654-02	R6650-R6657_obsolete.pdf	02-Mar-18	R30-5001602	R30-500.pdf
R6655-02	R6650-R6657_obsolete.pdf	02-Mar-18	R30-5001802	R30-500.pdf
R6656-02	R6650-R6657_obsolete.pdf	02-Mar-18	R30-5002002	R30-500.pdf
R6657-02	R6650-R6657_obsolete.pdf	02-Mar-18	R30-5002502	R30-500.pdf
R6691-02	R6690-R6697_obsolete.pdf	02-Mar-18	R30-1000402	R30-100.pdf

Obsolete Product Notification from Harwin

Part number being made obsolete	Drawing for obsolete product	Last Time Buy?	Alternative product	Drawing for alternative product
R6692-02	R6690-R6697_obsolete.pdf	02-Mar-18	R30-1000602	R30-100.pdf
R6693-02	R6690-R6697_obsolete.pdf	02-Mar-18	R30-1000902	R30-100.pdf
R6694-02	R6690-R6697_obsolete.pdf	02-Mar-18	R30-1001202	R30-100.pdf
R6695-02	R6690-R6697_obsolete.pdf	02-Mar-18	R30-1001602	R30-100.pdf
R6696-02	R6690-R6697_obsolete.pdf	02-Mar-18	R30-1001802	R30-100.pdf
R6697-02	R6690-R6697_obsolete.pdf	02-Mar-18	R30-1002202	R30-100.pdf
R8280-02	R8280-R8284_obsolete.pdf	02-Mar-18	R30-1002502	R30-100.pdf
S108761C	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
S108782CR	Contact technical@harwin.com	02-Mar-18	S1731-46R	S1731R.pdf
S108802CR	Contact technical@harwin.com	02-Mar-18	S1621-46R	S1621R.pdf
S109080C	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
S109080CR	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
S109114CR	Contact technical@harwin.com	02-Mar-18	S1721-46R	S1721-XXR.pdf
S109138CR	Contact technical@harwin.com	02-Mar-18	S7121-42R	S7121R.pdf
S109194CR	Contact technical@harwin.com	02-Mar-18	S8101-46R	S8101R.pdf
S109195CR	Contact technical@harwin.com	02-Mar-18	S8111-46R	S8111R.pdf
S150231C	Contact technical@harwin.com	02-Mar-18	S8101-46R	S8101R.pdf
S150236CR	Contact technical@harwin.com	02-Mar-18	S1621-46R	S1621R.pdf
TD2195	Contact technical@harwin.com	02-Mar-18	Z80-280	Z80-280.pdf
TD2294	Contact technical@harwin.com	02-Mar-18	Z80-280	Z80-280.pdf
TD2295	Contact technical@harwin.com	02-Mar-18	Z80-280	Z80-280.pdf
W2224-09	Contact technical@harwin.com	02-Mar-18	Contact technical@harwin.com	
W2330B00	Contact technical@harwin.com	02-Mar-18	W2330-00	W2330.pdf
W2331B00	Contact technical@harwin.com	02-Mar-18	W2331-00	W2331.pdf
W2632-00	W2632_obsolete.pdf	02-Mar-18	W2332-00	W2332.pdf
Z80-280A	Contact technical@harwin.com	02-Mar-18	Z80-280	Z80-280.pdf