



Harwin plc
Fitzherbert Road
Farlington, Portsmouth
Hampshire PO6 1RT
United Kingdom

Reception: +44 (0)23 9231 4545
Sales Desk: +44 (0)23 9237 0451

Wednesday 23rd May, 2018

Dear Customer,

Re: Obsolescence notification for Harwin product.

Please be advised that the following ranges are now obsolete with immediate effect:

- H9033-01, H9036-01, H9037-01, H9042-01 + associated tooling
- R40-301 series
- R4421-02 to R4429-02
- R4451-02 to R4457-02
- R4480-02 to R4487-02
- Various customer special products

Please see the following spreadsheet for a detailed list of affected items:

https://cdn.harwin.com/pdfs/Obsolescence_spreadsheet_23-05-2018_various_products.xlsx

Unfortunately, we are no longer able to support these product lines. Alternative items are available in some cases; please see the attached spreadsheet for the alternative part numbers.

If you have any further questions regarding this letter, please do not hesitate to contact us.

Yours faithfully,

The Product Change Team
technical@harwin.com

Obsolete Product Notification from Harwin

Part number being made obsolete	Drawing for obsolete product	Last Time buy date	Alternative product	Drawing for alternative product
3432-3042	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
APM331290051341	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
D01C150188C	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
D3088B98	Contact technical@harwin.com	Immediate	D3088-98	D3088.pdf
D3088B99	Contact technical@harwin.com	Immediate	D3088-99	D3088.pdf
D3089B98	Contact technical@harwin.com	Immediate	D3089-98	D3089.pdf
D3089B99	Contact technical@harwin.com	Immediate	D3089-99	D3089.pdf
H101750C	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
H105589C	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
H109149C	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
H109174C-05	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
H3161-T6	Contact technical@harwin.com	Immediate	H3161-46	H3161.pdf
H9033-01	H9033_obsolete.pdf	Immediate	H9020-01	H9020-H9021.pdf
Z9033-00	Z9033_obsolete.pdf	Immediate	Contact technical@harwin.com	
H9036-01	H9036_obsolete.pdf	Immediate	H2055-01	H2055.pdf
Z9036-00	Z9036_obsolete.pdf	Immediate	Contact technical@harwin.com	
H9037-01	H9037_obsolete.pdf	Immediate	H2055-01	H2055.pdf
Z9037-00	Z9037_obsolete.pdf	Immediate	Contact technical@harwin.com	
H9042-01	H9042_obsolete.pdf	Immediate	H2039-01	H2039.pdf
Z9042-00	Z9042_obsolete.pdf	Immediate	Contact technical@harwin.com	
M106739C	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M108394C	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M20-030051E0245	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M20-032022V0546	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M20-032022V0646	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M20-057159F2545	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M20-078000S0646	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M20-085100F1046	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M20-110200F0545	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M20-140030V0546	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M20-140030V1546	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M20C108229C	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M20C109153CR	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M22-035050W0505	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M22-035080F1005	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M30C108546C-20-145	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M40C109088C-01	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M40C109088C-02	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M50-030040W0545	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M50-045065F1545	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M50-045105F2045	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M50-060000S1045	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M50-080023W0545	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M50-080023W0845	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M52-025000P0545R	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M52-078023W4045	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M80C107762C	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M80C107803C	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M80C107804C	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M80C107917C	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M80C108450C	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M80C108451C	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M80C108849C	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
M80C109072C	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
R30C108160C	Contact technical@harwin.com	Immediate	Contact technical@harwin.com	
R40-3010802	R40-301_obsolete.pdf	Immediate	R40-3000802	R40-300.pdf
R40-3011002	R40-301_obsolete.pdf	Immediate	R40-3001002	R40-300.pdf
R40-3011502	R40-301_obsolete.pdf	Immediate	R40-3001502	R40-300.pdf

Obsolete Product Notification from Harwin

Part number being made obsolete	Drawing for obsolete product	Last Time buy date	Alternative product	Drawing for alternative product
R40-3012002	R40-301_obsolete.pdf	Immediate	R40-3002002	R40-300.pdf
R40-3012502	R40-301_obsolete.pdf	Immediate	R40-3002502	R40-300.pdf
R40-3013002	R40-301_obsolete.pdf	Immediate	R40-3003002	R40-300.pdf
R4421-02	R4421-R4429_obsolete.pdf	Immediate	R40-1000502	R40-100.pdf
R4422-02	R4421-R4429_obsolete.pdf	Immediate	R40-1000602	R40-100.pdf
R4423-02	R4421-R4429_obsolete.pdf	Immediate	R40-1000802	R40-100.pdf
R4424-02	R4421-R4429_obsolete.pdf	Immediate	R40-1001002	R40-100.pdf
R4425-02	R4421-R4429_obsolete.pdf	Immediate	R40-1001202	R40-100.pdf
R4426-02	R4421-R4429_obsolete.pdf	Immediate	R40-1001402	R40-100.pdf
R4427-02	R4421-R4429_obsolete.pdf	Immediate	R40-1001602	R40-100.pdf
R4428-02	R4421-R4429_obsolete.pdf	Immediate	R40-1001802	R40-100.pdf
R4429-02	R4421-R4429_obsolete.pdf	Immediate	R40-1002002	R40-100.pdf
R4451-02	R4451-R4457_obsolete.pdf	Immediate	R40-1000602	R40-100.pdf
R4452-02	R4451-R4457_obsolete.pdf	Immediate	R40-1000902	R40-100.pdf
R4453-02	R4451-R4457_obsolete.pdf	Immediate	R40-1001202	R40-100.pdf
R4454-02	R4451-R4457_obsolete.pdf	Immediate	R40-1001502	R40-100.pdf
R4455-02	R4451-R4457_obsolete.pdf	Immediate	R40-1001802	R40-100.pdf
R4456-02	R4451-R4457_obsolete.pdf	Immediate	R40-1002002	R40-100.pdf
R4457-02	R4451-R4457_obsolete.pdf	Immediate	R40-1002502	R40-100.pdf
R4480-02	R4480-R4487_obsolete.pdf	Immediate	R40-6000302	R40-600.pdf
R4481-02	R4480-R4487_obsolete.pdf	Immediate	R40-6000602	R40-600.pdf
R4482-02	R4480-R4487_obsolete.pdf	Immediate	R40-6000902	R40-600.pdf
R4483-02	R4480-R4487_obsolete.pdf	Immediate	R40-6001202	R40-600.pdf
R4484-02	R4480-R4487_obsolete.pdf	Immediate	R40-6001602	R40-600.pdf
R4485-02	R4480-R4487_obsolete.pdf	Immediate	R40-6001802	R40-600.pdf
R4486-02	R4480-R4487_obsolete.pdf	Immediate	R40-6002002	R40-600.pdf
R4487-02	R4480-R4487_obsolete.pdf	Immediate	R40-6002502	R40-600.pdf