



Harwin plc  
Fitzherbert Road  
Farlington, Portsmouth  
Hampshire PO6 1RT  
United Kingdom

Reception: +44 (0)23 9231 4545  
Sales Desk: +44 (0)23 9237 0451

Tuesday 21<sup>st</sup> April, 2020

Dear Customer,

**Re: Obsolescence notification for Harwin product.**

The following items are now obsolete **with a Last-Time Buy date of 21<sup>st</sup> August 2020**. Pin counts of **17 and 22 ONLY** are obsolete from the following ranges (**NOT the complete range**):

- M80-782
- M80-792
- M80-842
- M80-843
- M80-852
- M80-882

Please see the following spreadsheet for a detailed list of affected items:

[https://cdn.harwin.com/pdfs/Obsolescence\\_notification\\_spreadsheet\\_21-Apr-2020.xlsx](https://cdn.harwin.com/pdfs/Obsolescence_notification_spreadsheet_21-Apr-2020.xlsx)

Unfortunately, after these dates and upon exhaustion of stock, we are no longer able to support these product lines. Alternative items may be available in some cases; please see the spreadsheet for the alternative part numbers where applicable. The website will be updated as soon as possible.

If you have any further questions regarding this letter, please do not hesitate to contact us.

Yours faithfully,

The Product Change Team

[technical@harwin.com](mailto:technical@harwin.com)

## Obsolete Product Notification from Harwin

Part number being made obsolete	Drawing for obsolete product	Last Time buy date	Alternative product	Drawing for alternative product
M80-7821722	<a href="#">M80-782.pdf</a>	21st August 2020	M80-8771722	<a href="#">M80-877.pdf</a>
M80-7821742	<a href="#">M80-782.pdf</a>	21st August 2020	M80-8771722	<a href="#">M80-877.pdf</a>
M80-7821745	<a href="#">M80-782.pdf</a>	21st August 2020	M80-8771705	<a href="#">M80-877.pdf</a>
M80-7822222	<a href="#">M80-782.pdf</a>	21st August 2020	M80-8772222	<a href="#">M80-877.pdf</a>
M80-7822242	<a href="#">M80-782.pdf</a>	21st August 2020	M80-8772222	<a href="#">M80-877.pdf</a>
M80-7822245	<a href="#">M80-782.pdf</a>	21st August 2020	M80-8772205	<a href="#">M80-877.pdf</a>
M80-7921722	<a href="#">M80-792.pdf</a>	21st August 2020	M80-8761722	<a href="#">M80-876.pdf</a>
M80-7921742	<a href="#">M80-792.pdf</a>	21st August 2020	M80-8761722	<a href="#">M80-876.pdf</a>
M80-7921745	<a href="#">M80-792.pdf</a>	21st August 2020	M80-8761705	<a href="#">M80-876.pdf</a>
M80-7922222	<a href="#">M80-792.pdf</a>	21st August 2020	M80-8762222	<a href="#">M80-876.pdf</a>
M80-7922242	<a href="#">M80-792.pdf</a>	21st August 2020	M80-8762222	<a href="#">M80-876.pdf</a>
M80-7922245	<a href="#">M80-792.pdf</a>	21st August 2020	M80-8762205	<a href="#">M80-876.pdf</a>
M80-8421722	<a href="#">M80-842.pdf</a>	21st August 2020	M80-8761722	<a href="#">M80-876.pdf</a>
M80-8421742	<a href="#">M80-842.pdf</a>	21st August 2020	M80-8761722	<a href="#">M80-876.pdf</a>
M80-8421745	<a href="#">M80-842.pdf</a>	21st August 2020	M80-8761705	<a href="#">M80-876.pdf</a>
M80-8422222	<a href="#">M80-842.pdf</a>	21st August 2020	M80-8762222	<a href="#">M80-876.pdf</a>
M80-8422242	<a href="#">M80-842.pdf</a>	21st August 2020	M80-8762222	<a href="#">M80-876.pdf</a>
M80-8422245	<a href="#">M80-842.pdf</a>	21st August 2020	M80-8762205	<a href="#">M80-876.pdf</a>
M80-8431722	<a href="#">M80-843.pdf</a>	21st August 2020	M80-8781722	<a href="#">M80-878.pdf</a>
M80-8431742	<a href="#">M80-843.pdf</a>	21st August 2020	M80-8781722	<a href="#">M80-878.pdf</a>
M80-8431745	<a href="#">M80-843.pdf</a>	21st August 2020	M80-8781705	<a href="#">M80-878.pdf</a>
M80-8432222	<a href="#">M80-843.pdf</a>	21st August 2020	M80-8782222	<a href="#">M80-878.pdf</a>
M80-8432242	<a href="#">M80-843.pdf</a>	21st August 2020	M80-8782222	<a href="#">M80-878.pdf</a>
M80-8432245	<a href="#">M80-843.pdf</a>	21st August 2020	M80-8782205	<a href="#">M80-878.pdf</a>
M80-8521722	<a href="#">M80-852.pdf</a>	21st August 2020	M80-8791722	<a href="#">M80-879.pdf</a>
M80-8521742	<a href="#">M80-852.pdf</a>	21st August 2020	M80-8791722	<a href="#">M80-879.pdf</a>
M80-8521745	<a href="#">M80-852.pdf</a>	21st August 2020	M80-8791705	<a href="#">M80-879.pdf</a>
M80-8522222	<a href="#">M80-852.pdf</a>	21st August 2020	M80-8792222	<a href="#">M80-879.pdf</a>
M80-8522242	<a href="#">M80-852.pdf</a>	21st August 2020	M80-8792222	<a href="#">M80-879.pdf</a>
M80-8522245	<a href="#">M80-852.pdf</a>	21st August 2020	M80-8792205	<a href="#">M80-879.pdf</a>
M80-8821722	<a href="#">M80-882.pdf</a>	21st August 2020	M80-8771722	<a href="#">M80-877.pdf</a>
M80-8821742	<a href="#">M80-882.pdf</a>	21st August 2020	M80-8771722	<a href="#">M80-877.pdf</a>
M80-8821745	<a href="#">M80-882.pdf</a>	21st August 2020	M80-8771705	<a href="#">M80-877.pdf</a>
M80-8822222	<a href="#">M80-882.pdf</a>	21st August 2020	M80-8772222	<a href="#">M80-877.pdf</a>
M80-8822242	<a href="#">M80-882.pdf</a>	21st August 2020	M80-8772222	<a href="#">M80-877.pdf</a>
M80-8822245	<a href="#">M80-882.pdf</a>	21st August 2020	M80-8772205	<a href="#">M80-877.pdf</a>