



Harwin plc
Fitzherbert Road
Farlington, Portsmouth
Hampshire PO6 1RT
United Kingdom

Reception: +44 (0)23 9231 4545
Sales Desk: +44 (0)23 9237 0451

Wednesday 22nd December, 2021

Dear Customer,

Re: Obsolescence notification for Harwin product.

Please be advised that the following part numbers are now obsolete with immediate effect.

- M40-301xx46
- M40-401xx46
- **NOTE: M40-301xx46R and M40-401xx46R are not affected, and are still available**

Please see the following spreadsheet for a detailed list of affected items:

https://cdn.harwin.com/pdfs/Obsolescence_notification_spreadsheet_2021-12-22.xlsx

Unfortunately, we are no longer able to support this packing variation on these product ranges. Alternative items are available; please see the attached list for the alternative part numbers.

If you have any further questions regarding this letter, please do not hesitate to contact us.

Yours faithfully,

The Product Change Team

technical@harwin.com

Obsolete Product Notification from Harwin

Part number being made obsolete	Drawing for obsolete product	Last Time buy date	Alternative product	Drawing for alternative product
M40-3010246	M40-301_obsolete.pdf	Immediate	M40-3010246R	M40-301R.pdf
M40-3010346	M40-301_obsolete.pdf	Immediate	M40-3010346R	M40-301R.pdf
M40-3010446	M40-301_obsolete.pdf	Immediate	M40-3010446R	M40-301R.pdf
M40-3010546	M40-301_obsolete.pdf	Immediate	M40-3010546R	M40-301R.pdf
M40-3010646	M40-301_obsolete.pdf	Immediate	M40-3010646R	M40-301R.pdf
M40-3010746	M40-301_obsolete.pdf	Immediate	M40-3010746R	M40-301R.pdf
M40-3010846	M40-301_obsolete.pdf	Immediate	M40-3010846R	M40-301R.pdf
M40-3010946	M40-301_obsolete.pdf	Immediate	M40-3010946R	M40-301R.pdf
M40-3011046	M40-301_obsolete.pdf	Immediate	M40-3011046R	M40-301R.pdf
M40-3011146	M40-301_obsolete.pdf	Immediate	M40-3011146R	M40-301R.pdf
M40-3011246	M40-301_obsolete.pdf	Immediate	M40-3011246R	M40-301R.pdf
M40-3011346	M40-301_obsolete.pdf	Immediate	M40-3011346R	M40-301R.pdf
M40-3011446	M40-301_obsolete.pdf	Immediate	M40-3011446R	M40-301R.pdf
M40-3011546	M40-301_obsolete.pdf	Immediate	M40-3011546R	M40-301R.pdf
M40-3011646	M40-301_obsolete.pdf	Immediate	M40-3011646R	M40-301R.pdf
M40-3011746	M40-301_obsolete.pdf	Immediate	M40-3011746R	M40-301R.pdf
M40-3011846	M40-301_obsolete.pdf	Immediate	M40-3011846R	M40-301R.pdf
M40-3011946	M40-301_obsolete.pdf	Immediate	M40-3011946R	M40-301R.pdf
M40-3012046	M40-301_obsolete.pdf	Immediate	M40-3012046R	M40-301R.pdf
M40-4010246	M40-401_obsolete.pdf	Immediate	M40-4010246R	M40-401R.pdf
M40-4010346	M40-401_obsolete.pdf	Immediate	M40-4010346R	M40-401R.pdf
M40-4010446	M40-401_obsolete.pdf	Immediate	M40-4010446R	M40-401R.pdf
M40-4010546	M40-401_obsolete.pdf	Immediate	M40-4010546R	M40-401R.pdf
M40-4010646	M40-401_obsolete.pdf	Immediate	M40-4010646R	M40-401R.pdf
M40-4010746	M40-401_obsolete.pdf	Immediate	M40-4010746R	M40-401R.pdf
M40-4010846	M40-401_obsolete.pdf	Immediate	M40-4010846R	M40-401R.pdf
M40-4010946	M40-401_obsolete.pdf	Immediate	M40-4010946R	M40-401R.pdf
M40-4011046	M40-401_obsolete.pdf	Immediate	M40-4011046R	M40-401R.pdf
M40-4011146	M40-401_obsolete.pdf	Immediate	M40-4011146R	M40-401R.pdf
M40-4011246	M40-401_obsolete.pdf	Immediate	M40-4011246R	M40-401R.pdf
M40-4011346	M40-401_obsolete.pdf	Immediate	M40-4011346R	M40-401R.pdf
M40-4011446	M40-401_obsolete.pdf	Immediate	M40-4011446R	M40-401R.pdf
M40-4011546	M40-401_obsolete.pdf	Immediate	M40-4011546R	M40-401R.pdf
M40-4011646	M40-401_obsolete.pdf	Immediate	M40-4011646R	M40-401R.pdf
M40-4011746	M40-401_obsolete.pdf	Immediate	M40-4011746R	M40-401R.pdf
M40-4011846	M40-401_obsolete.pdf	Immediate	M40-4011846R	M40-401R.pdf
M40-4011946	M40-401_obsolete.pdf	Immediate	M40-4011946R	M40-401R.pdf
M40-4012046	M40-401_obsolete.pdf	Immediate	M40-4012046R	M40-401R.pdf