



Monday 19 June, 2023

Dear Customer,

**Re: Obsolescence notification for Harwin product.**

Please be advised that the following products are now obsolete with immediate effect:

- M22-6023042
- M22-6033042
- M83-LML3M1N19-0101-333
- M83-LML3M5N13-0302-313
- M83-LML3M5N25-0101-333
- M83-LML3MSN40-0008-333
- M83-LML3MQNXX-0000-000 range
- H108949C
- H109051C
- H109053C
- R6308-02

Please see the following spreadsheet for a detailed list of affected items:

[https://cdn.harwin.com/pdfs/Obsolescence\\_notification\\_spreadsheet\\_2023-06-19.xlsx](https://cdn.harwin.com/pdfs/Obsolescence_notification_spreadsheet_2023-06-19.xlsx)

Unfortunately, we are no longer able to support these product lines. Alternative item suggestions are available for some of these items; please see the attached spreadsheet for the applicable part numbers.

If you have any further questions regarding this letter, please do not hesitate to contact us.

Yours faithfully,

The Product Change Team  
[technical@harwin.com](mailto:technical@harwin.com)