



23 October 2023

Dear Customer,

Re: Obsolescence notification for Harwin product.

Please be advised that the following RS-specific products are now obsolete with immediate effect:

- R181xB91
- R632xB02
- R633xB02

Unfortunately, we are no longer able to support these product lines under these part numbers. However, all products have an identical standard product available - please consult the spreadsheet for the standard product.

Please see the following spreadsheet for the list of affected items and the standard alternatives: https://cdn.harwin.com/pdfs/Obsolescence_notification_2023-10-23_2_Harwin_spreadsheet.xlsx

If you have any further questions regarding this letter, please do not hesitate to contact us.

Yours faithfully,

The Product Change Team
technical@harwin.com

Obsolete Product Notification from Harwin

Part number being made obsolete	Drawing for obsolete product	Last Time buy date	Alternative: Standard product	Drawing for alternative product
R1811B91	R1811B91-R1817B91_obsolete.pdf	Immediate	R30-9400800	R30-940.pdf
R1812B91	R1811B91-R1817B91_obsolete.pdf	Immediate	R30-9401000	R30-940.pdf
R1814B91	R1811B91-R1817B91_obsolete.pdf	Immediate	R30-9401400	R30-940.pdf
R1815B91	R1811B91-R1817B91_obsolete.pdf	Immediate	R30-9401600	R30-940.pdf
R1817B91	R1811B91-R1817B91_obsolete.pdf	Immediate	R30-9402000	R30-940.pdf
R6322B02	R6322B02-R6392B02_obsolete.pdf	Already unavailable	R30-5000602	R30-500.pdf
R6323B02	R6322B02-R6392B02_obsolete.pdf	Already unavailable	R30-5000802	R30-500.pdf
R6324B02	R6322B02-R6392B02_obsolete.pdf	Already unavailable	R30-5001002	R30-500.pdf
R6327B02	R6322B02-R6392B02_obsolete.pdf	Already unavailable	R30-5001602	R30-500.pdf
R6329B02	R6322B02-R6392B02_obsolete.pdf	Already unavailable	R30-5002002	R30-500.pdf
R6334B02	R6332B02-R6338B02_obsolete.pdf	Already unavailable	R30-1011202	R30-101.pdf
R6338B02	R6332B02-R6338B02_obsolete.pdf	Already unavailable	R30-1012002	R30-101.pdf